ZIERKE SOIL TESTING

Charlie Berquist 23881 St Croix Trl N Scandia, MN 55073

10/7/2022

Dear Charlie Berguist,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your septic system is <u>compliant</u>. A certification of compliance is in effect for three years from the date it is issued. To be clear, this should not be construed as a guarantee of future system function – there are too many factors that influence the lifespan of a septic system for an inspector to predict or even guess how long a septic system will last. A copy of this report will be filed with your local unit of government for their records.

Sincerely,

Benjamin Zierke

MPCA Lic 119, Cert 9594

Benjamin Zieske

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346

EMAIL benzierke@gmail.com



Compliance inspection report form

520 Lafayette Road North St. Paul, MN 55155-4194

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking number:						
Parcel ID# or Sec/Twp/Range: 0603219130004	Reason for Inspection Sale						
Local regulatory authority info: Washington County							
Property address: 23881 St Croix Trl N Scandia, MN 55073							
Owner/representative: Charlie Berquist	Owner's phone: 612-719-3620						
Brief system description: 1500/1000 gallon septic tanks, 1000 gallon lift tank, drop box rock trench drainfield							
System status							
System status on date (mm/dd/yyyy):10/7/2022							
□ Compliant – Certificate of compliance*	☐ Noncompliant – Notice of noncompliance						
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.						
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public health and safety (ITPHS) must be						
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.						
Reason(s) for noncompliance (check all applicab	ole)						
☐ Impact on public health (Compliance component #1)	– Imminent threat to public health and safety						
☐ Tank integrity (Compliance component #2) – Failing	to protect groundwater						
☐ Other Compliance Conditions (Compliance components)							
Other Compliance Conditions (Compliance compone	,						
-	2500 (Compliance component #3) – Failing to protect groundwater						
Soil separation (Compliance component #5) – Failing							
	npliance component #4) – Noncompliant - local ordinance applies						
Comments or recommendations							
System functioning normally during site visit 10/3/2022.							
Certification							
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,						
	and correct, to the best of my knowledge, and that this information can be						
Business name: Zierke Soil Testing	Certification number: 9594						
Inspector signature: Benjamin Zierke	License number: 119						
(This document has been electronically sign	ned) Phone: 651-249-1346						
Necessary or locally required supporting do							
	equired forms						
☐ Other information (list): Previous inspection boring							

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the	☐ Yes* ⊠ No	Other:
ground surface		⊠ Not applicable
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No	
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No	
Any "yes" answer above indicates imminent threat to public health ar		
Describe verification methods and	results:	
None of the above observed during s	site visit 10/3/2022.	
ank integrity Compliance	component #2	of E
nk integrity – Compliance	component #2	
Compliance criteria:	component #2	Attached supporting documentation:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	· 	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	· 	Attached supporting documentation:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	_ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: Smilies
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	_ Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	_ Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 10/3/2022 □ Existing tank integrity assessment (Attach) Date of maintenance
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	Yes* No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 10/3/2022 □ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 10/3/2022 □ Existing tank integrity assessment (Attach) Date of maintenance
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	Yes* ⊠ No Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 10/3/2022 □ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies Minn. R. 7082.0700 subp. 4 B (1)) □ Tank is Noncompliant (pumping not necessary – explain by
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	Yes* No Yes* No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: Smilies License number of maintenance business: 2428 Date of maintenance: 10/3/2022 □ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment complies Minn. R. 7082.0700 subp. 4 B (1))

Property Address: 23881 St Croix Trl N Scandia, MN 55073	
Business Name: Zierke Soil Testing	Date: 10/7/2022
3. Other compliance conditions – Compliance component #	3 of 5
3a. Maintenance hole covers appear to be structurally unsound (damaged, crack	
☐ Yes* ☐ No ☐ Unknown	
3b. Other issues (electrical hazards, etc.) to immediately and adversely impact pub	ic health or safety? ☐ Yes* ☒ No ☐ Unknown
*Yes to 3a or 3b - System is an imminent threat to public health and sat	•
3c. System is non-protective of ground water for other conditions as determined	
3d. System not abandoned in accordance with Minn. R. 7080.2500?	yes* ⊠ No
*Yes to 3c or 3d - System is failing to protect groundwater	
Describe verification methods and results:	
Attached supporting documentation: Not applicable	
4. Operating permit and nitragen PMP* Compliance com	nonent #4 of E. Martine Politic
4. Operating permit and nitrogen BMP* – Compliance com	porient #4 013 🗵 Not applicable
Is the system operated under an Operating Permit?	☐ Yes ☐ No If "yes", A below is required
Is the system required to employ a Nitrogen BMP specified in the system design?	☐ Yes ☐ No If "yes", B below is required
BMP = Best Management Practice(s) specified in the system design	
If the answer to both questions is "no", this section does not need to	be completed.
Compliance criteria:	
a. Have the operating permit requirements been met?	No
b. Is the required nitrogen BMP in place and properly functioning? $\ \ \ \ \ \ \ \ \ \ \ \ \ $	No
Any "no" answer indicates noncompliance.	
Describe verification methods and results:	
Attached supporting documentation: Operating permit (Attach)	

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

ısiness Name: Zierke Soil Testing		Date: 1	10/7/2022		
Soil separation – Compliance co	omponent #5 o	f 5			
Date of installation 9/11/1997 (mm/dd/yyyy)	Unknown				
Shoreland/Wellhead protection/Food beverage lodging?	⊠ Yes □ No	Yes ☐ No Attached supporting documentation: ☐ Soil observation logs completed for t			
Compliance criteria (select one):		☐ Two previous verifications of required	vertical separation		
5a. For systems built prior to April 1, 1996, an not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	d Yes No*	☐ Not applicable (No soil treatment area)			
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.					
5b. Non-performance systems built	⊠ Yes □ No*	Indicate depths or elevations			
April 1, 1996, or later or for non- performance systems located in Shoreland		A. Bottom of distribution media	98.2'		
or Wellhead Protection Areas or serving a		B. Periodically saturated soil/bedrock	94.0'		
food, beverage, or lodging establishment: Drainfield has a three-foot vertical		C. System separation	4.2'		
separation distance from periodically		D. Required compliance separation*	3.0'		
saturated soil or bedrock.*		*May be reduced up to 15 percent if allo Ordinance.	owed by Local		
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required \$2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day) Drainfield meets the designed vertical					
separation distance from periodically saturated soil or bedrock.					


failing to protect groundwater.

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

800-657-3864

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021



Logs of Soil Borings

Location of Project: 23881 St Croix Trl N Scandia, MN 55073

Borings Made by Ben Zierke Date: 10/3/2022

Hand bucket auger used for borings; USDA - SCS Soil Classification used.

Depth, in Inches	Boring Number 1	Depth, in Inches	Boring Number 2
0-19"	10YR 3/2 loamy sand 5% rock	0	
19-38"	10YR 4/4 medium sand 5% rock		
38-42"	10YR 3/2 sandy loam		
42-68"	10YR 4/3 fine sand <5% rock		
68-72"	10YR 6/4 fine sand <5% rock		
End of boring at Standing water tab Present at Standing water not p Mottled Soil: Observed at Mottled soil not pres Comments:	feet of depth Hours after boring feet of depth feet of depth	End of boring at Standing water tal Present at Standing water not Mottled Soil: Observed at Mottled soil not pre Comments:	feet of depth Hours after boring present in hole feet of depth
Depth, in Inches	Boring Number 3	Depth, in Inches	Boring Number 4
0		0	
End of boring at	feet	End of boring at	feet

Log Of Soil Borings

Locat	tion of Project:	23881 St. Croix Trail	N, Scandia, MN 55073 Date: 6/4/10				
Borings Made By: Inspect Minnesota					6/4/10		
Auger Used: Hand/Bucket			Class	Classification System: USDA			
Boring Number: 1		Boring Number:		ring Number:	2		
Surface Same ground surface at inspection		surface at inspection	Surface Same ground surface at		ound surface at		
Elevation of	at south en	d of last drainfield	Elevation of inspection at north end of las				
Boring		trench	Boring				
Depth In Inches	Soils E	ncountered	Depth In Inches	Soils Encountered			
0-16	Loamy Sand	& Sandy Loam Fill	0-33	ΙO	am. Sandy Loai	m. & Loamy Sand Fill	
	OYR 2/2 Loamy S	Sand (Original Topsoil) 3 Loamy Sand	33-72 72-76				
		ım Sand And Trace Gravel			•	Mottles/Redox	
74" De	Depth To End Of Boring Or Mottled Soils			Depth To End Of Boring Or Mottled So			
		g Relative To System					
-35" Depth To Bottom Of System		-35" Depth To Bottom Of System					
≥39" Of Separation		≥37"		Separation	- /		
_	LOCE			_	1065	76"	
	nd Of Boring At:	74"	NA - 2 1 1		d Of Boring At:	76"	
Mottled Soil Present At: None		Mottled Soil Present At: 72"					
Standing Water Present At: None		Standing	wa	ter Present At:	None		

Bottom	Of	Distribution	Medium	Δ+·	35	Inches
DULLUIII	Οı	DISTIDUTION	Mediuiii	AL.	55	THUCHES