Midwest Sewer Services

P.O. Box 10853 White Bear Lake, MN 55110		Brian Humpal	
651-492-7550/Brian@Midwestsoiltesting.com		MPCA Licensed Advanced Inspector	
SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT			
Date: December 12, 2022	Time: 1:30 PM	Owner: Brett & Alison Ellingson	
Inspection Address: 11885 Dellwood Rd, Grant, MN 55082			

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks, a pre-cast lift tank, and a seepage bed. Pinky's Sewer Service pumped the septic tank on December 12, 2022.

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



520 Lafayette Road North St. Paul, MN 55155-4194

Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking number:	
Parcel ID# or Sec/Twp/Range:	Reason for Inspection	Property Transfer
Local regulatory authority info: Washington County		
Property address: 11885 Dellwood Rd, Grant, MN 55082		
Owner/representative: Brett & Alison Ellingson		Owner's phone: 651-214-3582
Brief system description: Two pre-cast septic tanks, a pre-cast lift ta	ank, and a seepage bed.	

System status

System status on date (mm/dd/yyyy): 12/12/2022

Compliant – Certificate of compliance*

(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)

*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.

□ Noncompliant – Notice of noncompliance

Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.

An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.

Reason(s) for noncompliance (check all applicable)

Impact on public health (Compliance component #1) – Imminent threat to public health and safety

Tank integrity (Compliance component #2) - Failing to protect groundwater

Other Compliance Conditions (Compliance component #3) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance component #3) - Failing to protect groundwater

System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) – Failing to protect groundwater

Soil separation (Compliance component #5) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance component #4) – Noncompliant - local ordinance applies

Comments or recommendations

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

By typing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form.

Business name: Midwest Sewer Services

Humpal After the

Certification number: 5342/9852

Inspector signature:

document has bee	n electronically signed)
------------------	--------------------------

License number: L2896

Phone: 651-492-7550

Necessary or locally required supporting documentation (must be attached)

Soil observation logs System/As-Built Locally required forms Tank Integrity Assessment Operating Permit Other information (list): Report Summary, Property Information, Disclaimer

Property Address:	11885 Dellwood Rd	, Grant, MN 55082

Business Name: Midwest Sewer Services

Date: 12/12/2022

1. Impact on public health – Compliance component #1 of 5

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	🗌 Yes* 🛛 No	☐ Other: ☐ Not applicable
System discharges sewage to drain tile or surface waters.	🗌 Yes* 🛛 No	_
System causes sewage backup into dwelling or establishment.	🗌 Yes* 🛛 No	
Any "yes" answer above indicates imminent threat to public health an		_
Describe verification methods and	results:	

None of the above found.

2. Tank integrity – Compliance component #2 of 5

Compliance criteria:		Attached supporting documentation	:
System consists of a seepage pit,	🗌 Yes* 🛛 No	Empty tank(s) viewed by inspector	
cesspool, drywell, leaching pit, or other pit?		Name of maintenance business:	Pinky's Sewer Service
Sewage tank(s) leak below their	🗌 Yes* 🛛 No	⊠ No License number of maintenance business:	
designed operating depth?		Date of maintenance:	12/12/2022
		Existing tank integrity assessment (Atta	ch)
If yes, which sewage tank(s) leaks:		Date of maintenance (mm/dd/yyyy): (must be withi	n three years)
Any "yes" answer above indicates the system is failing to protect groundwater.		(See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))	ment complies with
		Tank is Noncompliant (pumping not necessary – explain below)	
		☐ Other:	
Describe verification methods and	l results:		

4 of 9

Property Address:	11885 Dellwood Rd, Grant, MN 55082
Business Name:	Midwest Sewer Services

Date: 12/12/2022

3. Other compliance conditions - Compliance component #3 of 5

3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or uns	secured?	
🗋 Yes* 🖾 No 📋 Unknown		
3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safe	ety? 🗌 Yes* 🛛 No 🗌 Unknown	
*Yes to 3a or 3b - System is an imminent threat to public health and safety.		
3c. System is non-protective of ground water for other conditions as determined by inspector?	🗌 Yes* 🖾 No	
3d. System not abandoned in accordance with Minn. R. 7080.2500?	🗌 Yes* 🖾 No	
*Yes to 3c or 3d - System is failing to protect groundwater.		
Describe verification methods and results:		
Attached supporting documentation: 🛛 Not applicable		
Operating permit and nitrogen BMP* – Compliance component #4	of 5 🖂 Not applicable	

4. Operating permit and nitrogen BMP* – Compliance component #4 of 5 🖂 Not applicable

Is the system operated under an Operating Permit?		es 🗌 N	If "yes", A below is required
Is the system required to employ a Nitrogen BMP specified in the system	em design? 🔲 າ	es 🗌 N	If "yes", B below is required
BMP = Best Management Practice(s) specified in the system de	sign		
If the answer to both questions is "no", this section does not need to be completed.			
Compliance criteria:			
a. Have the operating permit requirements been met?	🗌 Yes 🗌 No		
b. Is the required nitrogen BMP in place and properly functioning?	🗌 Yes 🗌 No		
Any "no" answer indicates noncompliance.			

Describe verification methods and results:

Attached supporting documentation:
Operating permit (Attach)

Property Address:	11885 Dellwood Rd, Grant, MN 55082

Business Name: Midwest Sewer Services

5. Soil separation – Compliance component #5 of 5

Date of installation 2016 (mm/dd/yyyy)	Unknown		
 Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one): 5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, 	☐ Yes ⊠ No	Attached supporting documentation:	l vertical separation a)
beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.			
 5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* 	⊠ Yes □ No*	Indicate depths or elevationsA. Bottom of distribution mediaB. Periodically saturated soil/bedrockC. System separationD. Required compliance separation*	24" See Attached Boring Log(s)
 5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day) Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock. 	☐ Yes ☐ No*	*May be reduced up to 15 percent if allo Ordinance.	wed by Local

*Any "no" answer above indicates the system is failing to protect groundwater.

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.


Date: 12/12/2022

<u>Midwest Sewage Testing</u> Subsurface Sewage Treatment System Owner/Property Information

Date of Inspection: December 12, 2022 Time: 1:30 PM Property Address: 11885 Dellwood Rd, Grant, MN Zip: 55082 Property Owner: Brett & Alison Ellingson Phone: 651-214-3582 Tank(s) Tank(s)Material Soil Treatment System Other Acrobic Plastic Gravelless trench Hendiding Other system Other: Block Mound Other system Other system Other: Block Mound Other system Other system Year house built: 2016 Yeas septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? Are any buildings on this property such as garages or out-buildings? Is the well a deep well? Y Have our experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of swage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? Are there any additional systems on this property serving other buildings? Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots,	This information will be used for the purpose of conducting an MPCA Compliance Inspection.				
Property Address: 11885 Dellwood Rd, Grant, MN Zip: 55082 Property Owner: Brett & Alison Ellingson Phone: 651-214-3582 Tank(s) Tank(s)Material Soil Treatment System Other Areobic Plastic Gravelless trench Experimental system Block Metal Chamber trench Cesspool system Other: Block Mound Other system Other: Block Mound Other system Other: Concrete Scepage bed Other system Other: Block Mound Other system Performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 2016 Year septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system?					
Property Owner: Brett & Alison Ellingson Phone: 651-214-3582 Tank(s) Tank(s)(Material Soil Treatment System Other Aerobic Plastic Gravelless trench Alternative system Holding Concrete Seepage bed Other system Other: Block Mound Other system Other: Block Mound Other system Other concerted Seepage bed Other system Seepage bed Wen observed Other concerted Seepage bed Other system Wear house built: 2016 Year septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of septic system on lot? Northeast Side Location of settic system on lot? Northeast Side Is the well a deep well? Y Have you ever experinenced any problems with the system such as: tree roots					
Property Owner: Brett & Alison Ellingson Phone: 651-214-3582 Tank(s) Tank(s)(Material Soil Treatment System Other Aerobic Plastic Gravelless trench Alternative system Holding Concrete Seepage bed Other system Other: Block Mound Other system Other: Block Mound Other system Other concerted Seepage bed Other system Seepage bed Wen observed Other concerted Seepage bed Other system Wear house built: 2016 Year septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of septic system on lot? Northeast Side Location of settic system on lot? Northeast Side Is the well a deep well? Y Have you ever experinenced any problems with the system such as: tree roots	Property Address: 11885 Dellwood Rd, Grant, MN	Zip: 55082			
Septic 2 Fiberglass Gock trench Chamber trench Experimental system Acrobic Plastic Gravelless trench Experimental system Acrobic Other Chamber trench Cesspool system Block Mound Other system Other: Block Mound Other: Block Mound Are the tank maintenance covers accessible? Yes No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system. Year house built: 2016 Year septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Mare all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West		· · · · · · · · · · · · · · · · · · ·			
the ground surface to facilitate access and proper maintenance of the system. Year house built: 2016 Year septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is your property located in a shoreland management area? N	Septic 2 Fiberglass Rock trench Aerobic Plastic Gravelless trench XLift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Alternative system Experimental system Cesspool system Other system mo, proper maintenance must be			
Year house built: 2016 Year septic installed: 2016 Tank size (gals.): 1-1500, 1-1000 How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is your property located in a shoreland management area? N					
How long has seller owned the property? Number of residents in home? Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is your property located in a shoreland management area? N					
Number of bedrooms? 5 Are all floors drained by gravity? Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is system?					
Garbage disposal? Whirlpool bath? More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is system?					
More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain: When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is system?					
Does this property have any footing drain tiles connected to the septic system? Are any buildings on this property such as garages or out-buildings connected to this system? Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain: When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is system?					
Are there any additional systems on this property serving other buildings? Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain: When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is system?					
Location of septic system on lot? Northeast Side Location of water well on lot? West Side Is the well a deep well? Y Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain: When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is your property located in a shoreland management area? N	Are any buildings on this property such as garages or out-buildings connected to this system?				
Location of water well on lot? West SideIs the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain:When was the system last pumped? 12/12/2022Name of pumper: Pinky's Sewer ServiceHow often pumped in previous years?Is system on a monitoring plan?Have you received notices from any government agency concerning this system?Is system?	Are there any additional systems on this property serving other buildings?				
Location of water well on lot? West SideIs the well a deep well? YHave you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain:When was the system last pumped? 12/12/2022Name of pumper: Pinky's Sewer ServiceHow often pumped in previous years?Is system on a monitoring plan?Have you received notices from any government agency concerning this system?Is system?	Location of septic system on lot? Northeast Side				
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain: When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service How often pumped in previous years? Is system on a monitoring plan? Have you received notices from any government agency concerning this system? Is system?	Location of water well on lot? West Side Is the	e well a deep well? Y			
How often pumped in previous years?Is system on a monitoring plan?Have you received notices from any government agency concerning this system?Is your property located in a shoreland management area? N	surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made				
How often pumped in previous years?Is system on a monitoring plan?Have you received notices from any government agency concerning this system?Is your property located in a shoreland management area? N	When was the system last pumped? 12/12/2022 Name of pumper: Pinky's Sewer Service				
Have you received notices from any government agency concerning this system? Is your property located in a shoreland management area? N					
Do you have any additional information that should be given to the new owner?					
	Do you have any additional information that should be given to the new owner?				

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant:



Client/ Add	ress: 11005 thy	96		Legal De	cription/GPS	1		Date:	6/9/1	4
	Material(s): Till	Outwash) la	acustrine A	luvium L	oess Organic I	Vlatter Be	drock		
	Position: Summit	Shoulder	Ba	ack/Side Slope) Foot Slo	pe Toe Slope	Slo	pe Shape:	Con	~
Vegetation:			Sc	oll Survey Map	Unit(s):	mtore - 49	۶۰ Slo	pe (%): 5	-6	
Weather co	nditions/Time of Day:	clear	- 0	bservation #/L	ocation/Meth	od:	Ele	vation:		
Depth (in)	Texture	12:00	Rock	Matrix	Mottle Color(s)	Redox Kind(s)	Saturated Soil Indicator(s) (see back)	Structure Shape	Structure Grade	Consistenc
)-10	Loan		Frag %	10 4/3	colon(s)	Concentrations Depletions Gleyed	(are back)	Granular Platy Prismatic Single Grain Maanive	Moderate Strong Loose	Loose Riable Firm Extremely Fire Rigid
10-2-6	Loung Sal			7.5/4		Concentrations Depletions Gleyed		Grenolar Platy Biogle Single Grain Massive	Moderate Strong Loose	Firm Extremely Firm Rigid
2-7-36	Low		35	7:5 /4		Concentrations Depletions Gleyed		Granular Platy Historic Frismatike Single Grain Massive	Weak Moderate Strong Loose	Firm Extremely Firm Rigid
36-60	Sandy lon		w	754/4		Concentrations Depletions Gleyed		Granular Platy Blocky Prismatic Single Grain Masshre	Weak Coderate Strong Loose	Firm Extremely Firm Rigid
						Concentrations Depletions Gleyed		Granular Platy Blocky Prismatic Single Grain Massive	Weak Moderate Strong Loose	Loose Friable Firm Extremely Firr Rigid
						Concentrations Depletions Gleved		Granular Platy Blocky Prismatic Single Grain Massive	Weak Moderate Strong Loose	Loose Friable Firm Extremely Firm Rigid
omments:	Bosing with	Pm	76	odien -	conte	- f Aren		1		
ertified Statemer	nt: I hereby certify that I have e with all applicable ordinance	completed th es. rules and l	aws.	(Designar)		(Signatur	Gun	1	170 -2 (License #)	(Date)

	INNESOT	<u></u>		Observatio		Project ID:				
c	lient/ Address:				Legal Description/ GPS:					
Soil parent	material(s): (0	heck all	that apply) 🛛 Out	vash 🗌 Lacustrine 🛛	🛛 Loess 🗔 Till	Aliuvium	Bedrock	Organic Matte	er	
Landscape	Position: (chec	k one)	🗌 Summit 🗔 Shoul	der 🔄 Back/Side Slope	Foot Slope	Toe Slope	Slope shape			
Vegetation	n		Sc	il survey map units		Slope%		Elevation:	98.6	
Weather Co	onditions/Time	of Day:	1			L	Date		10.0	
Observatio	on #/Location:		BZ			Obse	ervation Type:			
Depth (in) Texture		Rock	Hatsiy Calanta)		Redox Kind(s)		human Strue		ctureI	
beptir (iii)	Frag. %		Matrix Color(s)	trix Color(s) Mottle Color(s)		Indicator(s)	Shape	Grade	Consistence	
09	Topson		104R3/3							
9-26	LOAMY SAND		7.54R4/4							
26-39	SILT LOAM		10yr4/3							
39-45	SANDI Loam		57124/3							
45-55	CLAY LOAM		7.5yr.\$4							
55-66 RED	SILT LOAM		2.SYR414	70NS 2.5	ule Dec	LETIDUS	Eve (17			
Comments							SHCALO		1	
hereby certi	fy that I have o	ompleted	this work in accord	ance with all applica	able ordinances, r	ules and laws.				
	(Designer)			(Signature)		-	(License #)		(Date)	

Cli	ent/ Address:	10000	DELLWOO	o Ro	Legal Desc	ription/ GPS:	24.030	.21.11.00	5
oil parent r	material(s): (C	heck all th	nat apply) 🔀 Outw	ash 🗌 Lacustrine 🗌		Alluvium	Bedročk	Organic Matter	r
andscape P	osition: (chec	k one) [Summit 🗌 Should	er 🔀 Back/Side Slope	Foot Slope	Toe Slope	Slope shape	CONV	EX
Vegetation	LAW	J	So	Slope%	3-4%	Elevation:	97.7		
Weather Cor	L	of Day:	CLOUDY	PM			Date	4-3	20-16
Observatio	n #/Location:	31	_			Obse	rvation Type:		
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	I- Shape	Grade Consistence	
0-8	TOPSOIL		104R4/3				Jindpo		
8-14	LOAM		(orp.4/4						
14-30	SANDY LOAM		syr44						
30-51	SILT LOAM		7.sy ⊾ 4/4						5
51-62	MED		5712413						
	OX @ 5		2.57R4/8						
Comments		semplotor	I this work in accor	dance with all applie	cable ordinances.	rules and laws			
	(Designer)			(Signature			1568 (License #)	-	4-20-16 (Date)

Cli	ent/ Address:				Legal Desc	Project ID: ription/ GPS:				
		heck all t	aat apoly) 🔲 Outv	vash 🗌 Lacustrine 🗌			Bedrock	Organic Matter		
	osition: (chec			ler 🗌 Back/Side Slope		Toe Slope	Slope shape	_		
		k one)					Stope snape		98.4	
Vegetation			So	il survey map units		Slope%		Elevation:	76.4	
	nditions/Time						Date			
Observation #/Location: 83							rvation Type:	Structur		
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Indicator(s)	Shape	Grade	Consistence		
0-11	Topson		10/12 3/3							
11-26	LOAMY		7.51R444							
2640	SANDY SI	LT	7.54R7/6							
40-57	LOAM		104R5/4							
57-66	MED		SIRSY							
CK	TO 66	11								
Comments	-									
		_								
Observation #/Location: B4						Obse	rvation Type:	StructureI		
Observatio	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Shape	Grade	Consistence	
Depth (in)	readers		10/23/3							
	TOPSOIL		1 MICAS							
Depth (in)	TYPEOUL		7.5/25/4							
Depth (in)			7.51254							
Depth (in)	TOPSOIL SILTI SAND SANDY LOAM									
Depth (in) O-11 11-41 41-55	TOPSOIL SILTY SAND SANDY		7.5/R5/4 10/R 4/3							

8 of 9

DISCLAIMER

Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.