## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a	- C-1		
This section must be completed in its entirety prior to performing maintenance activit	ies and remain o	alid maintenance	permit. This permit r	nust be completed
Data of William Of 2 D 321	ies and remain o	ii-site for the dura	ition of the maintenar	nce activity.
Date of Maintenance: $9-2D_{c}2^{2}$ Reason	for Maintenance:	houtine		
Property Address: 13160 Ozark 7r	N	Property Owner's	Name: Kevin	Stokes
Municipality: <u>Stillwater</u> ZIP: <u>5508</u>	Property Ide	entification Numbo	r.	
Maintenance Permit No. 08 1104 2003 1 N	Naintainer Name a	and License No. Pin	ky's Environmental Sev	wer Service/ L1673
/ Maintenance Performed	Tank Mea	Suramont (must b		
	Tank Measurement (must be completed if tanks NOT pumped)			
(-)	Liquid Level of Tank — in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: $\Box$ Maintenan	ce Hole Other			
2. Were all covers securely replaced? Yes	¬No	enter additionization c	.oue)	
<ol> <li>Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structure</li> </ol>	ic, notaing, pret	reatment or pump	tank below the opera	ating depth or
evidence of damaged, cracked, or structura	ily ulisound mair	tenance hole cove	ers?  Yes  No	
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?			Tes Ino	
Tank #1 /2 00 gal Tank #2	pal Pretreatment	tank	ol Duma Taul	3
5. Other information: List any troubleshooting, r	ninor renairs cor	dusted tenters	at Pump rank	gal
and the	illior repairs cor	iducted, tank safe	ty concerns, or other	concerns.
PIB Ching				
b. Location of septage disposal:	+ 1/4	7 1 000	/	
. Location of septage disposal:	ev men of	let St. Km	/	
Pinky's	Environmental Se	wer Service Inc.		

PO Box 354

Afton MN 55001