GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

01333330967 SSTS MAINTENANCE REPORT

Date of Maintenand	:e 4/9/23 A	leason for Maintenance		,	
Property Address:	7/7/ 1901	h 5T. N.	Property Owner's Name:	Greg Lyford	
Municipality: 607	35T Lake	State M Zip	Code 55025 GI	O Code/Property I.D.#:	
a seathirth are	lo te lè th e sy tem.			Gomile Regionary - sees	
Tank(s) Pumped		ET SEE SEE SEE SEE SEE SEE SEE SEE SEE S	Superator for the William	are in the second and the second seco	
Sludge and scum measured.		Liquid Level o	f Tarik in. Sluc	ige Level in. Scum Level i	
Do tanks need to be pumped?		1		-	
Yes No (If no provide measure		ements) Total (Sludge -	Scum) / Liquid	Level = %Sludge & Scum	
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) 2. If maintenance hole was used wors all sovers assuming to 15. The maintenance hole was used wors all sovers assuming to 15. The maintenance hole was used wors all sovers assuming to 15. The maintenance hole was used wors all sovers assuming to 15. The maintenance hole was used wors all sovers assuming to 15. The maintenance hole was used worse all sovers assuming to 15. The maintenance hole was used to 15. The m					
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain					
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
I, .					
(owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance. 4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
The second state of the second state of the second					
Tank#1 Yes No Verificatio Method Used: VIGUA					
Tank#2 Yes No Verificatio Method Used: // 1911 a					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank		Leaking In	Cover Damage	
the second second second	/Holding Tank#1	☐ Yes ☑ No	Yes No	☐ Yes ⊠No	
Septic/Holding Tank #2		☐ Yes ☐ No	Yes No	Yes No	
Pretrea	etment Tank	Yes No	Yes No	☐Yes ☐No	
Pump	[ank	☐ Yes ☑ No	☐ Yes ☒ No	☐ Yes ☑No	
6. How many gallons of septage were removed?					
Tank#1 1000 Tank#2 1000 Pretreatment Tank Pump Tank 300					
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
8. Certification: I hereby and mad	certify as a State of M e the observations, o	innesota certified SSTS N r directly supervised oth	laintainer that I personall ers in the performance of	y conducted the work	
Maintainer's Name: Olson's Sewer Service, Inc. Maintainer's Address: 17638 Lyons Street NE, Forest Lake, MN					
Maintainer's License #: 216 Maintainer's Phone #: 651-464-2082					
Maintainer's Signature Date: 6/19/23					