GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

		in i enance re	FORT	_
Property Address Co. 200	Reason for Maintenan		1	Steaker wo
Property Address: G A CO	,	N3822b	32347 0	Stalsu
Property Address: 90993	cisterta N	Property Owner's Nan	ne: Squah	Hab work
Municipality: 5 to // cucter		Zip Code	GEO Code/Property I.D. #:	Dobah
to a dividual to a other in		Marina de la como de l La como de la como dela como de la como de la como dela como de la como de l		
Tank(s) Pumped			E LA COLLA EIR DEN	
Sludge and scum measured.	Liquid Leve	loiTalk :		
Do tanks need to be pumped?	11	in. S	ludge Level in. Sci	ım Level in.
Yes No (If no provide meas	urements) Total (Sludg	e + Scum) / Lion		
1. Access used to remove septage:				dge & Scum
2. If maintenance hole was used, were all	COVERS SECURED TENTANT	ther (Go to #3 below)	* Tank must be puiss greater, than 2:	Imped if this value
Explanation:	training replaced	! LXYes [No please	explain	
3. If owner refuses to allow a Subsurface	Sewana Transmand Co			
3. If owner refuses to allow a Subsurface them complete and sign the following	statement;	stem (SSTS) to be pump	ed through the maintena	nce hole, have
1 , ·	(Assumants was a second	•		
hole. I understand that removal of solids	and liquide about a second	to allow the removal of :	solids and liquids through t	he maintean
hole. I understand that removal of solids 4. Is the tank designed as a leaky tank? exam	and indoins fullandly off	er access points is not cor	nsidered maintenance.	reminerance
- An -	Pres recpuye pit, cesspoo	l, drywell, leaching pit		
Tank#1 Yes No Verificatio Meti	hod Used:			
Tank#2 Tyes No Verificatio Meth	2			
5. Is there evidence of early lasting				
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank be	elow the operating done.	
Tank	in members able c	1		or evidence of
Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	Yes No	
	Yes No	Yes No	Yes No	- .
Pretreatment Tank 27	TYes No	☐Yes ☑No		•
Pump Tank	Yes Alo	Yes No	Yes No	
6. How many gallons of septage were remov	ed?	LI TES LAND	Yes Allo	
Tank#1	#3			
1000 1011112 1257	Pretreatment Tar	ik / see Pui	mp Tank	
7. Other information: List any troubleshootin	O. Minor rennire cond.	7000	950	
7. Other information: List any troubleshooting	2 (cpans congu	ctee, tank safety concer	ns, or other concerns.	
Certification: I hereby certify as a State of Mi and made the observations, or	nnesota certified SSTS M	aintainer that I personally	Conducted the west	
		rs in the performance of t	his job.	
Maintainer's Name: Olson's Sewer Service, Inc		Address: 17638 Lyons St		
		3 110 - 21	HEEL INC. POIDE I -L. III.	
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-2	082	THEET INE, POTEST Lake, MN	
Maintainer's License #: 216 Maintain Maintainer's Signature	er's Phone #: 651-464-2	082		
	er's Phone #: 651-464-2	082 Date: 9^/		