

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| Date of Maintenance: <u>11/</u>   | 15/2023 Reason for Main | tenance: Routine                    |                |
|-----------------------------------|-------------------------|-------------------------------------|----------------|
| Property Address: 2750 W          | oodlane Dr Woodbury, MN | Property Owner's Name:              | Dean Duffy     |
| Municipality:                     | ZIP: <u>55125</u> Pro   | operty Identification Number:       |                |
| Maintenance Permit No: Maintainer |                         | r Name and License No. Schlomka Ser | vice LLC/L2989 |

| Maintenance Performed   | Tank Measurement (must be completed if tanks NOT pumped)  |  |  |
|---|---|--|--|
| <ul> <li>Tank(s) Pumped</li> <li>Sludge and scum measured</li> <li>Do tanks need to be pumped?</li> <li>Yes No (if no provide measurements)     </li> </ul> | Liquid Level of Tank in       Sludge Level in Tank in         Sludge + Scum / Liquid Level X 100         = % Sludge & Scum Tanks must be pumped if 25% or greater |  |  |

**1. Access used to remove septage:** An Maintenance Hole Other (enter authorization code)

- 2. Were all covers securely replaced? Tes No N/A
- 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? <u>No couldn't confirm precast vis</u> No - couldn't confirm precast via camera

| Tank                   | Leaking Out     | Leaking In                   | Cover Damage |  |
|------------------------|-----------------|------------------------------|--------------|--|
| Septic/Holding Tank #1 | Some answers un | Ves No<br>known. Pumped thro | Yes No-      |  |
| Septic/Holding Tank #2 | - I Yes I No    | - Yes No                     | - Yes No-    |  |
| Pretreatment Tank      | □ Yes □No       | □ Yes □No                    | □ Yes □No    |  |
| Pump Tank              | 🗆 Yes 🗌 No      | □ Yes □No                    | □ Yes □No    |  |

4. How many gallons of septage were removed?

Tank #1<u>750</u> gal Tank #2<u>750</u> \_gal Pretreatment tank\_\_\_\_\_gal Pump Tank \_\_\_\_\_gal

5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.

Some answers unknown. Pumped through inspection pipe.

Location of septage disposal: Metro MCES WWTP

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.