

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Property Address: _	8791 Lamar Ave S, Hasting	gs, MN F	roperty Owner's Na	ame:	RicK Hagen	
Municipality:	ZIP:	033 Property Ide	ntification Number:			
Maintenance Permit	No:	Maintainer Name ar	d License No. Sch	llomka Service LLC	C/L2989	
Mainter	nance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
☑ Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured Do tanks need to be pumped?			Sludge Level in Tank in Scum Level in Tank in			
		[- 이번 1일 : 100 전 100 HE 100		evel X 100		
☐ Yes ☐ No (if no provide measurements) = % Studge & Sci	ım ıaı	nks must be pumped	1 IT 25% OF greater	
1. Access used to r	emove septage: Mainten	ance Hole 🛭 Other (e	enter authorization co	ode)		
	securely replaced? 🖯 Yes					
2. Were all covers	securely replaced: 🗀 Tes	LINO				
			eatment or numn	tank below the one	erating depth or	
	e of tank leakage from a se maged, cracked, or structu		eatment or pump tenance hole cove	tank below the opers? No-couldn't	erating depth or conf <u>irm precast via</u>	
			reatment or pump tenance hole cove Leaking In		erating depth or confirm precast via	
	e of tank leakage from a se maged, cracked, or structu	Leaking Out	Leaking In	camera	erating depth or conf <u>irm precast via</u>	
	e of tank leakage from a se maged, cracked, or structu Tank	Leaking Out Yes No Some answers un	Leaking In	Cover Damage Yes No ough inspection pipe.	erating depth or conf <u>irm precast via</u>	
	e of tank leakage from a se maged, cracked, or structu Tank Septic/Holding Tank #1	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Yes No ough inspection pipe.	erating depth or confirm precast via	
	e of tank leakage from a semaged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Ves No Nough inspection pipe.	erating depth or confirm precast via	
3. Is there evidence evidence of data	e of tank leakage from a semaged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No	Leaking In Yes No known. Pumped thro Yes No Yes No	Cover Damage Yes No No Yes No Yes No Yes No	erating depth or confirm precast via	
Is there evidence evidence of data 4. How many gallo	e of tank leakage from a semaged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ns of septage were remove	Leaking Out Yes No	Leaking In Yes No known. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No ough inspection pipe. Yes No Yes No Yes No		
4. How many gallo Tank #1	rank Septic/Holding Tank #2 Pretreatment Tank Pump Tank Pump Tank rs of septage were remove gal Tank #2	Leaking Out Yes No	Leaking In Yes No known. Pumped thro Yes No Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Pes No	gal	
4. How many gallo Tank #1 500 5. Other informati	e of tank leakage from a semaged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ns of septage were remove	Leaking Out Yes No Yes	Leaking In Yes No known. Pumped thro Yes No Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Pes No	gal	

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033

License# 2989 P: 651-459-3718