## 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730 GOVERNMENT CENTER

## SSTS MAINTENANCE REPORT X 5307h 34739

Date of Maintenance 4/8/2	il Person for the	"FINANCE	REPORT X 5307h 34	7-
Property Address: 12183	4	enance:		
Municipale	Janeto Ale 1	Property Owner's	Name: Adam Fak	
Tivido	State MW		1101.6%	
E Le Viel de Control (Vile v		3303	GEO Code/Property I.D. E.	
Tank(s) Pumped			lice cople enough on Fig.	*54
Do tanks need to be pumped?	Liquid L	read at the Ac		
Yes No (If no provide me	Total (Stu	dan e c	TO THE PARTY OF TH	
7. Access used to remove centage.	asurements)	- / L	iquid Level = %Sludge & Scum	
7. Access used to remove septage: 2. If maintenance hole was used were	Maintenance Hole	Other (Go to #3 below)	* Tank must be pumped if this value is greater than 25%	J
Explanation:	en covers securely replac	ed? Wyes [No plea	is greater than 25%.	
<ol> <li>If owner refuses to allow a Subsurfa them complete and sign the following</li> </ol>	40.5			
them complete and sign the following	ce Sewage Treatment ; ng statement:	System (SSTS) to be pun	ped through the mail	
	(Outports	•	the maintenance hole, have	
hole. I understand that removal of solid 4. Is the tank designed as a leaky tank? exa	is and liquids through a	se to allow the removal o	solids and liquids through the maintenance	
4. Is the tank designed as a leaky tank? exa	mple: seepage nit cessor	ner access points is not co	Posidered maintenance	
Tank#1 Yes No Verificatio Me		on, anywell, leaching pit		
Tank#2 Tives It No Voice				
5. is there evidence of tank leakage from damaged, cracked, or structurally unsoin Tank	hod Used:	7		
damaged, cracked, or structurally unso	septic, holding, pretr	eatment or pump tank #	Blowst.	
Tank	Leaking Out	COVers?	crow the operating depth or evidence of	
Septic/Holding Tank #1	Yes No	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	☐ Yes ☑ No	Yes No	
Pretreatment Tank	☐Yes ☐No	Yes No	☐ Yes ▼No	
Pump Tank	114	Yes No	□Yes □No	
6. How many gallons of septage were remove	ed?	Yes No	Li Yes Li No	
Tank#1 1500 Tank#2 1000	) .			
7. Other information: List any troubleshooting	Pretreatment Tar	lkPur	np Tank	
	g, minor repairs condu	cted, tank safety concern	IS. Brother	
THE THE PROPERTY OF THE PARTY O	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW			
and made the observations, or a  Maintainer's Name: Olson's Sewer Service Inc.	mesota certified SSTS Ma	intainer that I personally	Conductod	
Maintainer's Name: Olson's Sewer Service, Inc.			12 100	
Maintainer's Lieure and		Address: 17638 Lyons Str	eet NE, Forest Lake, MN	
Maintainer's Signature	r's Phone #: 651-464-20	82	2009	
	$\langle \lambda$	Date: U/c	.1	
V			124	