## ZIERKE SOIL TESTING

Debbie Chauss 9565 187<sup>th</sup> St N Forest Lake, MN 55025

4/9/2024

Dear Debbie Chauss,

At your request, I have conducted a septic inspection to determine the compliance status of your septic system pursuant to Minnesota Rules Chapter 7080.1500.

The compliance test set out in 7080.1500 has three main inquiries: 1). Is the system functioning hydraulically (disposing of effluent in a manner that prevents it from coming in contact with people)? 2). Are the septic tanks water tight? 3). Does the system have sufficient vertical separation between the bottom of the septic system and restrictive layers (bedrock, standing water, seasonally wet layers, etc) to provide full treatment of effluent?

Based off of these criteria, your septic system is <u>compliant</u>. A certification of compliance is in effect for three years from the date it is issued. To be clear, this should not be construed as a guarantee of future system function – there are too many factors that influence the lifespan of a septic system for an inspector to predict or even guess how long a septic system will last. A copy of this report will be filed with your local unit of government for their records.

Sincerely,

Benjamin Zierke

Benjamin Zieska

MPCA Lic 119, Cert 9594

ADDRESS: 28587 Jeffrey Ave Chisago City, MN 55013

PHONE 651-249-1346

EMAIL benzierke@gmail.com



## Compliance inspection report form

**Existing Subsurface Sewage Treatment System (SSTS)** 

520 Lafayette Road North St. Paul, MN 55155-4194

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at <a href="https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf">https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf</a>.

Property information	Local tracking number:	
Parcel ID# or Sec/Twp/Range: 3603221240003	Reason for Inspection Sale	
Local regulatory authority info: Washington County		
Property address: 9565 187 <sup>th</sup> St N Forest Lake, MN 55025		
Owner/representative: Debbie Chauss	Owner's phone:	
Brief system description: 1500 gallon septic tank, 1000 gallon se	eptic tank, 1000 gallon lift tank, mound dispersal system	
System status		
System status on date (mm/dd/yyyy):4/9/2024		
□ Compliant – Certificate of compliance*	☐ Noncompliant – Notice of noncompliance	
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.	
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)  *Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.	
Reason(s) for noncompliance (check all applicab	ole)	
☐ Impact on public health (Compliance component #1)	) – Imminent threat to public health and safety	
☐ Tank integrity (Compliance component #2) – Failing	to protect groundwater	
☐ Other Compliance Conditions (Compliance components)		
☐ Other Compliance Conditions (Compliance components)		
-	2500 (Compliance component #3) – Failing to protect groundwater	
Soil separation (Compliance component #5) – Failin		
	npliance component #4) – Noncompliant - local ordinance applies	
Comments or recommendations		
No issues observed with system during site visit 4/9/2024	<b>.</b>	
Certification		
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,	
,	and correct, to the best of my knowledge, and that this information can be	
Business name: Zierke Soil Testing	Certification number: 9594	
Inspector signature: Benjamin Zierke	License number: 119	
(This document has been electronically sign	ned) Phone: 651-249-1346	
Necessary or locally required supporting do	cumentation (must be attached)	
☐ Soil observation logs ☐ System/As-Built ☐ Locally re	equired forms	
Other information (list):		

Compliance criteria:		Attached supporting documentation:	
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other:	
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* ⊠ No		
Any "yes" answer above indicates the system is an imminent threat to public health and safety.			
Describe verification methods and	results:		
None of the above observed.			
which cutter. Consuling a		af F	
nk integrity – Compliance Compliance criteria:	component #2		
Compliance criteria:  System consists of a seepage pit,	component #2	of 5  Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector	
Compliance criteria:	· 	Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector	milies
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	· 	Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	_ Yes* ⊠ No	Attached supporting documentation:  ☑ Empty tank(s) viewed by inspector  Name of maintenance business: Sr  License number of maintenance business: 24	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	_ Yes* ⊠ No	Attached supporting documentation:  ☑ Empty tank(s) viewed by inspector  Name of maintenance business: Sr  License number of maintenance business: 24	428
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	_ Yes* ⊠ No	Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector  Name of maintenance business: Sr  License number of maintenance business: 24  Date of maintenance: 4/2	428 /9/2024
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business: 24  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance	428 /9/2024 ee years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic	Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business: Sr License number of maintenance business: 24  Date of maintenance: 4//  Existing tank integrity assessment (Attach)  Date of maintenance (mm/dd/yyyy): (must be within three  (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1))  Tank is Noncompliant (pumping not necessary -	428 /9/2024 ee years) complies w
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic	Yes* No  Yes* No  Yes* No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business: 24  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1))	428 /9/2024 ee years) complies w


	roperty Address: 9565 187 <sup>th</sup> St N Forest Lake, MN 55025	
	usiness Name: Zierke Soil Testing	Date: 4/9/2024
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsec	cured?
	☐ Yes* ☑ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes*
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	 ☐ Yes* ⊠ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation:   Not applicable	
4.	Operating permit and nitrogen BMP* – Compliance component #4 of	5 Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No I	"yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design?   Yes No I	•
	BMP = Best Management Practice(s) specified in the system design	yee , 2 selen le lequileu
	If the answer to both questions is "no", this section does not need to be completed	
	·	•
	Compliance criteria:	
	a. Have the operating permit requirements been met?	
	b. Is the required nitrogen BMP in place and properly functioning?   Yes  No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Describe vernication metrious and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Describe vernication methods and results.	
	Attached supporting documentation:   Operating permit (Attach)	

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

usiness Name: Zierke Soil Testing		Date: <u>4/9/2024</u>		
Soil separation – Compliand	ce component #5 o	f 5		
Date of installation 6/26/2013 (mm/dd/yyyy)	Unknown			
Shoreland/Wellhead protection/Food beverage lodging?	☐ Yes  ☐ No	Attached supporting documentation:  Soil observation logs completed for the repo		
Compliance criteria (select one):		☐ Two previous verifications of required vertical separation		
5a. For systems built prior to April 1, 19	96, and Yes No*	☐ Not applicable (No soil treatment are	a)	
not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:				
Drainfield has at least a two-foot ver separation distance from periodically saturated soil or bedrock.				
5b. Non-performance systems built		Indicate depths or elevations		
April 1, 1996, or later or for non- performance systems located in Sho	preland	A. Bottom of distribution media	103.7'	
or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:  Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*	ving a	B. Periodically saturated soil/bedrock	99.0'	
	ment.	C. System separation	4.7'	
	y	D. Required compliance separation*	3.0'	
		*May be reduced up to 15 percent if all Ordinance.	owed by Local	
5c. "Experimental", "Other", or "Perform systems built under pre-2008 Rules; Type IV or V systems built under 20 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License req 2,500 gallons per day; Advanced Ins License required > 2,500 gallons pe	: 08 uired ≤ spector			
Drainfield meets the designed vertic separation distance from periodically saturated soil or bedrock.				
*Any "no" answer above indicate failing to protect groundwater.	es the system is			
Describe verification methods and re	esults:			
See attached boring log and elevations	:			

**Upgrade requirements:** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

800-657-3864



## **Logs of Soil Borings**

Location of Project: 9565 187th St N Forest Lake, MN 55025

Borings Made by Ben Zierke Date: 4/9/2024

Hand bucket auger used for borings; USDA - SCS Soil Classification used.

Depth, in Inches	Boring Number 1	Depth, in Inches	Boring Number 2
0-19"	10YR 3/3 fine sandy loam	0	
19-30"	10YR 4/3 loamy fine sand, few 10YR 5/1 depletions, 7.5YR 5/6 iron stains at 28" *12" separation credit		
End of boring at Standing water table Present at Standing water not p Mottled Soil: Observed at Mottled soil not pres Comments:	feet of depth Hours after boring resent in hole  1 feet of depth	End of boring at Standing water tab Present at Standing water not p Mottled Soil: Observed at Mottled soil not pres Comments:	feet of depth Hours after boring present in hole feet of depth
Depth, in Inches	Boring Number 3	Depth, in Inches	Boring Number 4
O	feet	O	feet
End of boring at Standing water table Present at Standing water not p Mottled Soil: Observed at Mottled soil not pres Comments:	le: feet of depth Hours after boring resent in hole feet of depth	End of boring at Standing water tal: Present at Standing water not p Mottled Soil: Observed at Mottled soil not pre: Comments:	feet of depth feet of depth feet of depth feet of depth