Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information

Property/Owner Informat	ion Permit #: <u>B852GH35S14</u>
Complete in its entirety to constitute a valid ma maintenance activities and remain on-site for the	aintenance permit. This permit must be completed prior to performing
Date of Maintenance: 6/18/24	Property ID #:
Property Address: 20233 Quincli Street Address	Ave N Scardia MN 55073 City State Zip
Property Owner Name: Barb + Don 1	Mitcheil
Maintenance Performed	
Tanks Pumped: □ Emergency □ Home Sale □ High-level alarm Routine/Maintenance □ Compliance Inspection □ Repair □ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Were all covers securely replaced? Yes□ Is the tank designed as a leaky? Ex. Seepage	Penance Hole Other (enter authorization code) No If No, Explain: ge pit, cesspool drywell leaching pit Uisual Gallons Removed:
	sed: Gallons Removed:
Tank #3: ☐ Yes ☐ No Verification Method U Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Tank #4: ☐ Yes ☐ No Verification Method U Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Pump Tank: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	Sed:Gallons Removed: No Cover Damaged: Yes \(\text{No} \) Od Used:Gallons Removed: No Cover Damaged: Yes \(\text{No} \)
Waste Disposal Method ☆ Treatment plant Other remarks or Concerns:	t 🔲 Land Apply: Location
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Fores Phone Number: 651-464-2082 License N	st Lake, MN 55025 Jumber: L216 aintainer that I personally conducted the work and made the observations, or directly

