## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information Permit #: <u>G6931T3G240</u>	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 7/10/24 Property ID #:	
Property Address: 9400 170 5 Street Address	HN Hugo MN 55038 City State Zip
Property Owner Name: Cocdon Cole	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scum  Tanks must be Pumped if 25% or greater
Maintenance Information  Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced?  Yes \_No If No, Explain:  Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: \_Yes \( \frac{1}{2} \) No Verification Method Used: Gallons Removed: Seepage Design Cover Damaged: \_Yes \( \frac{1}{2} \) No	
Tank #2:□ Yes □ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Tank #3: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Tank #4: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Waste Disposal Method: Treatment plant □ Land Apply: Location Other remarks or Concerns:	
	st Lake, MN 55025 Number: L216 Iaintainer that I personally conducted the work and made the observations, or directly

