Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informa	tion Permit #: 19381h36242
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 7/15/24 Property ID #:	
Property Address: 10277 Kuller Street Address	City State Zip
Property Address: 10277 Kuller Road North Scandia 55673 Street Address City State Zip Property Owner Name: May e Musiosici	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☑ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Maintenance Informatio Access used to remove septage: ✓ Maintenance	tenance Hole Other (enter authorization code)
Were all covers securely replaced? ★Yes No If No, Explain:	
Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit	
Tank #1: ☑Yes ☐ No Verification Method Used: Viguel ~ Black Tank Gallons Removed: 780 Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑ No Cover Damaged: ☐ Yes ☑ No	
	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	Gallons Removed:
Tank #3:□Yes □ No Verification Method	Used:Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	□ No. Cover Damaged:□Ves□No.
Tank #4: □Yes □ No Verification Method	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: ☐ Yes ☐ No Verification Meth	
Leaking Out:□Yes□No Leaking In:□ Yes [
Waste Disposal Method: ☐ Treatment plan	
Other remarks or Concerns:	
	est Lake, MN 55025 Number: L216
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly	

Washington County

Maintenance activities must be reported to the Department within 90 days.