

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	: 7/22/2024	Reason for Maintenance:	Routine	
Property Address:	'613 Laverne Ave ,	Cottage Grove, MN	Property Owner's Name:	Julie Hubeler
Municipality:	ZI	P: <u>55016</u> Property Id	entification Number:	
Maintenance Permit No:		Maintainer Name	and License No. Schlom	ca Service LLC/L2989
Maintenance Permit	NO:	Maintainer Name a	and License No. Scholler	a service LEC/12707

Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)		
<ul> <li>Tank(s) Pumped</li> <li>Sludge and scum measured Do tanks need to be pumped?</li> <li>Yes No (if no provide measurements)</li> </ul>	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater		

1. Access used to remove septage: 
Maintenance Hole Other (enter authorization code)

- 2. Were all covers securely replaced? Tes No N/A
- 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? <u>No couldn't confirm precast vis</u> No - couldn't confirm precast via camera

Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Some answers un	Ves No known. Pumped thro	<u>Yes</u> No ugh inspection pipe.
Septic/Holding Tank #2	- I Yes I No	- Yes No	Yes - No-
Pretreatment Tank	🗌 Yes 🗌 No	□ Yes □No	🗆 Yes 🗌 No
Pump Tank	🗌 Yes 🗌 No	□ Yes □ No	□ Yes □No

4. How many gallons of septage were removed?

Tank #1<u>1000</u> gal Tank #2<u>1000</u> gal Pretreatment tank\_\_\_\_\_\_ gal Pump Tank \_\_\_\_ \_\_ gal

5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.

Some answers unknown. Pumped through inspection pipe.

Location of septage disposal: Metro MCES WWTP

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.