Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 95863036633	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 8/27/2029 Property ID #:	
Property Address: 19350 Orwa Street Address	ell Avenue Marine MV 55047 City State Zip
Property Owner Name: John + Laura Dinovan	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scun Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Seepage pit, cesspool drywell leaching pit Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Gallons Removed: Gallons Removed:	
	Used:Gallons Removed: □ No Cover Damaged:□Yes□No Used:Gallons Removed: □ No Cover Damaged:□Yes□No
Leaking Out(☐Yes No Leaking In:☐Yes No Cover Damaged:☐Yes☐No Waste Disposal Method:☐Treatment plant ☐ Land Apply: Location Other remarks or Concerns:	
	Number: L216 Maintainer that I personally conducted the work and made the observations, or directly

