#### **Midwest Sewer Services**

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal MPCA Licensed Advanced Inspector

#### SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

**Inspection Address:** 21970 Manning Trl N, Scandia, MN 55073

#### REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system (installed in 2018) consists of two pre-cast septic tanks, a pre-cast lift tank, and a mound. Smilie's Sewer Service pumped the septic tank on August 26, 2024. This house is presently vacant.

Although not a compliance criteria, it should be noted that the effluent alarm electrical is poorly configured and should be re-configured to reduce the potential for problems.

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



520 Lafayette Road North St. Paul, MN 55155-4194

## Compliance inspection report form

**Existing Subsurface Sewage Treatment System (SSTS)** 

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at <a href="https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf">https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf</a>.

Property information	Local tracking	number:
Parcel ID# or Sec/Twp/Range:	Reason for Inspection	Property Transfer
Local regulatory authority info: Washington County		
Property address: 21970 Manning Tr N, Scandia, MN 55073		
Owner/representative: Lewis Berge		Owner's phone: 651-402-5581
Brief system description: Two pre-cast septic tanks, a pre-cast I	ift tank, and a mound.	
System status		
System status on date (mm/dd/yyyy): 8/26/2024		
□ Compliant – Certificate of compliance*	☐ Noncompliant – Notice	ce of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and		ound water must be upgraded, replaced, or ime required by local ordinance.
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	upgraded, replaced, or its us	health and safety (ITPHS) must be e discontinued within ten months of receipt
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	of this notice or within a shor under section 145A.04 subdi	ter period if required by local ordinance or vision 8.
Reason(s) for noncompliance (check all applicate	ole)	
☐ Impact on public health (Compliance component #1) – Immi	•	nd safety
☐ Tank integrity (Compliance component #2) – Failing to prote	ct groundwater	
$\hfill \Box$ Other Compliance Conditions (Compliance component #3) -	- Imminent threat to public he	ealth and safety
☐ Other Compliance Conditions (Compliance component #3) -	- Failing to protect groundwa	ter
☐ System not abandoned according to Minn. R. 7080.2500 (Co		Failing to protect groundwater
Soil separation (Compliance component #5) – Failing to prot	•	
Operating permit/monitoring plan requirements (Compliance	component #4) – Noncompi	liant - local ordinance applies
Comments or recommendations		
Certification		_
I hereby certify that all the necessary information has been gathered future system performance has been nor can be made due to unknown inadequate maintenance, or future water usage.		
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my	knowledge, and that this information can be
Business name: Midwest Sewer Services		Certification number: 5342/9852
Inspector signature: Brian Humpal (After 1)	<u></u>	License number: L2896
(This document has been electronically sign	ned)	Phone: 651-492-7550
Necessary or locally required supporting do		
☐ Soil observation logs ☐ System/As-Built ☐ Locally red	•	ity Assessment
Other information (list): Report Summary, Property Informa	tion, Disclaimer	

ss Name: Midwest Sewer Services		Date: <u>8/</u>	26/2024
npact on public health – Co	ompliance comp	ponent #1 of 5	
Compliance criteria:		Attached supporting documentation	1:
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes* ⊠ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* ⊠ No		
Any "yes" answer above indicates imminent threat to public health a			
Describe verification methods and	l results:		
None of the above found.			
ank integrity – Compliance	component #2	of 5	
ank integrity – Compliance	component #2	of 5	
ank integrity – Compliance Compliance criteria:	component #2	of 5  Attached supporting documentation	<u> </u>
Compliance criteria:	· 	Attached supporting documentation	ı:
Compliance criteria:  System consists of a seepage pit,	component #2		ı:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,	· 	Attached supporting documentation	
Compliance criteria:  System consists of a seepage pit,	· 	Attached supporting documentation	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	Yes* ⊠ No	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:	Smilie's S Service
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	· 	Attached supporting documentation  ⊠ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busine	Smilie's S Service ss: L2428
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:	Smilie's S Service ss: L2428 8/26/2024
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation  ⊠ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busine  Date of maintenance:  □ Existing tank integrity assessment (Atta	Smilie's S Service ss: L2428 8/26/2024
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	Yes* ⊠ No	Attached supporting documentation  ⊠ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busine  Date of maintenance:  □ Existing tank integrity assessment (Atta	Smilie's S <u>Service</u> ss: <u>L2428</u> <u>8/26/2024</u> ch)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	Yes* ⊠ No	Attached supporting documentation  ⊠ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busine  Date of maintenance:  □ Existing tank integrity assessment (Atta	Smilie's S Service ss: <u>L2428</u> 8/26/2024 ch)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance  (mm/dd/yyyy):  (must be with	Smilie's S Service ss: <u>L2428</u> 8/26/2024 ch)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the companies of the companies)  (See form instructions to ensure assess the companies of	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance  (mm/dd/yyyy):  (must be with	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the companies of the companies)  (See form instructions to ensure assess the companies of	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicing is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ eates the system	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  ☐ Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy):  (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))  ☐ Tank is Noncompliant (pumping not necessor)	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ eates the system	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  ☐ Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy):  (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))  ☐ Tank is Noncompliant (pumping not necessor)	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicing is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ eates the system	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  ☐ Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy):  (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))  ☐ Tank is Noncompliant (pumping not necessor)	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicing is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ eates the system	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  ☐ Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy):  (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))  ☐ Tank is Noncompliant (pumping not necessor)	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicing is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ eates the system	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  ☐ Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy):  (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))  ☐ Tank is Noncompliant (pumping not necessor)	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicing is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ☐ eates the system	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines  Date of maintenance:  ☐ Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy):  (must be with (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))  ☐ Tank is Noncompliant (pumping not necessor)	Smilie's S Service ss: L2428 8/26/2024 ch) n three years ment complie

Pro	operty Address: _21970 Manning Tr N, Scandia, MN 55073	
Bus	siness Name: Midwest Sewer Services	Date: 8/26/2024
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or u	nsecured?
	☐ Yes* ☒ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or sa	afety? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☒ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation:   Not applicable	
4	Operating permit and nitrogen BMP* – Compliance component #4	1 of 5 ⊠ Not applicable
		o If "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design?   Yes  No	o If "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design	-4- d
	If the answer to both questions is "no", this section does not need to be completed.	etea.
	Compliance criteria:	
	a. Have the operating permit requirements been met?	
	b. Is the required nitrogen BMP in place and properly functioning?  Yes No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Attached supporting documentation:   Operating permit (Attach)	

https://www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • Use your preferred relay service • Available in alternative formats wq-wwists4-31b • 4/28/2021 Page 3 of 4

pperty Address: 21970 Manning Tr N, Scandia, siness Name: Midwest Sewer Services	MN 5507	3	Date: 8/	26/2024
	nnana	nt #F 0		
Soil separation — Compliance cor         Date of installation       2018 (mm/dd/yyyy)	Unkr		13	
Shoreland/Wellhead protection/Food beverage lodging?  Compliance criteria (select one):	⊠ Yes	□No	Attached supporting documentation:  ☐ Soil observation logs completed for the supporting documentation:  ☐ Two previous verifications of required.	-
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:  Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.	☐ Yes	□ No*	<ul> <li>□ Not applicable (No soil treatment are</li> <li>☑ Reviewed design and permit records</li> </ul>	,
5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:  Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*	⊠ Yes	□ No*	Indicate depths or elevations  A. Bottom of distribution media  B. Periodically saturated soil/bedrock  C. System separation  D. Required compliance separation*  *May be reduced up to 15 percent if all Ordinance.	See Attached Boring Log(s)
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)  Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.	☐ Yes	□ No*		

**Upgrade requirements:** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

Use your preferred relay service

# <u>Midwest & of 11</u> Subsurface Sewage Treatment System Owner/Property Information

	A Compliance Inspection.
Date of Inspection: August 26, 2024	Time: 10:45 AM
Property Address: 21970 Manning Trl N, Scandia, MN	Zip: 55073
Property Owner: Lewis Berge	Phone: 651-402-5581
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 2       Fiberglass       Rock trench         Aerobic       Plastic       Gravelless trench         Lift       Metal       Chamber trench         Holding       Concrete       Seepage bed         Other:       Block       Mound         Other       At-grade	Other  Alternative system  Experimental system  Cesspool system  Other system
Are the tank maintenance covers accessible?   Yes   No *I performed through the maintenance holes. Maintenance hole co the ground surface to facilitate access and proper maintenance of	vers should be made accessible to
Year house built: 1973 Year septic installed: 2018	Tank size (gals.): 1000
	residents in home?
Number of bedrooms? 3 Are all floors drained by	<u> </u>
Garbage disposal? Whirlpool bath	1?
More than one system (laundry, etc.)?	
Does this property have any footing drain tiles connected to the	septic system?
Are any buildings on this property such as garages or out-buildir	igs connected to this system?
	J.
Are there any additional systems on this property serving other b	J.
Location of septic system on lot? West Side	ouildings?
Location of septic system on lot? West Side  Location of water well on lot? South Side  Is the septic system on lot?	ne well a deep well? Y
Location of septic system on lot? West Side	ne well a deep well? Y s: tree roots, sewage back-ups,
Location of septic system on lot? West Side  Location of water well on lot? South Side  Have you ever experienced any problems with the system such a surfacing of sewage onto the ground, septic tank overflowing, et to the system?  If yes, explain:  When was the system last pumped? 8/26/2024  Name of pu	ne well a deep well? Y s: tree roots, sewage back-ups, c.; or have any repairs been made
Location of septic system on lot? West Side  Location of water well on lot? South Side  Have you ever experienced any problems with the system such a surfacing of sewage onto the ground, septic tank overflowing, et to the system?  If yes, explain:  When was the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system	ne well a deep well? Y s: tree roots, sewage back-ups, c.; or have any repairs been made  mper: Smilie's Sewer Service m on a monitoring plan?
Location of septic system on lot? West Side  Location of water well on lot? South Side  Have you ever experienced any problems with the system such a surfacing of sewage onto the ground, septic tank overflowing, et to the system?  If yes, explain:  When was the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system to the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system to the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system to the system last pumped? 8/26/2024	ne well a deep well? Y s: tree roots, sewage back-ups, c.; or have any repairs been made  mper: Smilie's Sewer Service m on a monitoring plan?
Location of septic system on lot? West Side  Location of water well on lot? South Side  Have you ever experienced any problems with the system such a surfacing of sewage onto the ground, septic tank overflowing, et to the system?  If yes, explain:  When was the system last pumped? 8/26/2024  Name of pu How often pumped in previous years?  Is system Have you received notices from any government agency concerns Is your property located in a shoreland management area? Y	ne well a deep well? Y s: tree roots, sewage back-ups, c.; or have any repairs been made  mper: Smilie's Sewer Service m on a monitoring plan? ning this system?
Location of septic system on lot? West Side  Location of water well on lot? South Side  Have you ever experienced any problems with the system such a surfacing of sewage onto the ground, septic tank overflowing, et to the system?  If yes, explain:  When was the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system to the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system to the system last pumped? 8/26/2024  Name of pure How often pumped in previous years?  Is system to the system last pumped? 8/26/2024	ne well a deep well? Y s: tree roots, sewage back-ups, c.; or have any repairs been made  mper: Smilie's Sewer Service m on a monitoring plan? ning this system?

by Inspect Minnesota and Midwest Soil Testing	•	
Owner/Occupant:	Date:	

NO SCALE

21970 Manning Trail N, Scandia, MN 55073



Installation Permits Installation Permit Site Review UID # 17019 Installation Permit: Permit # 2018-0972

**Status: Review Complete** 

Washington County Public Health & Environment 14949 - 62ND ST N, PO BOX 6, STILLWATER, MN 55082-0006 (651) 430-6655 FAX (651) 430-6730

#### **Site Inspection**

Date of the soil observation:	09/06/2018
Inspector:	Tyler Dale
Soil Information narrative:	Shoulder landscape position. Grass with hardwoods. Taken at 9:30 AM under sunny conditions.
Soil Parent Material Select all that apply:	<u>Till</u>
Parent Material:	Till
Landscape Position Please choose one:	Summit
Vegetation:	Grass with hardwoods
Soil Survey Map Unit(s) with description:	132D�Hayden fine sandy loam, 12 to 25 percent slopes

#### Soil Horizon Level 1

Depth:	0-5 Inches
Texture:	fine sandy loam
Matrix Color:	10 YR 2/2
Rock Fragment %:	0-35%
Is this the Restrictive Layer?	<u>No</u>

#### **Soil Horizon Level 2**

Depth:	5-12 Inches
Texture:	fine sandy loam
Matrix Color:	10 YR 3/4
Rock Fragment %:	<u>0-35%</u>
Redox Kind(s):	Concentrations
:	7.5 YR 5/6 at 26
Saturated Soil Indicator(s):	<u>S2</u>
Is this the Restrictive Layer?	<u>Yes</u>

#### **Restricitve Layer Depth**

|--|--|--|--|

#### **Approvals**

Approval	Signature
#1 Site Review Performed	Nate Arthur - 11/06/2018 9:18 AM
	bd2c9b88dbee7f927b551cc52ce3c482
	4d78783b256444a99d22b3f1ea5f4677

#### **Public Notes**

Text:	
File(s):	

#### **Internal Notes**

Text:	
File(s):	

### **SOIL BORING LOG**

MAC'S SEWER SERVICE: By Michael D. McElhatton-Designer I

997578004CCCR49FI	LEWIS BERGE	<b>5</b> 7.	Date: 7/25/2018 .	
cation:	21970 MANNING TR. N., SCANDIA, N	1N.	USDA-SCS; Recovered by hand au	
<b>Depth</b> Inches	SOIL BORING # 1 Surface Elevation: approx 100'	Depth Inches	SOIL BORING # 2 Surface Elevation: .approx. 102'6".	
0-5	10yr 3/3 dark brown fine sand	0-22	10yr 2/2 dark brown sandy loam	
5-18	10yr 3/4 dark brown fine sand & gravel	6-16	10yr 3/4 dark brown sandy loam	
	Mottling 14"+	16-20	10yr 3/4 dark brown sandy loam & gravel	
			Mottling 12"+	
End of I	Boring at 1.5 ft.	End of Boring at 1.7 ft.		
	g Water at ft. sent in holeX	Standing Water at ft.  Not present in hole X		
	soil at 1.2 ft	Mottled soil at ft. Not present in hole		
Comme	nts:	Comments:		
Depth Inches	SOIL BORING # 3 Surface Elevation: approx 101' 6"	Depth Inches	SOIL BORING # 4 Surface Elevation: approx. 99'	
0-6	10yr 3/3 dark brown fine sand	0-6	10yr 3/2 dark brown sandy loam	
6-18	10yr 4/4 dark brown fine sand	6-18	10yr 4/3 dark brown sandy loam	
18-24	10yr 4/4 dark brown fine sand & gravel	18-24	10yr 3/4 dark brown sandy loam & gravel	
	Mottling 18"+	\$	Mottling 18"+	
End of l	End of Boring at ft.		End of Boring at2_ ft	
	g Water atft. sent in hole	Standing Water atft.  Not present in holeX		
	soil atft.	-	Mottled soil atft.  Not present in hole	
Comme	nts:	Comments:		

#### **DISCLAIMER**

## Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include only verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.