## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 19516237236
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 9/19/2029 Property ID #:
Property Address: 23275 Itasca Ave Worth, Furest Lake MW 55025  Street Address City State Zip
Property Owner Name: Robert & Eilen Corwin
Maintenance Performed
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair  Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in
Maintenance Information
Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced? Yes \_No   If No, Explain:    Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: \_Yes \_No Verification Method Used: Gallons Removed:    Leaking Out: \_Yes \_No Leaking   In \_Yes \_No   Cover Damaged: \_Yes \_No    Tank #2: \_Yes \_No Verification Method Used: Gallons Removed:    Leaking Out: \_Yes \_No Leaking   In: \_Yes \_No   Cover Damaged: \_Yes \_No    Tank #3: \_Yes \_No Verification Method Used: Gallons Removed:    Leaking Out: \_Yes \_No Leaking   In: \_Yes \_No   Cover Damaged: \_Yes \_No    Tank #4: \_Yes \_No Verification Method Used: Gallons Removed:    Leaking Out: \_Yes \_No Leaking   In: \_Yes \_No   Cover Damaged: \_Yes \_No    Pump Tank: \_Yes \_No Verification Method Used: Gallons Removed:    Leaking Out: \_Yes \_No Leaking   In: \_Yes \_No   Cover Damaged: \_Yes \_No    Waste Disposal Method: \_Treatment plant \_ Land Apply: Location    Other parameters are Consequent.
Other remarks or Concerns:
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature:



Maintenance activities must be reported to the Department within 90 days.