

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	: <u>9/16/2024</u> Reason	Tor manifectance.	Routine	- 11-11:	
Property Address:	1250 Pasture Ridge Rd S, A	Afton, MN F	Property Owner's N	ame: Juliann Ash	ncraft
Municipality:	ZIP: <u>550</u>	001 Property Ide	ntification Number:		
	No:				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
✓ Tank(s) Pumped☐ Sludge and scum measured			Tank in		
			Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100		
Do tanks need to be pumped?				_evel X 10L nks must be pumped	
☐ Yes ☐ No (i	f no provide measurements)	- % Stadge & SC	um ra	nks must be pumped	11 25% of greater
1 Access used to re	emove septage: Maintena	ance Hole X Other (enter authorization co	ode)	
	securely replaced?		rootmant or numn	tank holow the one	rating depth or
2. 12 mere evidence					
evidence of dar	e of tank leakage from a se naged, cracked, or structu	rally unsound main	itenance hole cove	ers? No - couldn't	conf <u>irm precast via</u>
evidence of dar	F		The second second	camera	confirm precast via
evidence of dar	Tank	Leaking Out	tenance hole cove	No - couldn't camera Cover Damage	conf <u>irm precast via</u>
evidence of dar	F	Leaking Out	Leaking In	Cover Damage	conf <u>irm precast via</u>
evidence of dar	Tank	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dough inspection pipe.	conf <u>irm precast via</u>
evidence of dar	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dugh inspection pipe. Yes No	conf <u>irm precast via</u>
evidence of dar	Tank Septic/Holding Tank #1	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dough inspection pipe.	conf <u>irm</u> precast via
evidence of dar	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dugh inspection pipe. Yes No	conf <u>irm</u> precast via
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Some answers un Yes No Yes No Yes No	Leaking In Yes No No No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No	conf <u>irm</u> precast via
4. How many gallor	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ns of septage were remove	Leaking Out Yes No Some answers un Yes No Yes No Yes No	Leaking In Yes No- known. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Yes No	
4. How many gallor Tank #1 1300	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ns of septage were removed gal Tank #2	Leaking Out Yes No Some answers un Yes No Yes No Yes No Yes No gal Pretreatmer	Leaking In Yes No Iknown. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Yes No	gal
4. How many gallor Tank #1 1300 5. Other information	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ns of septage were removed gal Tank #2 con: List any troubleshooting	Leaking Out Yes No Some answers un Yes No Yes No Yes No gal Pretreatmen g, minor repairs co	Leaking In Yes No Iknown. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Yes No	gal
4. How many gallor Tank #1 1300 5. Other information	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ns of septage were removed gal Tank #2	Leaking Out Yes No Some answers un Yes No Yes No Yes No gal Pretreatmen g, minor repairs co	Leaking In Yes No Iknown. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Yes No	gal

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.