Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 00494435426	
	aintenance normit This require
Date of Maintenance: 06/16/2024	/ Property ID #:
Property Address: 4311 Necul Street Address	Ave So Aften MM 550001 City State Zip
Property Owner Name: MCWK To	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in
☑ Routine/Maintenance☐ Compliance Inspection☐ Repair☐ Other:	Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Were all covers securely replaced?	enance Hole Other (enter authorization code) No If No, Explain:
Is the tank designed as a leaky? Ex. Seepag	ge pit, cesspool drywell leaching pit
Tank #1: ☐ Yes ☑ No Verification Method L Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑	- Gallotto McHiloved.
Tank #2:□Yes□ No Verification Method L	Jsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐] No Cover Damaged: □Yes□No
Tank #3:□Yes □ No Verification Method L Leaking Out:□Yes□No Leaking In:□ Yes □	Jsed: Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method U	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	- Taniens nemoved.
Pump Tank: ☐ Yes ☐ No Verification Metho	
Leaking Out:□Yes□No Leaking In:□ Yes□	No Cover Damaged: ☐ Yes ☐ No
Waste Disposal Method: Treatment plan Other remarks or Concerns: M41 hoves	t ☐ Land Apply: Location
repaire in the parter marice of this job.	License Number: L4251 aintainer that I personally conducted the work and made the observations, or directly
Maintenance activities must be reported to	o the Department within 90 days

Washington County