# **Midwest Sewer Services**

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal MPCA Licensed Advanced Inspector

## SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

**Inspection Address:** 2706 Meadow Pass, Afton, MN 55001

## **REPORT SUMMARY**

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system (installed in 2017) consists of two pre-cast septic tanks, a pre-cast lift tank, and a seepage bed. Pinky's Sewer Service pumped the tanks on September 30, 2024.

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



520 Lafayette Road North St. Paul, MN 55155-4194

# Compliance inspection report form

**Existing Subsurface Sewage Treatment System (SSTS)** 

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at <a href="https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf">https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf</a>.

Property information	Local tracking number:
Parcel ID# or Sec/Twp/Range:	Reason for Inspection Property Transfer
Local regulatory authority info: Washington County	
Property address: 2706 Meadow Pass, Afton, MN 55001	
Owner/representative: Chad & Rebecca Wall/Ryan Baer - Kell	er Williams Owner's phone: 651-332-0309
Brief system description: Two pre-cast septic tanks, a pre-cast l	
System status	
System status on date (mm/dd/yyyy): 9/30/2024	
	☐ Noncompliant – Notice of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.	of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.
Reason(s) for noncompliance (check all applicab	ole)
<ul> <li>Impact on public health (Compliance component #1) − Immin</li> <li>Tank integrity (Compliance component #2) − Failing to prote</li> <li>Other Compliance Conditions (Compliance component #3) −</li> <li>System not abandoned according to Minn. R. 7080.2500 (Compliance component #5) − Failing to prote</li> <li>Operating permit/monitoring plan requirements (Compliance Comments or recommendations</li> </ul>	ct groundwater - Imminent threat to public health and safety - Failing to protect groundwater - Impliance component #3) – Failing to protect groundwater - Failing to protect groundwater
Certification	
	to determine the compliance status of this system. No determination of wn conditions during system construction, possible abuse of the system,
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my knowledge, and that this information can be
Business name: Midwest Sewer Services	Certification number: 5342/9852
Inspector signature: Brian Humpal Home	License number: L2896
(This document has been electronically sign	ned) Phone: 651-492-7550
Necessary or locally required supporting do	cumentation (must be attached)
oximes Soil observation logs $oximes$ System/As-Built $oximes$ Locally red	quired forms 🛛 Tank Integrity Assessment 🔲 Operating Permit
☑ Other information (list): Report Summary, Property Information	tion, Disclaimer

ty Address: _2706 Meadow Pass, Afto ss Name: _Midwest Sewer Services		Date: <u>9</u>	9/30/2024
npact on public health – Co	ompliance comp	ponent #1 of 5	
Compliance criteria:	<u> </u>	Attached supporting documentation	n:
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No		
Any "yes" answer above indicates imminent threat to public health an			
Describe verification methods and	results:		
None of the above found.			
ank integrity Compliance	component #2	of E	
ank integrity – Compliance	component #2	of 5	
ank integrity – Compliance Compliance criteria:	component #2	of 5  Attached supporting documentation	on:
Compliance criteria:	•	Attached supporting documentation	n:
Compliance criteria:  System consists of a seepage pit,	component #2		
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,	•	Attached supporting documentation  ☐ Empty tank(s) viewed by inspector	Pinky's Sev
Compliance criteria:  System consists of a seepage pit,	•	Attached supporting documentation	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,	•	Attached supporting documentation  ☐ Empty tank(s) viewed by inspector	Pinky's Sev Service
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	_ Yes* ⊠ No	Attached supporting documentation  ⊠ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busin	Pinky's Sev Service ess: L1673
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	_ Yes* ⊠ No	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:	Pinky's Sev <u>Service</u> ess: <u>L1673</u> 9/30/2024
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	_ Yes* ⊠ No	Attached supporting documentation  ☑ Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  ☐ Existing tank integrity assessment (Attached)	Pinky's Sev <u>Service</u> ess: <u>L1673</u> 9/30/2024
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	_ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  Existing tank integrity assessment (Attached)	Pinky's Sev <u>Service</u> ess: <u>L1673</u> <u>9/30/2024</u>
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with	Pinky's Sev Service ess: L1673 9/30/2024 ach)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicated the service of the sewage tank in the sewage t	Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the minus of the maintenance) (must be with the minus of the	Pinky's Sev Service ess: L1673 9/30/2024 ach)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines of maintenance:  Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicated the service of the sewage tank in the sewage t	Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the minus of the maintenance) (must be with the minus of the	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicated the service of the sewage tank in the sewage t	Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busine	Pinky's Sew Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates is failing to protect groundwate.	Yes* ⊠ No  Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines of maintenance:  Existing tank integrity assessment (Attached Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure assess Minn. R. 7082.0700 subp. 4 B (1))	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicated the service of the sewage tank in the sewage t	Yes* ⊠ No  Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busine	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates is failing to protect groundwate.	Yes* ⊠ No  Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busine	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates is failing to protect groundwate.	Yes* ⊠ No  Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busine	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates is failing to protect groundwate.	Yes* ⊠ No  Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busine	Pinky's Sev Service ess: L1673 9/30/2024 each) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates is failing to protect groundwate.	Yes* ⊠ No  Yes* ⊠ No  Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busine	Pinky's Se Service ess: L1673 9/30/2024 each) hin three years)

https://www.pca.state.mn.us
wq-wwists4-31b • 4/28/2021

Pro	perty Address: 2706 Meadow Pass, Afton, MN 55001	
	siness Name: Midwest Sewer Services	Date: 9/30/2024
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unse	ecured?
	☐ Yes* ☒ No ☐ Unknown	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safet	ty? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☑ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	_	
	Attached supporting documentation:   Not applicable	
4.	Operating permit and nitrogen BMP* – Compliance component #4 c	of 5 🖂 Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No	If "yes", A below is required
	BMP = Best Management Practice(s) specified in the system design	ii yes , b below is required
	If the answer to both questions is "no", this section does not need to be completed	d
	Compliance criteria:	u.
	a. Have the operating permit requirements been met?	
	b. Is the required nitrogen BMP in place and properly functioning?   Yes  No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Describe verification methods and results:	
	Attached supporting documentation:   Operating permit (Attach)	

https://www.pca.state.mn.us
wq-wwists4-31b • 4/28/2021

operty Address: <u>2706 Meadow Pass, Afton, MN</u>	55001			
siness Name: Midwest Sewer Services			Date: <u>9</u>	/30/2024
Soil separation – Compliance cor	mpone	nt #5 o	f 5	
Date of installation 2017 (mm/dd/yyyy)	_ 🗌 Unkr	nown		
Shoreland/Wellhead protection/Food beverage lodging?	☐ Yes	⊠ No	Attached supporting documentation:  Soil observation logs completed for the support of the suppo	
Compliance criteria (select one):			∑ Two previous verifications of require	-
5a. For systems built prior to April 1, 1996, and	☐ Yes ☐ No*		☐ Not applicable (No soil treatment are	•
not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:			⊠ Reviewed design and permit records	S
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.				
5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a		☐ No*	Indicate depths or elevations	
			A. Bottom of distribution media	See Attached Boring Log(s)
food, beverage, or lodging establishment:			B. Periodically saturated soil/bedrock	
Drainfield has a three-foot vertical separation distance from periodically			C. System separation	
saturated soil or bedrock.*			D. Required compliance separation*	
			*May be reduced up to 15 percent if al Ordinance.	lowed by Local
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)	☐ Yes	□ No*		
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.				


**Upgrade requirements:** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021

# <u>Midwest Sewer Testing</u> Subsurface Sewage Treatment System Owner/Property Information

D + CI +: C + 1 20 2024			
Date of Inspection: September 30, 2024	Time: 2:00PM		
Property Address: 2706 Meadow Pass, Afton, MN	Zip: 55001		
Property Owner: Chad & Rebecca Wall	Phone:		
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 2       □Fiberglass       □Rock trench         □Aerobic       □Plastic       □Gravelless trench         □Lift       □Metal       □Chamber trench         □Holding       □Concrete       □Seepage bed         □Other:       □Block       □Mound         □Other       □At-grade	Other  Alternative system Experimental system Cesspool system Other system		
Are the tank maintenance covers accessible? ⊠ Yes ☐ No *If performed through the maintenance holes. Maintenance hole cover the ground surface to facilitate access and proper maintenance of	vers should be made accessible to		
Year house built: 2017 Year septic installed: 2017	Tank size (gals.): 1-1500, 1-1000		
	esidents in home?		
Number of bedrooms? 5 Are all floors drained by § Garbage disposal? Whirlpool bath			
More than one system (laundry, etc.)?	1		
Does this property have any footing drain tiles connected to the s	eptic system?		
Are any buildings on this property such as garages or out-buildings connected to this system?			
Are there any additional systems on this property serving other by	vildin as 9		
Are there any additional systems on this property serving other b	andings?		
	andings?		
Location of septic system on lot? West Side  Location of water well on lot? East Side  Is the	e well a deep well? Y		
Location of septic system on lot? West Side	e well a deep well? Y s: tree roots, sewage back-ups,		
Location of septic system on lot? West Side  Location of water well on lot? East Side  Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system?  If yes, explain:  When was the system last pumped? 9/30/2024  Name of pur	e well a deep well? Y s: tree roots, sewage back-ups,		
Location of septic system on lot? West Side  Location of water well on lot? East Side  Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system?  If yes, explain:  When was the system last pumped? 9/30/2024  Name of pur How often pumped in previous years?  Is system	e well a deep well? Y s: tree roots, sewage back-ups, s:, or have any repairs been made nper: Pinky's Sewer Service m on a monitoring plan?		
Location of septic system on lot? West Side  Location of water well on lot? East Side  Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system?  If yes, explain:  When was the system last pumped? 9/30/2024  Name of pur How often pumped in previous years?  Is system Have you received notices from any government agency concern	e well a deep well? Y s: tree roots, sewage back-ups, s:, or have any repairs been made nper: Pinky's Sewer Service m on a monitoring plan?		
Location of septic system on lot? West Side  Location of water well on lot? East Side  Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system?  If yes, explain:  When was the system last pumped? 9/30/2024  Name of pur How often pumped in previous years?  Is system Is system any government agency concern Is your property located in a shoreland management area? N	e well a deep well? Y s: tree roots, sewage back-ups, s:, or have any repairs been made nper: Pinky's Sewer Service n on a monitoring plan? ing this system?		
Location of septic system on lot? West Side  Location of water well on lot? East Side  Have you ever experienced any problems with the system such as surfacing of sewage onto the ground, septic tank overflowing, etc to the system?  If yes, explain:  When was the system last pumped? 9/30/2024  Name of pur How often pumped in previous years?  Is system Have you received notices from any government agency concern	e well a deep well? Y s: tree roots, sewage back-ups, s:, or have any repairs been made nper: Pinky's Sewer Service n on a monitoring plan? ing this system?		

by Inspect Minnesota and Midwest Soil Testing	
Owner/Occupant:	Date:
•	





#### Site Inspection

Date of the soil observation:	3/28/2017
Inspector:	Chris LeClair
GPS Latitude :	44.90942888 Latitude
GPS Longitude:	-92.8604807 Longitude
Soil Parent Material Select all that apply:	Bedrock
Parent Material:	Bedrock
Landscape Position Please choose one:	Summit
Vegetation:	Prairie
Soil Survey Map Unit(s) with description:	340B-Whalan Sift Loam

#### Soil Horizon Level 1

Depth:	0-16" Inches
Texture:	silt loam
Matrix Color:	10YR3/3
Structure/Shape:	Blocky
Structure/Grade:	Moderate
Structure/Consistence:	Friable
Is this the Restrictive Layer?	<u>No</u>

#### Soil Horizon Level 2

Depth:	16-34" Inches
Texture:	silt loam
Matrix Color:	10YR4/4
Structure/Shape:	Blocky
Structure/Grade:	Moderate
Structure/Consistence:	Friable
Is this the Restrictive	<u>No</u>

#### Soil Horizon Level 3

Depth:	34-72" Inches
Texture:	sandy loam
Matrix Color:	10YR4/4
Structure/Shape:	Blocky
Structure/Grade:	Moderate
Structure/Consistence:	Loose
Is this the Restrictive Layer?	<u>Yes</u>

#### Restricitve Layer Depth

Depth to Restriction: 72 Inches

#### Approvals

Approval	Signature
#1 Site Review Performed	

#### Public Notes

Text:	
File(s):	

#### Internal Notes

Tradewell Soil Testing 18330 Dahlia Street NW Cedar, MN 55011

Date: February 2<sup>nd</sup>, 2017

Name: Divine Custom Homes

Address: Lot 10 Block 1 Cedar Bluffs 2<sup>nd</sup>, Afton, MN

#### SOIL BORING TEST REPORT

Boring #1-A	Boring #2-A	Boring #3-A	Boring #4-A
0"- 12" Topsoil	0"- 12" Topsoil	0"- 14" Topsoil	0"- 15" Topsoil
Loam	Loam	Loam	Loam
10YR 2/2	10YR 2/2	10YR 2/2	10YR 2/2
12"- 36"	12"- 36"	14"- 34"	15"- 32"
Fine Sandy Loam	Fine Sandy Loam	Fine Sandy Loam	Fine Sandy Loam
7.5YR 4/6 4/4	7.5YR 4/6 4/4	7.5YR 3/4 4/4	7.5YR 3/4 4/4
36"- 77"	**Hit Large Rock	34"- 72"	32"- 68"
Sandy Loam & Gravel	-	Loamy Fine Sand &	Sandy Loam & Gravel
7.5YR 3/4		Gravel 5YR 4/4	7.5YR 4/4
		**Hit Large Rock	**Hit Large Rock
No Mottles Found	No Mottles Found	No Mottles Found	No Mottles Found
Dry Hole	Dry Hole	Dry Hole	Dry Hole

5- Bedroom, Type 1 Home (750 GPD Flow)
Perc Rate = 16-30 MPl ...60 Soil Loading Rate
1500 and 1000 gallon septic tanks
1000 gallon pump tank
1250 square feet of drainfield with 6" of rock below the pipe
39 cubic yards or 55 ton of clean rock

Mark Tradewell MPCA #307

Tradewell Soil Testing 18330 Dahlia Street NW Cedar, MN 55011

Date: December 8th, 2016

Name: Divine Custom Homes

Address: Lot 10 Block 2 Cedar Bluffs 2<sup>nd</sup>, Afton, MN

### SOIL BORING TEST REPORT

Boring #1	Boring #2	Boring #3	Boring #4
0"- 8" Topsoil	0"- 12" Topsoil	0"- 10" Topsoil	0"- 8" Topsoil
Loam	Loam	Loam	Loam
10YR 2/2	10YR 2/2	10YR 2/2	10YR 2/2
8"- 20"	12"- 26"	10"- 28"	8"- 34"
Sandy Loam	Fine Sandy Loam	Fine Sandy Loam	Fine Sandy Loam
10YR 3/4	7.5YR 4/4	7.5YR 4/4	7.5YR 3/4 4/4
20"- 32"	26"- 40"	20"- 44"	34"- 52"
Coarse Sandy Loam &	Coarse Loamy Sand &	Coarse Loamy Sand &	Medium Loamy Sand
Gravel 7.5YR 3/4	Gravel 7.5YR 4/4 4/6	Gravel 7.5YR 4/4 4/6	7.5YR 4/6
32"- 58"	40"- 50"	44"- 68"	52"- 77"
Sandy Loam	Coarse Sand	Sandy Loam	Medium Sand
7.5YR 4/4 4/6	10YR 4/4	7.5YR 4/4	10YR 4/4 5/4 5/6
**Hit Large Rock	50"- 62"	**Hit Large Rock	
	Fine Sandy Loam	=	
	7.5YR 4/4		
	**Hit Large Rock		
No Mottles Found	No Mottles Found	No Mottles Found	No Mottles Found
Dry Hole	Dry Hole	Dry Hole	Dry Hole

# **DISCLAIMER**

# Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.