Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 13949n 36355		
Complete in its entirety to constitute a valid main maintenance activities and remain on-site for the	tenance permit This permit	
Date of Maintenance: 8-6-24	Property ID #:	
Property Address: 1121 0'Ryan Tr	r N Stillwater	MN 55082
Property Owner Name:	now	State Zip
Maintenance Performed		
☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	quid Level of Tank:in	st be completed if tanks NOT pumped)in
Maintenance Information Access used to remove septage: Maintena Were all covers securely replaced? Yes No Is the tank designed as a leaky? Ex. Seepage p Tank #1: Yes No Verification Method Use Leaking Out: Yes No Leaking In Yes No	pit, cesspool drywell leaching ed: UISUM Cover Damaged: Yes N	Coate manhole at time of Service pit Gallons Removed: 1500
Tank #2:□Yes □ No Verification Method Used Leaking Out:□Yes ☑No Leaking In: □ Yes ☑N		Gallons Removed: 1660
Tank #3: ☐ Yes ☐ No Verification Method Used Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ N	d: lo Cover Damaged:□Yes□	Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method Used Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No		Gallons Removed:
Pump Tank: ☐ Yes ☐ No Verification Method ULeaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Waste Disposal Method: ☐ Treatment plant ☐ Other remarks or Concerns:	Used: o Cover Damaged:□Yes□I	Gallons Removed:
Maintainer Information	License Number: L4251 ainer that I personally conducted the	

Washington County