## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information Permit #: <u>C4223637579</u>	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 10/15/24	Property ID #:
Property Address: 20661 Quint AV Street Address	e N Sandia MN 55073 City State Zip
Property Owner Name: Craig Christenson	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scum  Tanks must be Pumped if 25% or greater
Maintenance Information	າ
Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced? Yes \( \text{No If No, Explain: } \( \frac{6}{2} \) Cap  Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit	
	Used: Visual Gallons Removed: 1000
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐  Tank #2: ☐ Yes ☐ No Verification Method  Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	Used: Gallons Removed:
Tank #3:□Yes □ No Verification Method	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: ☐ Yes ☐ No Verification Meth	od Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location  Other remarks or Concerns: Purped through pipe, Couldn't inspect	



Maintenance activities must be reported to the Department within 90 days.