

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

V2 59	10411 Grey Cloud Trail S,			ame.	Charles Sins	
Municipality:	ZIP: <u>55</u>	016 Property Ide	ntification Number:			
Maintenance Permi	t No:	Maintainer Name ar	nd License No. Sch	nlomka Service LLC	C/L2989	
Mainte	enance Performed	Tank Meas	surement (must be	completed if tanks	NOT pumped)	
☑ Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in			
		23 41				
Sludge and scum measured		Sludge + Scum _	/ Liquid L	_evel X 100)	
Do tanks need to be pumped? Yes No (if no provide measurements)		= % Sludge & Sci	um Tai	nks must be pumped	I if 25% or greater	
□ 162 □ 140	(if no provide measurements	''				
1. Access used to	remove septage: 🗌 Mainten	ance Hole 🛮 Other (e	enter authorization co	ode)		
		□., N/A				
7. Were all covers	securely replaced? + Yes	HNO W/A				
	securely replaced?		reatment or pump	tank below the ope	erating depth or	
	securely replaced?		reatment or pump tenance hole cove	tank below the ope Prs? <u>No-co</u> uldn't camera	erating depth or conf <u>irm precast via</u>	
			reatment or pump tenance hole cove Leaking In		erating depth or confirm precast via	
	ce of tank leakage from a se amaged, cracked, or structu	Leaking Out	Leaking In	camera	erating depth or confirm precast via	
	ce of tank leakage from a se amaged, cracked, or structu Tank	Leaking Out Yes No Some answers un	Leaking In	Cover Damage Yes No Dugh inspection pipe.	erating depth or confirm precast via	
	ce of tank leakage from a seamaged, cracked, or structu Tank Septic/Holding Tank #1	Leaking Out Yes No Some answers un	Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dugh inspection pipe.	erating depth or confirm precast via	
	Tank Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No known. Pumped thro	Cover Damage Ves No Dugh inspection pipe.	erating depth or confirm precast via	
3. Is there evidence of descriptions of descriptions of descriptions of the evidence of the ev	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No	Leaking In Yes No known. Pumped thro Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No	erating depth or confirm precast via	
Is there evidence of devidence of devidence of devidence. 4. How many galler	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank Ons of septage were remove	Leaking Out Ves No Yes No	Leaking In Yes No known. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No		
4. How many galle Tank #1 125	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank Ons of septage were remove	Leaking Out Yes No	Leaking In Yes No Iknown. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Yes No	gal	
 4. How many galle Tank #1 125 5. Other informat 	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank Ons of septage were remove	Leaking Out Yes No Yes	Leaking In Yes No Iknown. Pumped thro Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Yes No	gal	

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033 License# 2989 P: 651-459-3718