### **Inspect Minnesota & Midwest Soil Testing**

P.O. Box 383 Hugo, MN 55038

Brian Humpal

651-492-7550/Brian@midwestsoiltesting.com

MPCA Licensed Advanced Inspector

### SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

**Inspection Address:** 7194 115th St N, Grant, MN 55082

### **REPORT SUMMARY**

I have performed an "MPCA Compliance Inspection" on this system and have reviewed a previous compliance inspection from 2009 on file at Washington County. This system consists of two pre-cast septic tanks, a pre-cast lift tank, and a mound.

Predicated on my inspection of the system and my review of the records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Brian Humpal



### **Compliance Inspection Form**

### Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspection results based on Minnesota requirements and attached forms – additional local re	quirements may also apply.
Submit completed form to Local Unit of Government within 15 days	nent (LUG) and system owner
System Status	
System status on date (mm/dd/yyyy): _11/	14/2016
Compliant – Certificate of Comp (Valid for 3 years from report date, unless frame outlined in Local Ordinance.)	<del>_</del> •
<ul> <li>☐ Other Compliance Conditions (Compliant</li> <li>☐ Tank Integrity (Compliance Component</li> <li>☐ Other Compliance Conditions (Compliant</li> <li>☐ Soil Separation (Compliance Component</li> </ul>	omponent #1) – Imminent threat to public health and safety nce Component #3) – Imminent threat to public health and safety #2) – Failing to protect groundwater nce Component #3) – Failing to protect groundwater
Property Information	Parcel ID# or Sec/Twp/Range:
	· · · · · · · · · · · · · · · · · · ·
Property address: 7194 115th St N. Grant MN 55	082 Reason for inspection: Property Sale
Property owner: Thomas Wintz	
Property address: 7194 115th St N, Grant, MN 55  Property owner: Thomas Wintz  or	Owner's phone:    Property Sale
Property owner: Thomas Wintz or	Owner's phone:
Property owner: Thomas Wintz or	Owner's phone:
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County  Brief system description: Two pre-cast septic tan	Owner's phone:  ty) Representative phone: 651-287-4040
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County	ty)
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County  Brief system description: Two pre-cast septic tan	ty)
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County Brief system description: Two pre-cast septic tan Comments or recommendations:  Certification I hereby certify that all the necessary information ha	Owner's phone:  ty)  Representative phone: 651-287-4040  Regulatory authority phone: 651-430-4052  k, a pre-cast lift tank, and a mound.  s been gathered to determine the compliance status of this system. No en nor can be made due to unknown conditions during system construction,
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real: Local regulatory authority: Washington County Brief system description: Two pre-cast septic tan Comments or recommendations:  Certification I hereby certify that all the necessary information had determination of future system performance has been	Owner's phone:  ty)  Representative phone: 651-287-4040  Regulatory authority phone: 651-430-4052  k, a pre-cast lift tank, and a mound.  s been gathered to determine the compliance status of this system. No en nor can be made due to unknown conditions during system construction,
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County Brief system description: Two pre-cast septic tan Comments or recommendations:  Certification I hereby certify that all the necessary information had determination of future system performance has been possible abuse of the system, inadequate maintenance.	Owner's phone:  ty)  Representative phone: 651-287-4040  Regulatory authority phone: 651-430-4052  k, a pre-cast lift tank, and a mound.  s been gathered to determine the compliance status of this system. No en nor can be made due to unknown conditions during system construction, ince, or future water usage.  Certification number: L5342
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County Brief system description: Two pre-cast septic tan Comments or recommendations:  Certification I hereby certify that all the necessary information had determination of future system performance has been possible abuse of the system, inadequate maintenant Inspector name: Brian Humpal	Owner's phone:  ty)  Representative phone:  Regulatory authority phone:  651-287-4040  Regulatory authority phone:  651-430-4052  k, a pre-cast lift tank, and a mound.  s been gathered to determine the compliance status of this system. No en nor can be made due to unknown conditions during system construction, nace, or future water usage.  Certification number:  L5342  Testing  License number:  L2896
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County Brief system description: Two pre-cast septic tan Comments or recommendations:  Certification I hereby certify that all the necessary information had determination of future system performance has been possible abuse of the system, inadequate maintenant Inspector name: Brian Humpal Business name: Inspect Minnesota, Midwest Soil	Owner's phone:  ty)  Representative phone: 651-287-4040  Regulatory authority phone: 651-430-4052  k, a pre-cast lift tank, and a mound.  s been gathered to determine the compliance status of this system. No en nor can be made due to unknown conditions during system construction, ince, or future water usage.  Certification number: L5342  Testing  License number: 651-492-7550
Property owner: Thomas Wintz  or  Owner's representative: Mark Ashby (Edina Real Local regulatory authority: Washington County Brief system description: Two pre-cast septic tan Comments or recommendations:  Certification I hereby certify that all the necessary information had determination of future system performance has bee possible abuse of the system, inadequate maintenant Inspector name: Brian Humpal Business name: Inspect Minnesota, Midwest Soil Inspector signature: Signar Humpal	Owner's phone:  ty)  Representative phone: 651-287-4040  Regulatory authority phone: 651-430-4052  k, a pre-cast lift tank, and a mound.  s been gathered to determine the compliance status of this system. No en nor can be made due to unknown conditions during system construction, noce, or future water usage.  Certification number: L5342  Testing  License number: L2896  Phone number: 651-492-7550

1.	Impact on Public Health — Compliance component #1 of 5			
	Sy gro	estem discharge sewage to the bund surface.  Testem discharge sewage to drain tile surface waters.  Testem cause sewage backup into velling or establishment.  The pure answer above indicates of Imminent Threat to Public Heal of the above found.	-	Verification method(s):  ☐ Searched for surface outlet ☐ Searched for seeping in yard/backup in home ☐ Excessive ponding in soil system/D-boxes ☐ Homeowner testimony (See Comments/Explanation) ☐ "Black soil" above soil dispersal system ☐ System requires "emergency" pumping ☐ Performed dye test ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)
2.	Ta	ank Integrity — Compliance com	nponent #2 of 5	
3.	Sy ce: Se con Se de If y	estem consists of a seepage pit, sspool, drywell, or leaching pit.  Repage pits meeting 7080.2550 may be impliant if allowed in local ordinance.  Rewage tank(s) leak below their signed operating depth.  Reyes, which sewage tank(s) leaks:  Rey "yes" answer above indicates and its Failing to Protect Green is Failing to Protect Green is were allowed in the tank - but their compliance conditions.	oundwater. paffles and tank walls	
	<ul> <li>a. Maintenance hole covers are damaged, cracked, unsecured, or appear to structurally unsound. ☐ Yes* ☒ No ☐ Unknown</li> <li>b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. ☐ Yes* ☒ No ☐ Unknown *System is an imminent threat to public health and safety</li> <li>Explain:</li> <li>c. System is non-protective of ground water for other conditions as determined by inspector ☐ Yes* ☒ No *System is failing to protect groundwater</li> <li>Explain:</li> </ul>			

Property address: 7194 115th St N, Grant, MN 55082

Inspector initials/Date: \_\_11/14/2016

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 3 of 979Y 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

	<b>-</b>				
	Date of installation: 2004	Unknown	V	erification method(s):	
	Shoreland/Wellhead protection/Food Beverage Lodging?  Compliance criteria:	⊠ Yes □ N	0	Soil observation does not expire. Previous soil observations by two independent parties are su unless site conditions have been altered or local requirements differ.  Conducted soil observation(s) (Attach boring Two previous verifications (Attach boring logs Not applicable (Holding tank(s), no drainfield) Unable to verify (See Comments/Explanation) Other (See Comments/Explanation)	
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:  Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.	☐ Yes ☐ N			
	Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	⊠ Yes □ N		comments/Explanation: eviewed previous compliand	ce inspection from 2009.
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*				
	"Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)	☐ Yes ☐ N		Bottom of distribution media	See Attached Boring Log(s)
	Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.		С	Periodically saturated soil/bed  System separation	
5.	Any "no" answer above indicates the Failing to Protect Groundwater.  Operating Permit and Nitrogen B.	<u> </u>	*!	Required compliance separate May be reduced up to 15 per Drdinance.	
_	Is the system operated under an Operating Peri			If "yes", A below is req	
	Is the system required to employ a Nitrogen BM			If "yes", B below is req	
	BMP=Best Management Practice(s) specified in the system design				
	If the answer to both questions is "no",	-	_	need to be completed.	
	Compliance criteria				
	a. Operating Permit number:		-	☐ Yes ☐ No	
	Have the Operating Permit requirements by	peen met?			
	b. Is the required nitrogen BMP in place and	nronerly function	nina?	☐ Yes ☐ No	

Inspector initials/Date: 11/14/2016

Property address: 7194 115th St N, Grant, MN 55082

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 4 off9TY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 3 of 3


Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

**Upgrade Requirements** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas,

### **Inspect Minnesota & Midwest Soil Testing**

### Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

Date of Inspection: November 14, 2016	Time: 2:30 PM				
Bute of hispection. November 11, 2010					
Property Address: 7194 115th St N, Grant, MN	Zip: 55082				
Property Owner: Thomas Wintz	Phone:				
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 2       Fiberglass       Rock trench         Aerobic       Plastic       Gravelless trench         Lift       Metal       Chamber trench         Holding       Concrete       Seepage bed         Other:       Block       Mound         Other       At-grade	Other  Alternative system  Experimental system  Cesspool system  Other system				
Are the tank maintenance covers accessible?   Yes   No *If no, proper maintenance must be performed through the maintenance holes. Maintenance hole covers should be made accessible to the ground surface to facilitate access and proper maintenance of the system.					
	Tank size (gals.): 1-1500, 1-1000				
	esidents in home?				
Number of bedrooms? 4 Are all floors drained by g					
Garbage disposal? Whirlpool bath?	)				
More than one system (laundry, etc.)?	1: 4 9				
Does this property have any footing drain tiles connected to the se	eptic system?				
Are any buildings on this property such as garages or out-building	gs connected to this system?				
Are there any additional systems on this property serving other bu	ildings?				
Location of septic system on lot? North Side					
	e well a deep well? Y				
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups, surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system?  If yes, explain:					
When was the system last pumped? Name of pum	1				
How often pumped in previous years?  Is system on a monitoring plan?					
Have you received notices from any government agency concerning this system?					
Is your property located in a shoreland management area? N					
Do you have any additional information that should be given to the new owner?					
I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.					
Owner/Occupant:	Date:				



### **Log Of Soil Borings**

Location of Project: 7194 115th St N, Grant, MN 55082						
Borings Made By: Inspect Minnesota		Date:		11/14/16		
Auger Used: Hand/Bucket		Hand/Bucket	Classification System:		USDA	
	Boring Number:	1		Boring Number:		
cievation of original		top of mound on inal contour	Surface Elevation Boring			
Depth In Inches	Depth In Soils Encountered		Depth In Inches	Soils En	Soils Encountered	
0-10 10-23 23-30	10YR 5/4 S 10YR 5/4 San 7.5YR 5/8, 5YR 5 And Iron Nodules	2 Sandy Loam Fandy Clay Loam dy Clay Loam With 5/8, &10YR 6/2 Redox & Decomposing Rocks				
23" [	Depth To End Of B	oring Or Redox		Depth To End Of Bo	oring Or Redox	
+37" Elevation Of Boring Below Top Of Mound			Elevation Of Boring	Relative To System		
-26" Depth To Bottom Of Distribution Media				f Distribution Media		
=34"	Of Separation			Of Separation		
	End Of Boring At:	30"		End Of Boring At:		
	Redox Present At:	23"		Redox Present At:		
Standing Water Present At: None		Standing	Water Present At:			

Bottom Of Distribution Medium A	at: 26 Inches
_	

### **DISCLAIMER**

### Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

# Sulbsurface Sewage Treatment Systems

Non-transferable



License # L2896

Maintainer License Expires:

Adv Inspector License Expires:

Oct 28, 2015 Dec 22, 2016 Dec 22, 2016 Dec 22, 2016 Dec 22, 2016

Adv Designer License Expires:

Date of Issuance:

Installer License Expires:

### Certification

Inspect Minnesota, Midwest Soil Testing

Expires

10/15/2017 10/15/2017

Advanced Designer (Certified) Advanced Inspector (Certified)

Maintainer (Certified)

Certification Type

**Designated Certified** 

Individual (DCI) Brian L. Humpal Brian L. Humpal Brian L. Humpal Brian L. Humpal Brian L. Humpal

10/15/2017

10/15/2017

10/15/2017

Service Provider (Certified)

Installer (Certified)

Designer (Certified) Inspector (Certified)

Christopher R. Uebe Christopher R. Uebe

03/04/2018

03/04/2018

Steven Giddings Manager Environmental Business Assistance Section



## Minnesota Pollution Control Agency

520 Lafayette Road North St. Paul, Minnesota 55155-4194