Inspect Minnesota & Midwest Soil Testing

P.O. Box 383 Hugo, MN 55038

Brian Humpal

651-492-7550/Brian@midwestsoiltesting.com

MPCA Licensed Advanced Inspector

SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

Date: April 20, 2017 **Time:** 9:45 AM **Owner:** Mike Fox

Inspection Address: 11033 66th St N, Grant, MN 55082

REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records on file at Washington County. This system consists of two pre-cast septic tanks and a gravelless trench drainfield.

Although not a compliance criteria, it should be noted that the dropbox caps are damage or missing and should be replaced.

Predicated on my inspection of the system and my review of the original design/permit records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Inspect Minnesota and Midwest Soil Testing have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Inspect Minnesota and Midwest Soil Testing disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Brian Humpal



Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

requirements and attached f	sults based on Minnesota Pollution Control Agorms – additional local requirements may also	apply.	For local tracking purpos	es:
Submit completed form to within 15 days	Decal Unit of Government (LUG) and sys	stem owner		
System Status				
System status on da	ite (mm/dd/yyyy):4/20/2017	_		
(Valid for 3 years	Certificate of Compliance from report date, unless shorter time Local Ordinance.)		pliant – Notice of No ade Requirements on pag	•
☐ Impact on Publ ☐ Other Compliar ☐ Tank Integrity (☐ Other Compliar ☐ Soil Separation	compliance (check all applicable) ic Health (Compliance Component #1) – Implied Compliance Component #3) Compliance Component #2) – Failing to profice Conditions (Compliance Component #3) (Compliance Component #4) – Failing to profit/monitoring plan requirements (Compliance)	 Imminent thre tect groundwate Failing to prot rotect groundwa 	at to public health and sa r ect groundwater er	fety
	The state of the s		,	
Property Information	ND Dorool ID# or	Coo/Turn/Dong		
	66 th St N, Grant, MN 55082	Sec/Twp/Range		Polo
		Reason for inspection: Property Sale Owner's phone: 612-282-7388		
Property owner: Mike For	X	Owner's p	1011e. <u>012-202-7300</u>	
Owner's representative:		Penresent	ative phone:	
Local regulatory authority:	Washington County	Representative phone: Regulatory authority phone: 651-430-4052		
Brief system description:	Two pre-cast septic tanks and a gravelless			
Comments or recommenda	·	tronon aranmola	•	
Although not a compliance	criteria, it should be noted that the dropbox o	aps are damage	or missing and should b	e replaced.
Certification				
determination of future syst	necessary information has been gathered to deem performance has been nor can be made m, inadequate maintenance, or future water	due to unknown		
Inspector name: Brian Hi	umpal	Certification	n number: L5342	
	Minnesota, Midwest Soil Testing	Licens	e number: <u>L2896</u>	
Inspector signature:	Brian Humpal	Phor	e number: 651-492-755	50
Necessary or Locall	y Required Attachments			
Necessary or Locall ☐ Soil boring logs	y Required Attachments ☑ System/As-built drawing	☐ Forms per lo	cal ordinance	

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 1 of 3

Property address: 11033 66th St N, Grant, MN 55082

Inspector initials/Date: 4/20/2017

1.	In	mpact on Public Health — Compliance component #1 of 5				
	Co	ompliance criteria:		Verification method(s):		
		stem discharge sewage to the ound surface.	☐ Yes ☐ No	 ✓ Searched for surface outlet ✓ Searched for seeping in yard/backup in home 		
	-	stem discharge sewage to drain tile surface waters.	☐ Yes ⊠ No	 ☑ Excessive ponding in soil system/D-boxes ☐ Homeowner testimony (See Comments/Explanation) ☐ "Black soil" above soil dispersal system 		
		stem cause sewage backup into velling or establishment.	☐ Yes ⊠ No	System requires "emergency" pumping Performed dye test		
		ny "yes" answer above indicates n Imminent Threat to Public Heal		☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
		nmments/Explanation: chough not a compliance criteria, it sho	ould be noted that the dropbo	ox caps are damage or missing and should be replaced.		
		μ				
2.	Ta	ank Integrity — Compliance con	nponent #2 of 5			
	Co	ompliance criteria:		Verification method(s):		
		stem consists of a seepage pit, sspool, drywell, or leaching pit.	☐ Yes ⊠ No	☑ Probed tank(s) bottom☑ Examined construction records		
	Se	epage pits meeting 7080.2550 may be mpliant if allowed in local ordinance.		Examined Constitution records Examined Tank Integrity Form (Attach) Observed liquid level below operating depth		
		ewage tank(s) leak below their signed operating depth.	☐ Yes No	☐ Examined empty (pumped) tanks(s)		
	If y	ves, which sewage tank(s) leaks:		☐ Probed outside tank(s) for "black soil"☐ Unable to verify (See Comments/Explanation)		
		ny "yes" answer above indica vstem is Failing to Protect Gr		☐ Officially (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation)		
	Comments/Explanation: Lowered underwater camera into tanks - baffles and tank walls OK.					
	LU	wered underwater camera into tanks -	ballies and talk walls OK.			
2	Ο.	thar Campliance Conditions				
3.		ther Compliance Conditions	· · · · · · · · · · · · · · · · · · ·			
	a. b.	Maintenance hole covers are damaged Other issues (electrical hazards, etc.) to i		·		
	٠.	*System is an imminent threat to pu		postpasiio nodali or carety. 🗀 ree 🔟 no 🗀 oriinioini		
		Explain:				
	C.	System is non-protective of ground wa *System is failing to protect ground		termined by inspector ☐ Yes* ☒ No		
		Explain:				

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Property address: 11033 66th St N, Grant, MN 55082

	Date of installation: 2000	Unknown	V	erification method(s):		
	Shoreland/Wellhead protection/Food Beverage Lodging?	ction/Food Beverage ⊠ Yes □ No		Soil observation does not expire. Previous soil		
	Compliance criteria:		ш	bservations by two independent parties are sufficient nless site conditions have been altered or local		
	For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ☐ No	requirements differ. ☐ Conducted soil observation(s) (Attach ☐ Two previous verifications (Attach bot ☐ Not applicable (Holding tank(s), no drail		ch boring logs)	
	Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.			Unable to verify (See Comments/Explanation)		
	Non-performance systems built April 1,	⊠ Yes □ No	С	Comments/Explanation:		
	1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:		R	eviewed design and permit record	ds.	
	Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*					
Ξ	"Experimental", "Other", or "Performance"	☐ Yes ☐ No	- In	ndicate depths of elevations		
	systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required)		<u>A.</u>	Bottom of distribution media	See Attached Boring Log(s)	
	Drainfield meets the designed vertical		В.	Periodically saturated soil/bedrock		
	separation distance from periodically saturated soil or bedrock.		<u>C</u> .	System separation		
			D.	Required compliance separation*		
	Any "no" answer above indicates the system is Failing to Protect Groundwater.			May be reduced up to 15 percent i Ordinance.	if allowed by Local	
			_			
5.	Operating Permit and Nitrogen B	MP* – Compliand	e com	ponent #5 of 5 🛮 🖂 Not app	licable	
	Is the system operated under an Operating Per	mit?	⊠ No	If "yes", A below is required		
	Is the system required to employ a Nitrogen BM	IP? ☐ Yes	⊠ No	If "yes", B below is required		
	BMP=Best Management Practice(s) specifi	ied in the system de	sign			
	If the answer to both questions is "no",	this section doe	s not r	need to be completed.		
	Compliance criteria					
	a Operating Permit number:					
	Have the Operating Permit requirements I			☐ Yes ☐ No		
	b. Is the required nitrogen BMP in place and			☐ Yes ☐ No		

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.


www.pca.state.mn.us • 651-296-6300 800-657-3864 wq-wwists4-31 • 1/24/12 Page 3 of 3

Inspector initials/Date: 4/20/2017

Inspect Minnesota & Midwest Soil Testing Subsurface Sewage Treatment System Owner/Property Information This information will be used for the purpose of conducting an MPCA Compliance Inspection.

D . CI				
Date of Inspection: April 20, 2017	Time: 9:45 AM			
Property Address: 11033 66 th St N, Grant. MN	Zip: 55082			
Property Owner: Mike Fox	Phone: 612-282-7388			
Tank(s) Tank(s)Material Soil Treatment System Septic 2 Fiberglass Rock trench Aerobic Plastic Gravelless trench Lift Metal Chamber trench Holding Concrete Seepage bed Other: Block Mound Other At-grade	Other Alternative system Experimental system Cesspool system Other system			
Are the tank maintenance covers accessible? ☐ Yes ☒ No *If	no, proper maintenance must be			
performed through the maintenance holes. Maintenance hole cov				
the ground surface to facilitate access and proper maintenance of	the system.			
1	Tank size (gals.): 1-1500 1-1000			
	esidents in home?			
Number of bedrooms? Are all floors drained by g	ž – – – – – – – – – – – – – – – – – – –			
Garbage disposal? Whirlpool bath)			
More than one system (laundry, etc.)?				
Does this property have any footing drain tiles connected to the se	eptic system?			
Are any buildings on this property such as garages or out-buildings connected to this system? Unknown Are there any additional systems on this property serving other buildings? Unknown				
Location of conting system on lot? South Side				
Location of septic system on lot? South Side Location of water well on lot? North East Is the	e well a deep well? Y			
Have you ever experienced any problems with the system such as	1			
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system? If yes, explain:				
When was the system last pumped? 2013 Name of pun	nper:			
How often pumped in previous years?				
Have you received notices from any government agency concerning this system?				
Is your property located in a shoreland management area? N				
Do you have any additional information that should be given to the new owner?				
I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in				

this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing.



Log Of Soil Borings

Location of Project: 11033 66th St N, Grant, MN 55082					
Borings Made By: Inspect Minnesota				Date:	4/20/17
Auger Used: Hand/Bucket			Classi	ification System:	USDA
	Boring Number:	1		Boring Number:	
Surface Elevation of Boring Same ground surface as last drainfield trench		Surface Elevation Boring	of		
Depth In Inches	Soils E	ncountered	Depth In Inches	Soils Er	ncountered
0-14 14-20 20-42 42-57 57-65 65-75	10YR 3/3 Medium 0 ≈10% Rc 10YR 4/4 10YR 4/4 10YR 4/3 Very 10YR 4/3 Very	2 Sandy Loam Coarse Sand With Gravel Ock Fragments /4 Fine Sand Fine Sand With y Fine Sand Layers / Fine Sand (Moist) Fine Sand (Saturated)			
75" [Depth To End Of B	oring Or Redox		Depth To End Of Bo	oring Or Redox
Same I	Elevation Of Boring	g Relative To System		Elevation Of Boring	Relative To System
-33" Depth To Bottom Of Distribution Media ≥42" Of Separation			Depth To Bottom C Of Separation	f Distribution Media	
	End Of Boring At:	75"		End Of Boring At:	
	Redox Present At:	None		Redox Present At:	
Standing \	Water Present At:	None	Standing	Water Present At:	

Bottom Of Distribution Medium At:	33 Inches

DISCLAIMER

Brian L. Humpal, Inc. dba. Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1st through April 1st) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.

Subsurface Sewage Treatment Systems

Non-transferable

Business License

Inspect Minnesota, Midwest Soil Testing

License # L2896

License Expires: 12/22/2017

Issued: 11/29/2016

Specialty Area(s):

Installer
Maintainer
Service Provider
Advanced Designer
Advanced Inspector

Designated Certified Individual(s):

Cert #

Name

Certification Expires:

C5342

Brian L Humpal

10/15/2017

Installer, Maintainer, Serv Prov, Adv Designer, Adv Inspector

C9852

Christopher R Uebe

3/4/2018

Designer, Inspector



St. Paul. Minnesota 55155-4194

Steven Giddings, Manager

Prevention and Solid Waste Management Section