

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	@ 22/17 Reason				
Property Address: 91	141 315TST.1	<u>V. </u>	Property Owner's Name: TED STERBENK		
Municipality: / AKE	ELMO ZIP: 550	142 Property Ider	ntification Number:	¥	
	X0738z6859				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
\square Yes \square No (if no provide measurements)					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes \sum No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
evidence of damaged, cracked, or structurally unsound maintenance noie covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🗹 No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes 🗹 No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 /600	of septage were removed gal Tank #2 /607 : List any troubleshooting	_ gal Pretreatmen	t tankg nducted, tank safe	al Pump Tank ety concerns, or oth	gal ner concerns.
6. Location of septage	e disposal:				

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162