

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| Date of Maintenance: | 11/27/17 Reason f | or Maintenance: _ | Routine) | | | | | | | | |
|--|------------------------|--|------------|--------------|--|--|--|--|--|--|--|
| Property Address: 10650 Differgare S. Property Owner's Name: Jerry 1055 | | | | | | | | | | | |
| Municipality: Denmark ZIP: 55033 Property Identification Number: | | | | | | | | | | | |
| Maintenance Permit No: 04494e10220 Maintainer Name and License No. | | | | | | | | | | | |
| and the second of the composition of the compositions of the composition of | | 980 (1990) (1990 | | | | | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | | | | | | | |
| Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements) | | Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater | | | | | | | | | |
| | | | | | | 1. Access used to remove septage: Maintenance Hole Other (enter authorization code) | | | | | |
| | | | | | | 2. Were all covers securely replaced? Yes No | | | | | |
| | | | | | | 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | | | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | | | | | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | | | | | | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | | | | | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | | | | | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | | | | | | |
| 4. How many gallons of septage were removed? | | | | | | | | | | | |
| Tank #1 1260 gal Tank #2 gal Pretreatment tank gal Pump Tank gal | | | | | | | | | | | |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | | | | | | | | | | |
| FROZE - COVER | | | | | | | | | | | |
| 6. Location of septage disposal: STPAUL - WTP | | | | | | | | | | | |

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162