

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 8/1/17 Reason for Maintenance: ROUTINE						
Property Address: 2564 ITASCA AVE. S. Property Owner's Name: CHARLES FARNHAM						
Municipality: STMARYS Pr. ZIP:55643 Property Identification Number:						
Maintenance Permit No: 290552736 / Maintainer Name and License No. Meyer Sewer Service, Inc./L915						
		STOCK ST	restudente diferim acusta se se se se se su dice.		-	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped			Liquid Level of Tank in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)			announced statements at 1 countries			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	to the second second					
3	Tank	Leaking Out	Leaking In	Cover Damage	g a	
*	Tank Septic/Holding Tank #1	Leaking Out Yes Kho	Leaking In	Cover Damage Yes Ano	a.	
,			1 -		а	
	Septic/Holding Tank #1	☐ Yes Who	☐ Yes ☐	☐ Yes I No	а	
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes KNo	☐ Yes	☐ Yes ☑No	a.	
the contract of the contract o	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes Mo☐ Yes No☐ Yes ☐ Yes ☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐	☐ Yes ☐No ☐ Yes ☐No ☐ Yes ☐No ☐ Yes ☐No	☐ Yes ANO ☐ Yes ANO ☐ Yes ☐ No ☐ Yes ☐ No	nal .	
Tank #1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes Mo ☐ Yes Mo ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Ro	☐ Yes ☐ You ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank _ g	☐ Yes ☑No ☐ Yes ☐No		
Tank #1 / GO:	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No gal Pretreatmen , minor repairs co	☐ Yes ☐ You ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank _ g	☐ Yes ☑No ☐ Yes ☐No		
Tank #1 / GO:	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes Mo ☐ Yes Mo ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Ro	☐ Yes ☐ You ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank _ g	☐ Yes ☑No ☐ Yes ☐No		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162