

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

| Inspection results based on Minnesota Pollution Control Agency requirements and attached forms – additional local requirements may | |
|---|--|
| Submit completed form to Local Unit of Government (LUG) and within 15 days | |
| System Status | |
| System status on date (mm/dd/yyyy): 7/25/2019 | |
| Compliant – Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.) | Noncompliant – Notice of Noncompliance (See Upgrade Requirements on page 3.) |
| Reason(s) for noncompliance (check all applicable) | |
| ☐ Impact on Public Health (Compliance Component #1) – Imminer | nt threat to public health and safety |
| ☐ Other Compliance Conditions (Compliance Component | #3) – Imminent threat to public health and safety |
| ☐ Tank Integrity (Compliance Component #2) – Failing to | |
| Other Compliance Conditions (Compliance Component | |
| Soil Separation (Compliance Component #4) – Failing | |
| Operating permit/monitoring plan requirements (Compli | апсе Сотропені #5) — Noncompilani |
| Property address: 4581 McDonald Dr Overlook Stillwater, MN 550 | |
| Property owner: Sally P Chrystal | Owner's phone: _651-472-4016 |
| Owner's representative: | Representative phone: |
| Local regulatory authority: Washington County | Regulatory authority phone: _651-430-6655 |
| Brief system description: Two 1000 gallon septic tanks and a 10 | 00 gallon pump tank lifting to a mound drainfield. |
| Comments or recommendations: | |
| Contision tion | |
| Certification I hereby certify that all the necessary information has been gathered | d to determine the compliance status of this system. No |
| determination of future system performance has been nor can be m possible abuse of the system, inadequate maintenance, or future was | ade due to unknown conditions during system construction, |
| Inspector name: Tom Trooien | Certification number: 323 |
| Business name: All State Septic Services LLC | License number: 1568 |
| Inspector signature: Tom I reoson | Phone number: 612-594-4496 |
| Necessary or Locally Required Attachments | |
| | |
| ☑ Soil boring logs☑ System/As-built drawing☑ Other information (list): | ☐ Forms per local ordinance |
| | |
| (5/00/502 | |
| www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • 7 | TY 651-282-5332 or 800-657-3864 • Available in alternative forma |

| Compliance criteria: | | Verification method(s): |
|---|--|--|
| System discharges sewage to the ground surface. | ☐ Yes ☒ No | Searched for surface outlet Searched for seeping in yard/backup in home |
| System discharges sewage to drain tile or surface waters. | ☐ Yes ☒ No | ☐ Excessive ponding in soil system/D-boxes ☐ Homeowner testimony (See Comments/Explanation) |
| System causes sewage backup into dwelling or establishment. | ☐ Yes ☒ No | ☐ "Black soil" above soil dispersal system ☐ System requires "emergency" pumping |
| Any "yes" answer above indicates the system is an imminent threat to public health and safety. | | ☐ Performed dye test ☐ Unable to verify (See Comments/Explanation) ☐ Other methods not listed (See Comments/Explanation) |
| Tank Integrity Causilian | 1.1/2 | |
| Tank Integrity – Complianc Compliance criteria: | e component #2 of 5 | Verification method(s): |
| System consists of a seepage pit, cesspool, drywell, or leaching pit. | ☐ Yes ☒ No | ☑ Probed tank(s) bottom |
| Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance. | P . | ☑ Examined construction records ☐ Examined Tank Integrity Form (Attach) |
| Sewage tank(s) leak below their designed operating depth. | ☐ Yes ☒ No | ☐ Observed liquid level below operating depth ☐ Examined empty (pumped) tanks(s) |
| If yes, which sewage tank(s) leaks: | | ☐ Proped outside tank(s) for "black soil" ☐ Unable to verify (See Comments/Explanation) |
| A 66 11 1 | dicates the | ☐ Other methods not listed (See Comments/Explanation) |
| system is failing to protect | | and methods not noted (occ comments/Explanation) |
| Any "yes" answer above inc system is failing to protect of Comments/Explanation: Tanks were pumped in July, 2019 Other Compliance Condition | groundwater. | |
| system is failing to protect (Comments/Explanation: Tanks were pumped in July, 2019 Other Compliance Condition | groundwater. Ons – Compliance com | |
| System is failing to protect of Comments/Explanation: Tanks were pumped in July, 2019 Other Compliance Condition Maintenance hole covers are dar | ons - Compliance com maged, cracked, unsecure b.) to immediately and adv | ponent #3 of 5 d, or appear to be structurally unsound. ☐ Yes* ☒ No ☐ Unkrersely impact public health or safety. ☐ Yes* ☒ No ☐ Unkr |

Property address: 4581 McDonald Dr Overlook Stillwater, MN 55082

wq-wwists4-31b • 6/4/14 Page 2 of 3

RECEIVED כענו ט ו TAM HELM 100' - Lower