

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

| Instructions: Inspection results based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply. Submit completed form to Local Unit of Government (LUG) and system owner | For local tracking purposes: | | | | | | |
|---|----------------------------------|--|--|--|--|--|--|
| within 15 days | | | | | | | |
| | | | | | | | |
| System Status | | | | | | | |
| System status on date (mm/dd/yyyy):7/22/2019 | | | | | | | |
| ☐ Compliant – Certificate of Compliance (Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.) ☐ Compliant – Certificate of Compliance (See Upgrade Requirements on page 3) | | | | | | | |
| Reason(s) for noncompliance (check all applicable) Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety Tank Integrity (Compliance Component #2) – Failing to protect groundwater Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater Soil Separation (Compliance Component #4) – Failing to protect groundwater | | | | | | | |
| Operating permit/monitoring plan requirements (Compliance Component | +3) — Попсотрнан | | | | | | |
| | | | | | | | |
| Property Information Parcel ID# or Sec/Twp/Range | ge: 1203221220002 | | | | | | |
| • • | or inspection: Property Transfer | | | | | | |
| Property owner: Douglas Haseltine Owner's or | • | | | | | | |
| Owner's representative: Represen | ntative phone: | | | | | | |
| Local regulatory authority: Washington County Regulato | ry authority phone: | | | | | | |
| Brief system description: 1-1250-gallon Septic Tank and two gravity flow trenches | | | | | | | |
| Comments or recommendations: | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Certification | | | | | | | |
| I hereby certify that all the necessary information has been gathered to determine the determination of future system performance has been nor can be made due to unknown possible abuse of the system, inadequate maintenance, or future water usage. | | | | | | | |
| Inspector name: Jeffrey Fertig Certificat | ion number: 2942 | | | | | | |
| | nse number: 2299 | | | | | | |
| | one number: 651-253-2969 | | | | | | |
| | | | | | | | |
| Necessary or Locally Required Attachments | | | | | | | |
| | local ordinance | | | | | | |
| Other information (list): | | | | | | | |

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wq-wwists4-31 • 1/24/12 Page 2 of 3

Explain:

less than 24 inches of separation

| Prop | roperty address: _22900 Jenson Ave N, Forest Lake, MN 55025 | | | | Inspector initials/Date: July | 22, 2019 | | |
|--|---|------------|--------|---|---|-----------|--|----------------|
| 4. | Soil Separation — Compliance compor | nent #4 o | of 5 | | | | | |
| | Date of installation: Prior to 4/1/96 | ⊠ Unkr | nown | Ver | ification method(s): | | | |
| | Shoreland/Wellhead protection/Food Beverage Lodging? | ☐ Yes | ⊠ No | | Soil observation does not expire. Previous soil observations by two independent parties are sufficient, | | | |
| | Compliance criteria: | | | unless site conditions have been altered or local | | | | |
| | For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: | ☐ Yes | ⊠ No | | | | Conducted soil observation(s) (Attach boring logs) Two previous verifications (Attach boring logs) | h boring logs) |
| | Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock. | | | | ☐ Unable to verify (See Comments/Explanation) ☐ Other (See Comments/Explanation) | | | |
| | Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: | Yes | i □ No | Cor | Comments/Explanation: | | | |
| | Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* | | | = | | | | |
| | "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080. 2350 or 7080.2400 (Advanced Inspector License required) Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock. | ☐ Yes ☐ No | | Indicate depths of elevations | | | | |
| | | | | _A. | Bottom of distribution media | 42 Inches | | |
| | | | | B. | Periodically saturated soil/bedrock | 24 Inches | | |
| | | | | C. | System separation | -0- | | |
| | | | | D. | Required compliance separation* | 24 | | |
| | Any "no" answer above indicates the system is Failing to Protect Groundwater. | | | | *May be reduced up to 15 percent if allowed by Local Ordinance. | | | |
| 5. Operating Permit and Nitrogen BMP* – Compliance component #5 of 5 Not applicable | | | | | | | | |
| | Is the system operated under an Operating Permit? | | | | | | | |
| | Is the system required to employ a Nitrogen BMP? | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

Any "no" answer indicates Noncompliance.

Have the Operating Permit requirements been met?

b. Is the required nitrogen BMP in place and properly functioning?

Compliance criteria

a. Operating Permit number:

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

☐ Yes ☐ No

☐ Yes ☐ No

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 • TTY 651-282-5332 or 800-657-3864 • Available in alternative formats wg-wwists4-31 • 1/24/12 Page 3 of 3

SUNRISE SEPTIC SERVICES, INC.

Jeffrey Fertig
Licensed and Bonded, PCA Certified #2942
12180 Saint Croix Trail, North Branch, MN 55056
(651) 253-2969

ON-SITE SEPTIC SYSTEM CONDITION REPORT

DATE:

July 22, 2019

CLIENT:

Douglas Haseltine

ADDRESS:

22900 Jenson Ave N, Forest Lake, MN 55025

PID#:

1203221220002

REPORT SUMMARY:

At the request of the seller of this property, I have performed an MPCA Compliance Inspection of this septic system. It is my opinion that this onsite sewage treatment system is **non-compliant**. The system consists of a 1250 gallon solid septic tanks and gravity flow trenches. Based on my inspection of the system it is my opinion that this system presently fails to meet MPCA minimum compliance inspection requirements. The bottom of the trenches were located at approximately at 48 inches below grade and redoximorphic features were found at 24 inches below ground, rendering the system with less than 24 inches of separation. Hassle Free Septic pumped the septic tank which appeared to be watertight, baffles in place and functioning properly.

Minimum compliance inspection requirements include only verification that the septic system has a water tight septic tank, the required drain field separation to saturated soils, no backup of sewage into the dwelling and no discharge of sewage/effluent onto the ground surface or surface water (lakes, streams, etc.). Sewage back up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the dwelling prior to inspection. Sunrise Septic Services cannot guarantee that the information given to us relative to back-ups is accurate. Certification of this system does not warranty future use beyond the date of the inspection.

Please contact me if you have any questions.

Jeffrey A. Fertig

Sunrise Septic Services, Inc.

NOTE: This report is not complete without the inclusion/attachment of the respective MPCA Septic System Compliance Inspection form, which consists of two separate pages. Sunrise Septic Solutions has not been retained to guarantee or certify the proper functioning of the system for any period in the future. Because of the numerous factors (usage, maintenance, tank pumping, soil characteristics, previous failures, etc.) which may affect the proper operation of a septic system, and the inability of my company to supervise or monitor the use or maintenance of the system, this report shall not be construed as a warranty by my company that the system will function properly for any particular buyer. Sunrise Septic Services hereby DISCLAIMS ANY WARRANTY, either expressed or implied, arising from the inspection of the septic system or this report. We are also not ascertaining any effect the system is having on the groundwater. This report/inspection is being done for only the seller and the buyer of this property. There is no contract between Sunrise Septic Services and any other party except the seller/buyer. Liability to Sunrise Septic Services Inc. is limited to the cost of this inspection.

Sunrise Septic Services DISCLAIMER SHEET

Relative to Septic System Compliance Inspections:

- 1. This inspection/report is being performed for only the seller/owner or of the property on which the septic system is located; there is no contract between Sunrise Septic Services, Inc. and any other party except the seller/owner unless otherwise noted. In such case that the buyer of the property is paying for the inspection, the contract is between only the buyer of the property and Sunrise Septic Services, Inc., there is no contract with any other party unless otherwise noted. Liability to Sunrise Septic Services Inc. is limited to the cost of this inspection.
- 2. Sunrise Septic Services, Inc. has not been retained to warrant, guarantee, or certify the proper functioning of the system for any period of time beyond the date of inspection or the future. Because of the numerous factors (usage, maintenance, tank pumping, soil characteristics, previous failures, etc.) which may affect the proper operation of a septic system, as well as the inability of Sunrise Septic Services, Inc. to supervise or monitor the use or maintenance of the system, the report shall not be construed as a warranty by Sunrise Septic Services, Inc. that the system will function properly for any particular person for any period of time.
- 3. Minimum Compliance Inspection requirements relative to this inspection and this report include only verification that the septic system has a water tight septic tank(s) and lift tank, the required separation from the bottom of the drainfield/mound distribution medium and saturated soils, no back-ups of sewage into the dwelling, and no discharge of sewage/effluent onto the ground surface or surface water (lakes, streams, etc.) Sunrise Septic Services, Inc. does not inspect basement ejector pumps or exterior lift tank pumps as they are considered to be a "maintenance item". Sewage backup verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the dwelling prior to inspection Sunrise Septic Services, Inc. cannot guarantee that the information given to them by the last occupants of the dwelling prior to inspection relative to backups or failure is accurate. Some persons may attempt to hide or conceal signs of previous back-ups.
- 4. Certification of this system does not warranty future use beyond the date of the inspection. Any system, old or new, can be hydraulically overloaded as a result of more people moving into the house than were previously occupying the house, improper maintenance and/or heavy usage, tree roots, freezing conditions, surface drainage problems, or the system can simply stop working because of its age. The average life expectancy of a properly maintained septic system is twenty five years.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the septic system, a Compliance Inspection is strictly for the purpose of determining if the septic system is polluting the environment at the date and time the inspection is performed. This inspection is not intended to determine if the septic system was originally designed or installed to past or present MPCA or Local Unit of Government code requirements.
- 6. WINTER WORK: Client (person paying for inspection) understands that inspections conducted during winter weather (approximately November 1st through April 1st) are more difficult to perform because of the possible snow cover and ground frost. Septic system components such as tanks, tank covers, drop boxes, drop box covers and soil treatment areas are more difficult to locate because of snow cover and ground frost. Soil borings and locating drainfields are more difficult to perform because of ground frost. Sunrise Septic Services, Inc. will attempt to use the same level of standards when performing winter work as when performing non-winter work. However, the client understands that because of aforementioned considerations, the same level of standards may not be possible.

Respectfully.

Jeffrey A. Fertig Inspector/Owner

JENSON AUC garage House septic land Ca Dieb Box