

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complet prior to performing maintenance activities and remain on-site for the duration of the maintenance activity

				cion of the manitene	ince activity.	
Date of Maintenance	: <u>9/18/18</u> Reasor	for Maintenance:	ROUTIN	E		
Property Address:	391 Quinlan	ave S	Property Owner's N	Name: Steve	Demik	
	keland ZIP: 35					
Maintenance Permit	No: 07249512927	Maintainer Name a	nd Liconso No. W	165 1916	A CONTRACTOR OF THE CONTRACTOR	
	<u></u>	manicaniei Name a	ind License No	1332 K7/13		
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)		11	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
		Sludge Level in				
		Sludge + Scum				
		- % studge & sc				
1. Access used to re	move septage:	unce Holo Mother /	oʻztor oyalb quiqabi.	1. Jal . 1		
			enter authorization c	ode) VII LOWES	coping	
	ecurely replaced? Yes					
evidence of dam	of tank leakage from a sep laged, cracked, or structur	otic, holding, pret ally unsound mair	reatment or pump Itenance hole cove	tank below the opeers? NG	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
* 2	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ❷No	☐ Yes ₩No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
A How many callone	of septage were removed	3				
Tank #1 1500	or septage were removed	f gal Dratuation	A Annali			
5. Other information	gal Tank #2	_ gat Pretreatmen	t tankg	at Pump Tank	gal	
	n: List any troubleshooting	, minor repairs co	nducted, tank sare	ty concerns, or other	er concerns.	
6. Location of septag	e disposal:					
	distinguished on the second of		en generation genètican reseau en en en jair en europer production acceptation en estimation (en jeun de section de secti			

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162