

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its anti-				
This section must be completed in its entirety	to constitute a v	alid maintenance p	permit. This perm	it must be completed
The state of the s	ies and remain o	n-site for the dura	tion of the mainte	nance activity
Date of Maintenance: 4-3-20 Reason	for Maintenance:	Rutius		names activity.
Property Address: 7509 115+ 5+.		Property Owner's N	Name: Chris	Dittbener
Municipality: Stilluuto zip: SSC	87 Property Ide	entification Number		
Maintenance Permit No: Ca 2859 h 1876	latatat N			
Maintenance Permit No: 0,2859 h 18709	laintainer Name a	nd License No. Pink	ky's Environmental	Sewer Service/ L1673
Maintenance Performed		surement (must be		
Tank(s) Pumped		Tank — in		no no r pamped)
☐ Sludge and scum measured	Sludge Level in Tank ——— in Country in Country			
Do tanks need to be pumped?	Sludge + Scum			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenant			inks must be pumpe	ed if 25% or greater
2 Were all covers securely and the last	ce Hole Gother (enter authorization co	ode)	
2. Were all covers securely replaced? Yes	□ No			
3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural	ic, holding, preti	eatment or pump	tank below the op	erating depth or
evidence of damaged, cracked, or structural	lly unsound main	tenance hole cove	rs? 🗌 Yes 🖳 No	
Tank	Leaking Out	Leaking In	Cover Damage	_
Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	-
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?			163 1/2 1/10	-
Tank #1 (500 gal Tank #2 /000 g	al Pretreatment	tank		
5. Other information: List any troubleshooting, n	ainor ropairs son	dirkgal	Pump Tank	gal
lift pump was not man const	mior repairs con	ducted, tank safety	y concerns, or oth	er concerns.
lift pump was out your arrival				
b. Location of septage disposal:				
Dinlata P	Environmental Sev			

PO Box 354

Afton MN 55001