Minnesota Pollution	
Control Agency	

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance Inspection Form

Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

Inspection results based on Minnesota Pollution Control Agency (MPCA)
requirements and attached forms - additional local requirements may also apply.

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

System Status

System status on date (mm/dd/yyyy): 8/19/2020

Compliant – Certificate of Compliance

(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)

Noncompliant – Notice of Noncompliance

For local tracking purposes:

(See Upgrade Requirements on page 3.)

Reason(s) for noncompliance (check all applicable)

- □ Impact on Public Health (Compliance Component #1) Imminent threat to public health and safety
- Other Compliance Conditions (Compliance Component #3) Imminent threat to public health and safety
- Tank Integrity (Compliance Component #2) Failing to protect groundwater

Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater

Soil Separation (Compliance Component #4) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

Property Information

Parcel ID# or Sec/Twp/Range: 0202820120029

Property address: 127 QL	JINLAN AVENUE LAKELAND	Reason for inspection:	PROPERTY TRANSFER
Property owner: LEGRID	MARYE	Owner's phone:	
or			
Owner's representative:		Representative phone:	
Local regulatory authority: WASHINGTON COUNTY		_ Regulatory authority pho	one:
Brief system description:	2 1000 GALLON SEPTIC TANKS, 1000-GALLO	ON LIFT TANK AND 750	SQ FT GRAVITY TRENCHES
Comments or recommend	lations:		

LIFT PUMP AND ELECTRICAL FOUND TO BE FAULTY AND REPLACED.

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

Inspector name:	RYAN-LASHINSKI	Certification number:	3053
Business name:	LASHINGKA SEPTIC SERVICE	License number:	L65
Inspector signature	Le Costist	Phone number:	763-434-3915
	$\nu \in$		
Necessary or	Locally Required Attachments		
🛛 Soil boring log	Js ⊠ System/As-built drawing	Forms per local ordinan	ice
Other informa	tion (list):		

1. Impact on Public Health – Compliance component #1 of 5

Compliance criteria:		Verification method(s):		
System discharges sewage to the	🗌 Yes 🖾 No	\boxtimes Searched for surface outlet		
ground surface.		Searched for seeping in yard/backup in home		
System discharges sewage to drain	🗌 Yes 🛛 No	Excessive ponding in soil system/D-boxes		
tile or surface waters.		Homeowner testimony (See Comments/Explanation)		
System causes sewage backup into	🗌 Yes 🖾 No	"Black soil" above soil dispersal system		
dwelling or establishment.		System requires "emergency" pumping		
Any "yes" answer above indicates the system is an imminent threat to public health and safety.		Performed dye test		
		Unable to verify (See Comments/Explanation)		
		Other methods not listed (See Comments/Explanation,		

Comments/Explanation:

2. Tank Integrity – Compliance component #2 of 5

Compliance criteria:		Verification method(s):
System consists of a seepage pit,	🗌 Yes 🛛 No	Probed tank(s) bottom
cesspool, drywell, or leaching pit.		Examined construction records
Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance.		Examined Tank Integrity Form (Attach)
		Observed liquid level below operating depth
Sewage tank(s) leak below their designed operating depth.	🗌 Yes 🖾 No	Examined empty (pumped) tanks(s)
If yes, which sewage tank(s) leaks:		\boxtimes Probed outside tank(s) for "black soil"
Any "yes" answer above ind	icatos tho	Unable to verify (See Comments/Explanation)
system is failing to protect g		Other methods not listed (See Comments/Explanation)
Comments/Explanation:		

TANKS RECENTLY PUMPED, LIFT PUMP AND ELECTICAL REPLACED

3. Other Compliance Conditions – Compliance component #3 of 5

a.	Maintenance hole covers are dam	aged, cracked, unsecured	d, or appear to be structurally	/ unsound. 🗌 Yes* 🛛 No 🗌 Unknown
----	---------------------------------	--------------------------	---------------------------------	----------------------------------

b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety. *System is an imminent threat to public health and safety.

Explain:

c. System is non-protective of ground water for other conditions as determined by inspector . □ Yes* ⊠ No *System is failing to protect groundwater.

Explain:

4. Soil Separation - Compliance component #4 of 5

Date of installation: 6/2/1997	Unknown	Verification method(s):	
(mm/dd/yyyy) Shoreland/Wellhead protection/Food beverage lodging?	🛛 Yes 🗌 No	Soil observation does not expire. Previous soil observations by two independent parties are sufficien unless site conditions have been altered or local	
Compliance criteria:		requirements differ.	
For systems built prior to April 1, 1996, and	🗌 Yes 🗌 No	\boxtimes Conducted soil observation(s) (At	
not located in Shoreland or Wellhead Protection Area or not serving a food,		Two previous verifications (Attach	boring logs)
beverage or lodging establishment:		Not applicable (Holding tank(s), no	drainfield)
Drainfield has at least a two-foot vertical		Unable to verify (See Comments/E	xplanation)
separation distance from periodically saturated soil or bedrock.		Other (See Comments/Explanation)	
Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	🖾 Yes 🔲 No	Comments/Explanation:	
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*			
"Experimental", "Other", or "Performance"	🗌 Yes 🔲 No	Indicate depths or elevations	
systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080.		A. Bottom of distribution media	30"
2350 or 7080.2400 (Advanced Inspector License required)		B. Periodically saturated soil/bedrock	<72"
Drainfield meets the designed vertical		C. System separation	>36"
separation distance from periodically saturated soil or bedrock.		D. Required compliance separation*	36"
Any "no" answer above indicates the system is failing to protect groundwater.		*May be reduced up to 15 percent if Ordinance.	allowed by Local

5. Operating Permit and Nitrogen BMP* – Compliance component #5 of 5 X Not applicable

 Is the system operated under an Operating Permit?
 □ Yes ⊠ No
 If "yes", A below is required

 Is the system required to employ a Nitrogen BMP?
 □ Yes ⊠ No
 If "yes", B below is required

BMP = Best Management Practice(s) specified in the system design

If the answer to both questions is "no", this section does not need to be completed.

Compliance criteria

a.	Operating Permit number:	□ Yes □ No			
	Have the Operating Permit requirements been met?				
b.	Is the required nitrogen BMP in place and properly functioning?	🗌 Yes 🔲 No			

Any "no" answer indicates Noncompliance.

Upgrade Requirements (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.



Compliance Inspection Attachment for Existing Individual Sewage Treatment Systems

Address 2127 Quinlan


Boring	#3 Elevation: 100'10"	Boring #2 Elevation: 100'3"	Boring #3 Elevation:"
0-6	10YR 3/4, 4/4 dark brown loamy fine sand.		
-43	10YR 5/4 fine sand		
-72	10YR 5/4, 5/3		
	fine/medium sand No redoximorphic mottling observed, soil dry.		

Sketch:


See attached


Comments: Benchmark = top of distribution pipe in fourth trench. Assumed elevation = 100'0". Soil boring #1 indicated no redoximorphic mottling at a depth of 72". The system does meet the required 36" vertical separation (31" with the allowable 15% reduction) from seasonally saturated soils. The system consists of two 1000-gallon septic tanks, a 1000-gallon lift tank and 750 sq. ft of gravity trenches w/12" of rock beneath the distribution pipe. The tanks were recently pumped, the baffles were checked and are o.k. The lift pump was replaced as it was found to be inoperable. The liquid level in all three boxes were below normal operating levels. This inspection is not a warranty or guarantee, either written or implied, of future or long-term hydraulic functionality/performance, but rather a determination if the systems use is/may cause pollution and/or adverse harm to the environment, groundwater or public health and safety at the time of this inspection. Buyers should be aware of the age of this system (23 years). No guarantee can be made on future hydraulic performance, or the performance of system components (pumps, controls, etc.). Changes in use can cause any system, failing or compliant, to become hydraulically overloaded and ultimately fail. Owner/buyer assumes full responsibility for the long-term performance of this system as well as any future upgrade, repairs or replacement costs. Liability is limited to the cost of this inspection.

Washington County, MN



August 19, 2020





STANDARD SYSTEM DESIGN INDIVIDUAL SEWAGE TREATMENT SYSTEM

RECEIVED

JUN 0 4 1997

WASHINGTON COUNTY HEALTH, ENVIRONMENT & LAND MANAGEMENT 14900 N. 61ST STREET, P.O. BOX 3803, STILLWATER, MN 55082-3803 612/430-6708 OR 612/430-6656 FAX 612/430-6730

Owner's Name	GARY LEGRID	
Job Site Address	127 QUINIAN LUE S.	
City or Township	LAKELLO MN. 55043	
Use of Building	S-F. D.	

Design Flow Rate 60	O Perc Rate	6 - 15	Land Slope	2	Percent
Two Required Tank Sizes	1000 Gallons	1000 Gallons	Lift Station Tank S	Size 100	Gallons
Type of System (standard, at	grade or bed)	STANDAR	23	<u></u>	<u> </u>
System Size: 750) -Square Feet	250 -Li	neal Feet	31	-Trench Width
Depth of rock below pipe	12"		Depth of Rock Ab	ove Pipe 2	75
MINimum Depth of Trench From Existing Grade	24"	Inches	MAXimum Depth From Existing Grad	* -	. Inches
Recommended Number of Tr	enches	6	Recommended Len	igth of Trenches	40
Trench Spacing Measured Ce	nter to Center	13	7		Feet
Any Other Special Conditions	S IF DEP 13 TOO PE		APD CI		

IF PRESSURE DISTRIBUTION IS USED, COMPLETE THE PRESSURE DISTRIBUTION WORK SHEET ATTACHED.

This design must be accompanied by a site plan that clearly shows the location of the area tested and approved by the following:

- 1. Use an appropriate scale and indicate direction by use of a north arrow.
- 2. Show ALL property boundaries, rights-of-way, easements, wetlands. If necessary, an enlarged detail of the house site may also be required.
- 3. Show location of house, garage, driveway and all other improvements existing or proposed.
- 4. Show location and layout of sewage treatment system.
- 5. Show location of water supply (well and/or community supply line).
- 6. Dimension all setbacks and separation distances.

This system has been designed by a Pollution Control Agency (PCA) Certified Profession	onal.
Designer Name JOE CHAVES	PCA Certification # 815
Address	Phone # <u>936-1384</u>
Signature Delta	Date 6-2-97

An Equal Employment Opportunity/Affirmative Action Employer

If You Need Assistance Due to Disability or Language Barrier, Please Call 430-6708 OR 430-6656 (TDD 439-3220)