### **Midwest Sewer Services**

P.O. Box 10853 White Bear Lake, MN 55110 651-492-7550/Brian@Midwestsoiltesting.com

Brian Humpal MPCA Licensed Advanced Inspector

#### SUBSURFACE SEWAGE TREATMENT SYSTEM (SSTS) COMPLIANCE REPORT

**Inspection Address:** 12841 90<sup>th</sup> St, Denmark Twp, MN 55033

#### REPORT SUMMARY

I have performed an "MPCA Compliance Inspection" on this system. We have contacted Washington County and were advised that there are no records for this system. This very old system (installation date unknown) consists of a cesspool. Additional cesspool(s) and/or a drainfield may exist beyond the first cesspool. This system was not pumped at the time of inspection.

My inspection indicates that this system is presently "non-compliant" in accordance with MPCA rules 7080.1500 Subp.4(B) because of the cesspool(s).

In accordance with MPCA rules, I am sending a copy of this complete report to Washington County. I cannot officially speak on behalf of the County relative to the upgrade requirements of these non-compliant systems. Please contact the Washington County Department of Public Health & Environment (651-430-6655) to verify the County's position.

Please advise buyer, agents, lender, etc. to contact me should they have any questions regarding this system.

Christopher Uebe

Brian Humpal

Brian Humpal



520 Lafayette Road North St. Paul, MN 55155-4194

# Compliance inspection report form

**Existing Subsurface Sewage Treatment System (SSTS)** 

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at <a href="https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf">https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf</a>.

Property information	Local tracking	number:		
Parcel ID# or Sec/Twp/Range:	Reason for Inspection	Property Transfer		
Local regulatory authority info: Washington County				
Property address: 12841 90 <sup>th</sup> St, Denmark Twp, MN 55033				
Owner/representative: Nick Keene		Owner's phone: 651-283-3212		
Brief system description: A cesspool with possible additional ces	sspool(s) and/or drainfield.			
System status				
System status on date (mm/dd/yyyy): 11/29/2023				
☐ Compliant – Certificate of compliance*	⊠ Noncompliant – Notic	ce of noncompliance		
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and		ound water must be upgraded, replaced, or ime required by local ordinance.		
a shorter time frame exists in Local Ordinance.)	upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.			
R. 7080.1500 as of system status date above and does not guarantee future performance.				
Reason(s) for noncompliance (check all applicab	le)			
<ul> <li>☐ Impact on public health (Compliance component #1) − Imminent threat to public health and safety</li> <li>☐ Tank integrity (Compliance component #2) − Failing to protect groundwater</li> <li>☐ Other Compliance Conditions (Compliance component #3) − Imminent threat to public health and safety</li> <li>☐ Other Compliance Conditions (Compliance component #3) − Failing to protect groundwater</li> <li>☐ System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) − Failing to protect groundwater</li> <li>☐ Soil separation (Compliance component #5) − Failing to protect groundwater</li> <li>☐ Operating permit/monitoring plan requirements (Compliance component #4) − Noncompliant - local ordinance applies</li> <li>Comments or recommendations</li> </ul>				
Certification				
I hereby certify that all the necessary information has been gathered future system performance has been nor can be made due to unknow inadequate maintenance, or future water usage.				
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my	knowledge, and that this information can be		
Business name: Midwest Sewer Services		Certification number: 5342/9852		
Inspector signature: Brian Humpal Home		License number: L2896		
(This document has been electronically sign	ned)	Phone: 651-492-7550		
Necessary or locally required supporting documentation (must be attached)				
☐ Soil observation logs ☐ System/As-Built ☐ Locally required forms ☐ Tank Integrity Assessment ☐ Operating Permit				
☐ Other information (list): Report Summary, Property Information	tion, Disclaimer			

npact on public health – Compliance compo Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes* ☒ No	☐ Other: ☐ Not applicable
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No	☐ Not applicable
System causes sewage backup into dwelling or establishment.	☐ Yes* ⊠ No	
Any "yes" answer above indicates imminent threat to public health a		
ank integrity – Compliance Compliance criteria:	component #2	of 5  Attached supporting documentation:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,	component #2	Attached supporting documentation:  ☐ Empty tank(s) viewed by inspector
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	· 	Attached supporting documentation:
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	∑ Yes* □ No	Attached supporting documentation:  □ Empty tank(s) viewed by inspector  Name of maintenance business:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	∑ Yes* □ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	∑ Yes* □ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indices.	Yes* □ No  Yes* □ No  All Tanks  ates the system	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure assessment complies within three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	Yes* □ No  Yes* □ No  All Tanks  ates the system	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance (mm/dd/yyyy): (must be within three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indices.	Yes* □ No  Yes* □ No  All Tanks  ates the system	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure assessment complies we Minn. R. 7082.0700 subp. 4 B (1))

Pro	pperty Address: 12841 90 <sup>th</sup> St, Denmark Twp, MN 55033		
	siness Name: Midwest Sewer Services	Date: 11/29/2023	
3.	Other compliance conditions – Compliance component #3 of 5		
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unso	ecured?	
	☐ Yes* ☒ No ☐ Unknown		
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safe	ty? ☐ Yes* ☐ No ☐ Unknown	
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.		
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No	
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☒ No	
	*Yes to 3c or 3d - System is failing to protect groundwater.		
	Describe verification methods and results:		
	Attached supporting documentation:   Not applicable		
4.	Operating permit and nitrogen BMP* – Compliance component #4 c	of 5 🛛 Not applicable	
	Is the system operated under an Operating Permit? ☐ Yes ☐ No	If "yes", A below is required	
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No		
	BMP = Best Management Practice(s) specified in the system design		
	If the answer to both questions is "no", this section does not need to be completed.		
	Compliance criteria:		
	a. Have the operating permit requirements been met?		
	b. Is the required nitrogen BMP in place and properly functioning?		
	Any "no" answer indicates noncompliance.		
	Describe verification methods and results:		
	Attached supporting documentation: ☐ Operating permit (Attach) ☐		

https://www.pca.state.mn.us 651-296-6300 800-657-3864 Use your preferred relay service •

Date of installation (mm/dd/yyyy)	_⊠ Unknown	
Shoreland/Wellhead protection/Food beverage lodging?	☐ Yes ⊠ No	Attached supporting documentation:  ☐ Soil observation logs completed for the report
Compliance criteria (select one):		☐ Two previous verifications of required vertical separation
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	☐ Yes ☐ No*	⊠ Not applicable (No soil treatment area)
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.		
	☐ Yes ☐ No*	Indicate depths or elevations  A. Bottom of distribution media
		B. Periodically saturated soil/bedrock
		C. System separation
		D. Required compliance separation*
		*May be reduced up to 15 percent if allowed by Local Ordinance.
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day)	☐ Yes ☐ No*	
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.		

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

https://www.pca.state.mn.us 651-296-6300 800-657-3864 Use your preferred relay service wq-wwists4-31b • 4/28/2021


Page 4 of 4

# Midwest Sewer Testing Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA	Compliance Inspection.			
Date of Inspection: November 29, 2023	Time: 12:30 PM			
Property Address: 12841 90 <sup>th</sup> St, Denmark Twp, MN	Zip: 55033			
Property Owner: Nick Keene	Phone: 651-283-3212			
Tank(s)       Tank(s)Material       Soil Treatment System         □ Septic       □ Fiberglass       □ Rock trench         □ Aerobic       □ Plastic       □ Gravelless trench         □ Lift       □ Metal       □ Chamber trench         □ Holding       □ Concrete       □ Seepage bed         □ Other:       □ Block       □ Mound         □ Other       □ At-grade	Other  Alternative system Experimental system Cesspool system 1 or more Other system			
Are the tank maintenance covers accessible? ☐ Yes ☒ No *If i	no, proper maintenance must be			
performed through the maintenance holes. Maintenance hole cover				
the ground surface to facilitate access and proper maintenance of t	he system.			
Year house built: 1958 Year septic installed: Unknown	Tank size (gals.):			
	sidents in home?			
Number of bedrooms? 3 Are all floors drained by g	-			
Garbage disposal? Whirlpool bath?				
More than one system (laundry, etc.)?				
Does this property have any footing drain tiles connected to the septic system?				
Are any buildings on this property such as garages or out-buildings connected to this system? Floor drains in outbuilding, daylight.				
Are there any additional systems on this property serving other buildings?				
Location of septic system on lot? West Side				
	well a deep well? Y?			
Have you ever experienced any problems with the system such as: tree roots, sewage back-ups,				
surfacing of sewage onto the ground, septic tank overflowing, etc.; or have any repairs been made to the system?  If yes, explain:				
When was the system last pumped? Unknown Name of pum	per: Unknown			
	on a monitoring plan?			
Have you received notices from any government agency concerning this system?				
Is your property located in a shoreland management area? N				
Do you have any additional information that should be given to the new owner?				
I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection				

this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this insp by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant:	Date:





### **DISCLAIMER**

## Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.