## **Midwest Sewer Services**

P.O. Box 10853 White Bear Lal 651-492-7550/Brian@Midwests	ce, MN 55110 oiltesting.com	Brian Humpal MPCA Licensed Advanced Inspector
SUBSURFACE SEWAGE TRE	ATMENT SYSTEM	(SSTS) COMPLIANCE REPORT
Date: 2/20/2024 & 2/23/2024	<b>Time:</b> 11:15 AM	<b>Owner:</b> John Zuniga
Inspection Address: 21400 Pomro	y Ave N, Scandia, MN	55073

### **REPORT SUMMARY**

I have performed an "MPCA Compliance Inspection" on this system and have reviewed the original design/permit records, along with a previous compliance inspection from 2000, which were on file at Washington County. This system (installed in 1978) consists of a pre-cast septic tank and a rock trench drainfield. Olson's Sewer Service pumped the septic tank on February 23, 2024.

Predicated on my inspection of the system and my review of the records, it is my opinion that this system <u>presently meets</u> MPCA minimum compliance inspection requirements.

Midwest Sewer Services have been hired to perform a compliance inspection of this SSTS for compliance with local ordinances pursuant to Minn. Stat. § 115.55 (2013). This compliance inspection covers only the criteria required by Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011). A compliance inspection is an indication of the current compliance status of the system and does not guarantee the performance or longevity of this system beyond the date of inspection, as it is impossible to determine the future performance of any system. Midwest Sewer Services disclaim any use of this compliance inspection beyond determining SSTS compliance pursuant to Minn. Stat. § 115.55 Subd. 5a (2013) and Minn. R. 7080.1500 (2011).

Please contact me should you have any questions.

Christopher Uebe

Brian Humpal

Brian Humpal



520 Lafayette Road North St. Paul, MN 55155-4194

# Compliance inspection report form

## Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at <a href="https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf">https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf</a>.

2 of 12

Property information	Local tracking	number:
Parcel ID# or Sec/Twp/Range:	Reason for Inspection	Property Transfer
Local regulatory authority info: Washington County		
Property address: 21400 Pomroy Ave N, Scandia, MN 55073		
Owner/representative: John Zuniga		_ Owner's phone: <u>651-783-2077</u>
Brief system description: A pre-cast septic tank and a rock trench	drainfield.	

### System status

System status on date (mm/dd/yyyy): 2/23/2024

Compliant – Certificate of compliance\*

(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)

\*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.

#### □ Noncompliant – Notice of noncompliance

Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.

An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.

#### Reason(s) for noncompliance (check all applicable)

Impact on public health (Compliance component #1) – Imminent threat to public health and safety

Tank integrity (Compliance component #2) - Failing to protect groundwater

Other Compliance Conditions (Compliance component #3) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance component #3) - Failing to protect groundwater

System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) – Failing to protect groundwater

Soil separation (Compliance component #5) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance component #4) – Noncompliant - local ordinance applies

#### **Comments or recommendations**

## Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

By typing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form.

Business name: Midwest Sewer Services

- Humpal After the

Certification number: 5342/9852

Inspector signature:

document has beer	n electronically signed)
-------------------	--------------------------

License number: L2896

Phone: 651-492-7550

### Necessary or locally required supporting documentation (must be attached)

Soil observation logs System/As-Built Locally required forms Tank Integrity Assessment Operating Permit Other information (list): Report Summary, Property Information, Disclaimer

3 of 12

Property Address: 21400 Pomroy Ave N, Scandia, MN 55073

Business Name: Midwest Sewer Services

Date: 2/23/2024

Page 2 of 4

## 1. Impact on public health – Compliance component #1 of 5

Compliance criteria:		Attached supporting documentation:	
System discharges sewage to the ground surface	🗌 Yes* 🛛 No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	🗌 Yes* 🛛 No		
System causes sewage backup into dwelling or establishment.	🗌 Yes* 🛛 No		
Any "yes" answer above indicates imminent threat to public health an		_	
Describe verification methods and	results:		

None of the above found.

## 2. Tank integrity – Compliance component #2 of 5

Compliance criteria:		Attached supporting o	locumentation:		
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	Empty tank(s) viewed by inspector Name of maintenance business:			
Sewage tank(s) leak below their designed operating depth?	🗌 Yes* 🛛 No	License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach)			
If yes, which sewage tank(s) leaks:		Date of maintenance (mm/dd/yyyy):	2/23/2024 (must be within three years)		
Any "yes" answer above indicates the system is failing to protect groundwater.		(See form instructions to ensure assessment complies wi Minn. R. 7082.0700 subp. 4 B (1))			
		☐ Tank is Noncompliant ( ☐ Other:	pumping not necessary – explain below)		

Describe verification methods and results:

4 of 12

Property Address: 21400 Pomroy Ave N, Scandia, MN 55073 Business Name: Midwest Sewer Services

Compliance criteria:

a. Have the operating permit requirements been met?

Describe verification methods and results:

Any "no" answer indicates noncompliance.

Date: 2/23/2024

### 3. Other compliance conditions – Compliance component #3 of 5

	За.	Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unso	ecured?		
		□ Yes* ⊠ No □ Unknown			
	3b.	Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safe	ty? □ Yes*	🖾 No 🔲 Unknown	
		*Yes to 3a or 3b - System is an imminent threat to public health and safety.			
	3c.	System is non-protective of ground water for other conditions as determined by inspector?	□ Yes*	🖾 No	
	3d.	System not abandoned in accordance with Minn. R. 7080.2500?	□ Yes*	🖾 No	
		*Yes to 3c or 3d - System is failing to protect groundwater.			
		Describe verification methods and results:			
		Attached supporting documentation: 🛛 Not applicable			
					-
4.	Ор	erating permit and nitrogen BMP* – Compliance component #4 c	of5 ⊠ №	lot applicable	
	Is th	e system operated under an Operating Permit?	lf "yes", A	below is required	
	Is th	e system required to employ a Nitrogen BMP specified in the system design? $\square$ Yes $\square$ No	lf "yes", B	below is required	
		BMP = Best Management Practice(s) specified in the system design			

□ Yes □ No

Attached supporting documentation: 
Operating permit (Attach)

If the answer to both questions is "no", this section does not need to be completed.

b. Is the required nitrogen BMP in place and properly functioning? 
Yes No

5 of 12

Property Address:	21400 Pomroy Ave N, Scandia, MN 55073
Rusiness Name	Midwest Sewer Services

Business Name: Midwest Sewer Services

## 5. Soil separation – Compliance component #5 of 5

Date of installation 1978 (mm/dd/yyyy)	_ 🗌 Unkr	nown			
Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one):		🛛 No	<ul> <li>Attached supporting documentation:</li> <li>⊠ Soil observation logs completed for the report</li> <li>□ Two previous verifications of required vertical set</li> </ul>		
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical	🛛 Yes	□ No*	<ul> <li>Not applicable (No soil treatment area</li> <li>Reviewed previous compliance inspective Reviewed design and permit records.</li> </ul>		
separation distance from periodically saturated soil or bedrock. 5b. Non-performance systems built	□ Yes	□ No*	Indicate depths or elevations		
April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:			A. Bottom of distribution media B. Periodically saturated soil/bedrock	See Attached Boring Log(s)	
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*			C. System separation     D. Required compliance separation*     *May be reduced up to 15 percent if allo	wed by Local	
<ul> <li>5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required &gt; 2,500 gallons per day)</li> <li>Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.</li> </ul>	☐ Yes	□ No*	Ordinance.		

\*Any "no" answer above indicates the system is failing to protect groundwater.

Describe verification methods and results:

**Upgrade requirements:** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

Date: 2/23/2024

MINNESOTA POLLUTION CONTROL AGENCY

# Sewage tank integrity assessment form

520 Lafayette Road North St. Paul, MN 55155-4194

### Subsurface Sewage Treatment Systems (SSTS) Program

Doc Type: Compliance and Enforcement

Purpose: This form *may* be used to certify the compliance status of the sewage tank components of the SSTS. This form is not a complete SSTS inspection report, only a tank integrity assessment, and may only certify sewage tank compliance status when entirely completed and signed by a qualified professional. SSTS compliance inspection report forms can be found at: <a href="https://www.pca.state.mn.us/water/inspections">https://www.pca.state.mn.us/water/inspections</a>.

**Instructions:** This form may be completed, and signed, by a Designated Certified Individual (DCI) of a licensed SSTS inspection, maintenance, installation, or service provider business who personally conducts the necessary procedures to assess the compliance status of each sewage tank in the system. Only a licensed maintenance business is authorized to pump the tank for assessment. A copy of this information should be submitted to the system owner and be maintained by the licensed SSTS business for a period of five (5) years from the assessment date.

When this form is signed by a qualified certified professional, it becomes *necessary supporting documentation* to an Existing System Compliance Inspection Report: <u>Compliance inspection form - Existing system (wq-wwists4-31b)</u>. This form can be found on the MPCA website at <u>https://www.pca.state.mn.us/water/inspections</u>.

The information and certified statement on this form is **required** when existing septic tank compliance status is determined by an individual other than the SSTS Inspector that submits an inspection report. This form represents a third party assessment of SSTS component compliance and is allowable under Minn. R. 7082.0700, subp. 4(B)(1). This form is valid for a period of three years beyond the signature date on this form unless a new evaluation is requested by the owner or owner's agent or is required according to local regulations. Additional Administrative Rule references for this activity can be found at Minn. R. 7082.0700, subp. 4(B),(C), and (D) and; Minn. R. 7083.0730(C).

#### **Owner information**

Owner/Representative John Zunigg		
Owner/Representative John Zuniga Property address: 21400 Pomroy Auc N		
Local Regulatory Authority:	Parcel ID:	
System status		
System status on date (mm/dd/yyyy): 2/23/24		
Certificate of sewage tank compliance	Notice of sewage tar	nk non-compliance
Complianc	e criteria:	
The SSTS has a seepage pit, cesspool, drywell, leaching pit, or oth Groundwater."	ner pit - "Failure to Protect	□ Yes*_₽KNo
The SSTS has a sewage tank that leaks below the designed opera Groundwater."	ting depth - "Failure to Protect	Yes* No
The SSTS presents a threat to public safety by reason of structural or weak) maintenance hole cover(s) or lids or any other unsafe con <b>Public Health or Safety.</b> "		
Any "vac" answar above indicate		

Any "yes" answer above indicates sewage tank non-compliance.

#### **Company information**

Print name: Mark Stadler

Company name: Olson's Sewer Service, Inc. Business license number: 216

Certification number: C1937

I personally conducted the work described above as a Designated Certified Individual of a Minnesota-licensed SSTS inspection, maintenance, installation, or service provider Business. I personally conducted the necessary procedures to assess the compliance status of each sewage tank in this SSTS.

By typing/signing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form.

Designated Certified Individual's signature:

(This document has been electronically signed.)

Date (mm/dd/yyyy): 2/23/24

www.pca.state.mn.us • 651-296-6300 • 800-657-3864 wq-wwists4-91 • 5/10/21


Available in alternative formats Page 1 of 1

## <u>Midwest Sewer Testing</u> Subsurface Sewage Treatment System Owner/Property Information

This information will be used for the purpose of conducting an MPCA Compliance Inspection.					
Date of Inspection: 2/20/2024 & 2/23/2024	Time: 11:15 AM				
Property Address: 21400 Pomroy Ave N, Scandia, MN	Zip: 55073				
Property Owner: John Zuniga	Phone: 651-783-2077				
Tank(s)       Tank(s)Material       Soil Treatment System         Septic 1       Fiberglass       Rock trench         Aerobic       Plastic       Gravelless trench         Lift       Metal       Chamber trench         Holding       Concrete       Seepage bed         Other:       Block       Mound         Other       At-grade	Other Alternative system Experimental system Cesspool system Other system				
Are the tank maintenance covers accessible? $\square$ Yes $\square$ No *If	no, proper maintenance must be				
performed through the maintenance holes. Maintenance hole cover					
the ground surface to facilitate access and proper maintenance of t					
	Tank size (gals.): 1200				
	sidents in home?				
Number of bedrooms? 3         Are all floors drained by g           Carbon dimensional backs         Which and backs					
Garbage disposal? Whirlpool bath?					
More than one system (laundry, etc.)? Does this property have any footing drain tiles connected to the se	ntia avatam?				
Does this property have any rooting drain thes connected to the se					
Are any buildings on this property such as garages or out-building					
Are there any additional systems on this property serving other bu	ildings?				
Lagation of continguation on lot? North Side					
Location of septic system on lot? North SideLocation of water well on lot? South SideIs the	e well a deep well? Y				
Have you ever experienced any problems with the system such as:	1				
surfacing of sewage onto the ground, septic tank overflowing, etc.	• •				
to the system? If yes, explain:	, of have any repairs been made				
When was the system last pumped? 2/23/2024 Name of pum	per: Olson's Sewer Service				
	n on a monitoring plan?				
Have you received notices from any government agency concerning	ng this system?				
Is your property located in a shoreland management area? N	2				
Do you have any additional information that should be given to th	e new owner?				

I hereby certify that the above information is correct to the best of my knowledge. I also understand that if the system is considered "non-compliant/failing" per MPCA rules, that the inspector must by law submit a copy of this report to the local government unit within 15 days of the date of inspection completion. I also agree that unless otherwise noted in this report, that I/we are ultimately responsible for payment of all fees for all work performed relative to this inspection by Inspect Minnesota and Midwest Soil Testing

Owner/Occupant:



# Soil Observations Log

Location of Project: 21400 Pomroy Ave N, Scandia, MN 55073							
Observations Made By: Midwest Sewer Ser						Date:	2/20/2024
C	lassific	ation System:	USDA				
	Soil	Observation:	ST-1		Soil C	bservation:	
Surface Elevation of Observation drainfield trench				face tion of vation			
Depth In Inches	Rock %	<u>Soils E</u>	ncountered	Depth In Inches	Rock %	<u>Soils</u>	<u>Encountered</u>
0-3 3-27 27-31 31-45 45-75	≈25	7.5YR 2 7.5YR 3/4 Sand 7.5YR 3/ 7.5YR 3/4 M Trace	.5/2 Silt Loam .5/3 Silt Loam dy Loam With Gravel '4 Sandy Loam ledium Sand With e Of Gravel				
75"	Depth T	o End Of Soil O	bservation Or Redox		Depth T	o End Of Soil (	Observation Or Redox
Same	Elevatio	n Of Observatio	on Relative To System		Elevatio	n Of Observati	on Relative To System
-42"	Depth T	o Bottom Of Dis	stribution Media		Depth T	o Bottom Of D	istribution Media
	Of Sepa				Of Sepa		
			75"			1	
		Observation At:	75"			servation At:	
		Conditions At:	None			onditions At:	
Stan	Standing Water Present At: None				ng Wate	r Present At:	

Bottom Of Distribution Medium At: 42 Inches

Signature:

Afren Va

Logs of Soil Borings 3-31 Location or Project 21400 10 of the m 5-9-00 Date Borings made by \_\_\_\_\_ Classification System: AASHO ; USDA-SCS X; Unified \_\_\_\_; other Auger used (check two): Hand X, or Power \_\_; Plight \_\_, or Bucket X : other \_\_ Boring number \_\_\_\_ Ъ-Boring number \_\_\_\_ Depth. Depth, in in Surface elevation Surface elevation \_\_\_\_ feet feet 0 -0 -10 1R 3/6 DK . YELL BRN. 1 -SANDY CL- LOAM. 2 ----2 -----3 — 5 -8 -End of boring at \_\_\_\_\_ feer. End of boring at feet Standing water table: Scanding water table: Present at \_\_\_\_\_ feet of deptri-Present at \_\_\_\_\_ feet of depth, hours after boring hours after boring, Not present in boring hole \_\_\_\_\_ Not present in boring hole \_\_\_\_\_ Mottled soil: Mottled soil: Observed at \_\_\_\_\_ feet of cestr Observed at \_\_\_\_\_ feet of depth. Not present in boring hole \_\_\_\_\_ Not present in boring hole \_\_\_\_\_. Observations and comments: Observations and comments: FEET OR **INCHES** TOP OF DRAINFIELD AT FEET OR BOTTOM OF DRAINFIELD AT INCHES REMARKS


### -SOIL BORINGS-

Soil borings are made in order to determine the type and structure of soils at various depths as. well as the location of the water table, impervious strata or bedrock.

Borings are most easily made with a hand auger, however other expedients may be utilized - back hoe, post hole auger, etc.

Soils encountered at various depths should be listed as to appearance, texture and composition.

Depth at which water, bedrock or heavy clay layer is encountered should be recorded.



## LOG OF SOIL BORINGS

BORING NO. I	BORING	NO. 2 BOR	ING NO. 3	BORIN	NG NO. 4
DEPTH SOIL IN DESCRIPTION	DEPTH S IN DESC FEET DESC	OIL DEPTH	SOIL DESCRIPTION	OEPTH IN FEET	SOIL DESCRIPTION
0 1/2 TopSoil	0 1/2 To	p.Sorl 1/2	TopSoil	0 1/2	TopSoil
1 11/2 Loam	11/2 Cl	ndy 11/2	Fine Sand	1	Sandy Chay Bed Rock
2 21/2 3	2 21/2 3	1 2 21/2 3	ljnavel	2 21/2 3	Sandy
3 . 31/2 4	31/2	31/2	4	31/2	Carg
41/2 clay 5 0 0	41/2 Jun 5 CV	ndy 41/2 41/2		41/2 5	
51/2 Bedrock	51/2 .d	wel 51/2 6	Bedroch	51/2 6	Bed Rock
61/2 frank	61/2 7 71/2 Sa	61/2 7		61/2 7	Sand
71/2 Sand 8 Irrauf	8	lal 8		71/2 8	Gravel
9	8 I/2 9	0 81/2		8 1/2 9	-K-

# **DISCLAIMER**

### Brian L. Humpal, Inc. dba. Midwest Sewer Services, Inspect Minnesota, Midwest Soil Testing Relative to Subsurface Sewage Treatment System (SSTS) Compliance Inspections

- 1. This inspection/report is being performed for only the seller/owner of the property on which the SSTS is located. In such case that another party is paying for the inspection, the contract is between only said party and Brian L. Humpal, Inc.; there is no contract between Brian L. Humpal, Inc. and any other party unless otherwise noted.
- 3. Brian L. Humpal, Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the SSTS for any period of time beyond the date of inspection or into the future. Because of the numerous factors (usage, maintenance, soil characteristics, previous failures, etc.) which may affect the proper operation of an SSTS, as well as the inability of Brian L. Humpal, Inc. to supervise or monitor the use or maintenance of the SSTS, the report shall not be construed as a warranty by Brian L. Humpal, Inc. that the SSTS will function properly for any particular party for any period of time.
- 4. Brian L. Humpal, Inc. is unable to verify the frequency and/or, quality of prior or future maintenance of the SSTS. Maintenance of the tank(s) must be performed through the tanks maintenance hole. The removal of solids from any location other than the maintenance hole is not a compliant method of maintenance. It is strongly recommended that maintenance covers be made accessible to the ground surface to facilitate proper maintenance.
- 5. Minimum Compliance Inspection requirements relative to this inspection and this report include <u>only</u> verification that the SSTS has tank(s) (septic tanks, lift tanks, dosing tanks, stilling tanks, etc.) which are watertight below the designed operating depth, the required separation between the bottom of the subsurface soil distribution medium and seasonally saturated soils, no back-ups of sewage into the dwelling, no discharge of sewage/effluent to the ground surface or surface waters, and no imminent safety hazards. Brian L. Humpal, Inc. does not inspect plumbing or pumps prior to the first SSTS component as these are plumbing components. The performance of exterior pumps and associated components are not inspected as they are considered to be maintenance items. Additionally, no indications relative to compliance with electrical code requirements have been made. It is recommended that any other applicable plumbing, electrical, housing, etc. inspections be performed by a qualified inspection business. Sewage back-up verification is limited to observing the floor drain area and/or the information supplied by the last occupants of the building prior to inspection. Brian L. Humpal, Inc. cannot guarantee that the information given to them by the last occupants of the building prior to inspection relative to back-ups is accurate.
- 4. Certification of this SSTS does not warranty future use beyond the date of the inspection. Any SSTS, old or new, can become hydraulically overloaded or discharge sewage/effluent to the ground surface as a result of more people moving into the house than were previously occupying the house, improper maintenance, heavy usage, leaking plumbing fixtures, groundwater infiltration, tree roots, freezing conditions, surface drainage problems, poor initial design, poor construction practices, or unsuitable materials used in constructing the system; the system can also simply stop working because of its age. An SSTS that has been properly designed and installed, properly maintained, and used in the manner for which the system was designed can be expected to provide service for twenty to twenty-five years on average. Some parts of the SSTS such as alarms, switches, pumps, filters, etc. will most likely have to be repaired or replaced over the lifetime of the system.
- 5. A Compliance Inspection is not meant to be a test or inspection for longevity of the system; a Compliance Inspection is strictly for the purpose of determining if the SSTS is protective of public health and safety, as well as the groundwater at the date and time the inspection was performed. This inspection is not intended to determine if the SSTS was originally designed or installed to past or present MPCA or other Local Government Unit code requirements. This inspection is not intended to determine if the SSTS was designed and/or installed to support the anticipated flow from the building as the use of the building may have changed since the design and construction of the SSTS due to the addition of bedrooms, occupants, etc. In addition, this inspection is not intended to determine the quality of the original SSTS design, the quality of the construction practices used while installing the SSTS, or the quality of the materials used in constructing the SSTS.
- 6. Brian L. Humpal, Inc. cannot guarantee the performance of SSTS products/components such as: gravelless pipe, chamber trenches, effluent filters, tanks, sewage pre-treatment components, piping, etc. Products such as gravelless pipe are no longer approved for installation in the State of Minnesota and may have a significantly reduced performance and/or life expectancy.
- 7. WINTER WORK: By accepting this report, it is understood that inspections conducted during winter months (approximately November 1<sup>st</sup> through April 1<sup>st</sup>) are more difficult to perform because of possible snow cover and/or ground frost. SSTS components such as tanks, maintenance covers, tank inspection pipes, subsurface distribution medium inspection pipes, and soil treatment areas are more difficult or impossible to locate due to snow cover and/or ground frost. In addition, soil borings are more difficult to perform due to snow cover and/or ground frost. Brian L. Humpal, Inc. will attempt to use the same level of standards when performing work during winter periods as when performing work during non-winter periods. However, the recipient of this report understands that because of the aforementioned considerations, the same level of standards may not be possible.
- 8. By accepting this report, the client understands that Brian L. Humpal, Inc. will not be responsible for any monetary damages exceeding the fee for the services provided.