

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 5/9/16 Reason for Maintenance: ROUTINE					
Property Address: 2390 . ITASCA AVES Property Owner's Name: JAMES BEYERS DORF					
Municipality: St. Marys Point ZIP: 55043 Property Identification Number:					
Maintenance Permit No: 04503 y OLIQ Maintainer Name and License No. MEYER - L915					
Maintenan	ce Performed	Tank Measu	rement (must be c	ompleted if tanks	NOT pumped)
X Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if n	o provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole □ Other (enter authorization code) Were all covers securely replaced? Yes □ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
,	Tank	Leaking Out	Leaking In	Cover Damage	
ā.	Septic/Holding Tank #1	☐ Yes 🕅 No	☐ Yes 🕅 No	☐ Yes 🗶 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 15(90) gal Tank #2		gal Pretreatment	tankgal	Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					