

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety				
prior to perform	ning maintenance activiti	es and remain on-	site for the duration	on of the maintenanc	ce activity.
	10/17/16 Reason				
Property Address:	3457 6th ST.	№ . P	roperty Owner's Na	me: KATHY W	IDIN
Municipality: WEST	LAKELAND ZIP: 550	82 Property Iden	tification Number:		
	:_n524124711 N				5
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec	ove septage: Maintenal curely replaced? Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, pretr	eatment or pump	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes No	□ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	
4. How many gallons		☐ Yes ☐ No			
Tank #1 1700	Pump Tank of septage were removed gal Tank #2	Yes No Yes No Real Pretreatmen	☐ Yes ☐ No t tankg	☐ Yes ☐ No al Pump Tank	gal
Tank #1 1700	Pump Tank	Yes No Yes No Real Pretreatmen	☐ Yes ☐ No t tankg	☐ Yes ☐ No al Pump Tank	
Tank #1 1700	Pump Tank of septage were removed gal Tank #2	Yes No Yes No Real Pretreatmen	☐ Yes ☐ No t tankg	☐ Yes ☐ No al Pump Tank	
Tank #1 1700	Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	Yes No Yes No Repair No gal Pretreatmen minor repairs co	☐ Yes ☐ No t tankg nducted, tank safe	☐ Yes ☐ No al Pump Tank	er concerns.