

## Chris LeClair

---

**From:** Gary Bruns  
**Sent:** Wednesday, April 26, 2017 10:10 AM  
**To:** Chris LeClair  
**Subject:** RE: 7707 St. Croix TR S

To make it easy, for now just send me all of them that we are issuing orders on to replace, and/or failing compliance inspections, regardless of determination.

This will keep me aware of what is going on.

---

**From:** Chris LeClair  
**Sent:** Wednesday, April 26, 2017 9:03 AM  
**To:** Gary Bruns  
**Subject:** RE: 7707 St. Croix TR S

Is this “awareness” just for those inspections where a permit was issued sometime in the past and we have to make decisions? Or do you want this awareness on any order to replace?

The reason I ask is because most of our non-compliant orders are “no-brainers”. Cesspools, separation in Lake Elmo (where there was no soil verification being done, so we don’t even bother with looking at old permit records), imminent threats, etc.

Thanks!

Chris

---

**From:** Gary Bruns  
**Sent:** Wednesday, April 26, 2017 8:49 AM  
**To:** Chris LeClair  
**Subject:** RE: 7707 St. Croix TR S

This is level of detail is good, “Awareness” is how I define it.

---

**From:** Chris LeClair  
**Sent:** Wednesday, April 26, 2017 8:06 AM  
**To:** Gary Bruns  
**Subject:** RE: 7707 St. Croix TR S

Six months.

I’m trying to figure out the level of detail you want for these. Is what I provided below too much? Not enough? If you could let me know as we navigate through this new process, that would be great.

Thanks, Chris

---

**From:** Gary Bruns  
**Sent:** Tuesday, April 25, 2017 4:45 PM  
**To:** Chris LeClair  
**Subject:** RE: 7707 St. Croix TR S

Hi Chris,

Thanks for sending my way. I concur. What would be the timeframe for replacement?

-Gary

---

**From:** Chris LeClair  
**Sent:** Tuesday, April 25, 2017 4:21 PM  
**To:** Gary Bruns  
**Subject:** 7707 St. Croix TR S

Here's a failing compliance inspection from Brian Humpal. He hit bedrock at 33" & 40", with a system that is 31" from grade.

We have a permit on file from 1999, but it was only for a tank replacement. No soil information.

I went out there today and conducted a soil observation, and hit bedrock at 39". Soil log is attached.

I think we should issue orders to replace the system. Let me know if you concur.

<https://septic.co.washington.mn.us/view.php?id=8284>

Thanks, Chris

**CHRISTOPHER W. LECLAIR, R.E.H.S.**

Sr. Environmental Specialist  
Washington County Department of  
Public Health & Environment  
651-430-4052  
[Chris.LeClair@co.washington.mn.us](mailto:Chris.LeClair@co.washington.mn.us)