DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety		_			
Date of Maintenance:	3/30/17 Reason	n for Maintenance: _	ROUTINE			
	320 MILITARY			ame: <i>CAROL SCHL</i>	ORHAUFER.	
-	<u>vPort</u> zip: <u>556</u>					
	o: <u>C3623e5890</u>					
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)	
★ Tank(s) Pumped			Liquid Level of Tank in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to		-		evel x 100 nks must be pumped i	f 25% or greater	
☐ Yes ☐ No (if	no provide measurements))		——————————————————————————————————————		
evidence of dama	aged, cracked, or structur	rally unsound main Leaking Out	tenance hole cove	rs? Yes No Cover Damage		
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes 🕅 No	☐ Yes ☒No		
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ⋈No	,	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1500	of septage were removed	gal Pretreatmen		al Pump Tank	gal	
5. Other information	: List any troubleshootin	g, minor repairs co	nducted, tank safe	ety concerns, or othe		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License Number: L915 P: 651-459-0162