

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Municipality: Ofton ZIP:5500 Property Identification Number:	NOT pumped)
Municipality: Ofton ZIP:5500 Property Identification Number: Maintenance Pertoit No: 4/62x/0/59 Maintainer Name and License No. Meyer Sewer Service, Inc. / Maintenance Performed Tank Measurement (must be completed if tanks N Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank	/L915 NOT pumped)
Maintenance Permit No: 4462x10159 Maintainer Name and License No. Meyer Sewer Service, Inc. / Maintenance Performed Tank Measurement (must be completed if tanks N Liquid Level of Tank	NOT pumped)
Maintenance Performed Tank Measurement (must be completed if tanks N Liquid Level of Tank in Sludge and sour measured Sludge Level in Tank in Scum Level in Tank	NOT pumped)
Tank(s) Pumped Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank	y kan di makan kan sa
Tank(s) Pumped Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank	
Sludge Level in Tank in Scum Level in Tank	in
Sludge and ssum managered Sludge Level in Tank in Scum Level in Tank	in
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100	
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if	f 25% or greater
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)	
 Were all covers securely replaced? X Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the opera evidence of damaged, cracked, or structurally unsound maintenance hole covers? 	ating depth or
Tank Leaking Out Leaking In Cover Damage	
Septic/Holding Tank #1 ☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☒ No	
Septic/Holding Tank #2	
Pretreatment Tank ☐ Yes ☐ No ☐ Yes ☐ No	
Pump Tank ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	
4. How many gallons of septage were removed?	
Tank #1 1200 gal Tank #2 gal Pretreatment tank gal Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other	gai
in the state of th	concerns.
5. Location of septage disposal:	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162