

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	8/24/17 Reason	i for Maintenance: _	ROUTINE			
Property Address: 🎉	691 75 UST. 1	<u>V ,</u>	Property Owner's Name: DIANA GUNDERSON			
Municipality: <u>GRAA</u>	IT ZIP: <u>550</u>	22 Property Ide	ntification Number:			
Maintenance Permit No: <u>C 9070 K 7433</u> Maintainer Name and License No. <u>Meyer Sewer Service, Inc./L915</u>						
			si .			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☐ Tank(s) Pumped ☐ Sludge and scum measured		Liquid Level of Tank in				
		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to h	e pumped?	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
Yes 🗆 No (if r	no provide measurements)		3			
1. Access used to remove septage:   Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced?   Yes   No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
		0.022				
*	Tank	Leaking Out	Leaking In	Cover Damage		
. *	Tank Septic/Holding Tank #1	Leaking Out  Ves No	Leaking In  Yes No	Cover Damage  See No		
» *				17 (40 (40 (40 (40 (40 (40 (40 (40 (40 (40		
. *	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	e	
4. How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	e	
	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 /0000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were removed	☐ Yes ☐ No ☐ Yes ☐ Ro d? _ gal Pretreatmen	☐ Yes ☐ No t tankg	☐ Yes ☐ No		
Tank #1 /0000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No Pes No Pes Ro  d? gal Pretreatmen g, minor repairs co	☐ Yes ☐ No t tankg	☐ Yes ☐ No		
Tank #1 /00-e	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were removed gal Tank #2 List any troubleshooting	Yes No Yes No Yes No Yes No Yes No Pes No Pes Ro  d? gal Pretreatmen g, minor repairs co	☐ Yes ☐ No t tankg	☐ Yes ☐ No		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162