

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 9/21/17 Reason f	for Maintenance: _	Routine		
Property Address: 8833 Oakgreen (1)	re.5. p	Property Owner's Na	ame: <u>Rich K</u>	obinson
Municipality: Denmark flusp IP: 550:	33 Property Ide	ntification Number:		·
Maintenance Permit No: <u>C651016'8786</u> M	aintainer Name ar	nd License No. <u>Meye</u>	er Sewer Service, Inc	.,/L915
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	31	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100		
Do tanks need to be pumped?	= % Sludge & Scu	•	nks must be pumped	
☐ Yes ☐ No (if no provide measurements)				····
1. Access used to remove septage: Maintenan	ice Hole 🗆 Other (e	enter authorization co	ode)	
2. Were all covers securely replaced? X Yes	□No			
2. Were all covers securely replaced? Yes [3. is there evidence of tank leakage from a sep	□ No tic, holding, pretr	reatment or pump	tank below the ope	rating depth or
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a septendence of damaged, cracked, or structural 	□ No tic, holding, pretr ally unsound main	eatment or pump tenance hole cove	tank below the ope rs?	rating depth or
2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a septevidence of damaged, cracked, or structura Tank	□ No tic, holding, pretr ally unsound main Leaking Out	reatment or pump tenance hole cove Leaking In	tank below the opers? Cover Damage	rating depth or
3. Is there evidence of tank leakage from a septendence of damaged, cracked, or structura	tic, holding, pretrally unsound main			rating depth or
3. Is there evidence of tank leakage from a septevidence of damaged, cracked, or structura	tic, holding, pretr ally unsound main Leaking Out	Leaking In	Cover Damage	rating depth or
3. Is there evidence of tank leakage from a septendence of damaged, cracked, or structura Tank Septic/Holding Tank #1	tic, holding, pretrailly unsound main Leaking Out Yes Wo	Leaking In Yes No	Cover Damage Yes No	rating depth or
3. Is there evidence of tank leakage from a septevidence of damaged, cracked, or structura Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No Yes No	rating depth or
Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 Jank #2 And Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal
Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 Jank #2 And Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162