

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

RODTINE

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	10/3/// Reason f	or Maintenance: _	ROUTINE		
	0809 LEHIGH.				YER
1 St. Co. 10 10 10 10 10 10 10 10 10 10 10 10 10	TAGE GROVE ZIP:5501	6 Property Ider	ntification Number:		
STATES OF THE TANK THE PERSON OF THE PERSON	: 06250 f 9122 M				
Mairicenance remite No	<u>() () () () () () () () () () () () () (</u>	u			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
		Liquid Level of Tank in			
Tank(s) Pumped		Sludge Level in Tank in Scum Level in Tank in			
☐ Sludge and scum measured Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
					ĺ
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 💆 No	☐ Yes No	☐ Yes 🏚 No	
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☑No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
A. Hannann gallang	of contago were removed	,			
4. How many gallons of septage were removed? Tank #1_1250 gal Tank #2 _1250 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
13-0 (, 0.1					
6. Location of septage disposal:					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162