

Date of Maintenance: 1 -22-1 \forall

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Reason for Maintenance:

Maintenance Performed			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		III '	Liquid Level of Tank in			
Sludge and scum measured		11 "	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Sc	= % Sludge & Scum 7 Equid Level X 100 Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if	no provide measurements	3)				
A a a a a a u a a d & - u - u	nove septage: Mainten	ance Hole Other	enter authorization c	ode)		
. Were all covers se . Is there evidence	curely replaced? Yes	□ No eptic, holding, pret	eatment or pump	tank below the oper	ating depth or	
2. Were all covers se 3. Is there evidence	curely replaced? Yes	□ No eptic, holding, pretorally unsound main Leaking Out	eatment or pump	tank below the oper	ating depth or	
2. Were all covers se 3. Is there evidence	curely replaced? Yes of tank leakage from a se aged, cracked, or structu	□ No eptic, holding, pret rally unsound main	reatment or pump tenance hole cove	tank below the operers? Yes No	ating depth or	
Were all covers se	curely replaced? Yes of tank leakage from a se aged, cracked, or structu	□ No eptic, holding, pretorally unsound main Leaking Out	reatment or pump tenance hole cove Leaking In	tank below the operers? Yes No	ating depth or	
2. Were all covers se 3. Is there evidence	curely replaced? Yes of tank leakage from a se aged, cracked, or structu Tank Septic/Holding Tank #1	Police No	Leaking In	tank below the operers? Yes No	ating depth or	
2. Were all covers se 3. Is there evidence	curely replaced? Yes of tank leakage from a se aged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2	No eptic, holding, pretorally unsound main Leaking Out Yes No	Leaking In Yes No Yes No	tank below the operers? Yes No Cover Damage Yes No Yes No	rating depth or	

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082