## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance Reason for Maintenance: ROUTINE					
Property Address: 9075 57 500 Property Owner's Name: Harvey Taipale					
Municipality: Leave Elmo State M Zip Code GEO Code/Property I.D. #:					
What was done to the system? Tank Measurements (must be completed if tanks NOT pumped)					
Tank(s) Pumpe	d	Liquid Level of Tank	in. Sludge Le	vel in. Scum Level in.	
☐ Sludge and scum measured.  Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements)		Liquid Level of Talik	III. Sludge Level		
		Total (Sludge + Scu	m) / Liquid Leve		
* Tank must be pumped if this value is greater than 25%.					
2. If maintenance hole was used, were all covers securely replaced? Yes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ₹ No	Yes K No	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes ☐ No	☐ Yes ♣ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed?					
Tank #1 1500 Tank #2 1500 Pretreatment Tank Pump Tank					
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.					
Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 354 Afton, MN 55001					
Maintainer's License #: 1673 Maintainer's Phone #: 651-439-4847					
Maintainer's Signature					