

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	12/10/18 Reason f	or Maintenance:	Routine	)	
Property Address: _ರ	060 Oakdale	1 Dr.	Property Owner's N	lame: Lordy	Steenmets
Municipality: Pines	Springs ZIP: 55/1.	5 Property Ide	ntification Number		(
Maintenance Permit N	0: n2367e 14642 M	aintainer Name a	nd License No MS	5-1915	
		ameamer name a	ild Electise No. <u>7 (3</u>		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
<ul><li></li></ul>		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
$\square$ Yes $\square$ No (if no provide measurements)		Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage:   Maintenand	re Hole 10 Other (	enter authorization of	ada)	
<ol> <li>Were all covers securely replaced? ✓ Yes □ No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li></ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes 🍽 No	☐ Yes 🌠 No	
	Septic/Holding Tank #2	☐ Yes QNo	☐ Yes <b>©</b> No	☐ Yes <b>Ø</b> No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons Tank #1 1600	of septage were removed? _ gal Tank #2	gal Pretreatmen	ttank ga	al Pump Tank	σal
Tank #1 1600 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Failed septend - New one will be put in					
	•				
6. Location of septage	disposal:				

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162