

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Municipality:  Maintenance Permit	No: 12956f/4632	O4J-Property Ide				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
<ul> <li>▼ Tank(s) Pumped</li> <li>□ Sludge and scum measured</li> <li>□ Do tanks need to be pumped?</li> <li>□ Yes □ No (if no provide measurements)</li> </ul>		Sludge Level in Sludge + Scum	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
4 4 14		Hala 180 Odlan (	ontor outhorization -	odo)		
2. Were all covers se	move septage:  Mainten ecurely replaced?  Yes of tank leakage from a se aged, cracked, or structu	□No			rating depth or	
2. Were all covers se	ecurely replaced? 🙋 Yes	□No			rating depth or	
2. Were all covers se	ecurely replaced? Yes of tank leakage from a se aged, cracked, or structu	□ No ptic, holding, pret rally unsound main	reatment or pump Itenance hole cove	tank below the oper ers?	rating depth or	
2. Were all covers se	ecurely replaced? 2 Yes of tank leakage from a se aged, cracked, or structu	□ No ptic, holding, pretally unsound main Leaking Out	reatment or pump Itenance hole cove Leaking In	tank below the operers?  Cover Damage	rating depth or	
2. Were all covers se	ecurely replaced? Yes of tank leakage from a se aged, cracked, or structu  Tank  Septic/Holding Tank #1	No ptic, holding, pretrally unsound main  Leaking Out  Yes Mo	reatment or pump itenance hole cove Leaking In	tank below the operers?  Cover Damage  Yes No	rating depth or	
2. Were all covers se	recurely replaced? Yes of tank leakage from a se aged, cracked, or structu  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	□ No ptic, holding, pretrally unsound main  Leaking Out □ Yes ♥ No □ Yes Ւ No	Leaking In  Yes  Yes  Yes	tank below the operers?  Cover Damage  Yes No	rating depth or	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162