
Property Address: 236





I have chosen to have my system serviced in a manner not meeting the requirements of Minnesota Rules, Chapter 7080.2450 subp. 3 B

If no maintenance hole exists on a sewage tank, the owner or the owner's agent shall install maintenance holes in accordance with Minnesota Rules Chapter 7080.1970, to allow for maintenance to take place through the maintenance hole. If the owner or owner's agent refuses to allow removal through a maintenance hole, the licensed Maintainer must, per Minnesota Rules Chapter 7083.0770 Subp. 2 C, obtain a signed statement the reason for refusal.

The reason for this choice is listed below.

I understand that this is my choice and accept responsibility if the system has problems and also understand that this is **substandard** as recommended in the Minnesota Rules Chapters 7080 - 7083.

Stated Reason:			
Owner or Agen	t's Name:	Jane McMullen	
Signature:	Jone	- Mc Mullan	

We at Kons Sewer Sorvice

do not recommend the pumping of the tank through the inspection pipe and cannot be responsible for the quality of cleaning or inspection of the tank when service is provided through the inspection pipe. We hope in the future to maintain your business and stand at the ready to meet your onsite sewage treatment needs.