

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entiretroprior to performing maintenance activates of Maintenance: 9-19-19 Reason | ities and remain on n for Maintenance: | -site for the durat Routine | tion of the maintena | ance activity. | |
|---|--|--|--|---------------------|--|
| Property Address: Duanuell | Property Ide | ntification Number | : | | |
| Maintenance Permit No: 3552£17071 | maintainer Name ar | nd License No. Pink | ky's Environmental S | ewer Service/ L167 | |
| Maintenance Performed | Tank Meas | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | Liquid Level of | Liquid Level of Tank — in | | | |
| ☐ Sludge and scum measured | Sludge Level in | Tank ——— in | Scum Level in Tank | in | |
| Do tanks need to be pumped? | Sludge + Scum - | Sludge + Scum / Liquid Level X 100 | | | |
| \square Yes \square No (if no provide measurements | s) = % Sludge & Sci | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 2. Were all covers securely replaced? Yes | □No HC | 175 XL97 | | rating depth or | |
| | □ No # Coptic, holding, pretr | eatment or pump | tank below the ope | rating depth or | |
| Were all covers securely replaced? Yes Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure | □ No # Control No pretrol no pre | eatment or pump tenance hole cove | tank below the ope ers? Yes No | rating depth or | |
| Were all covers securely replaced? Yes Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure. Tank | □ No # Control No H Control No | eatment or pump tenance hole cove | tank below the ope ers? Yes No | rating depth or | |
| 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank | ptic, holding, pretrrally unsound main Leaking Out | eatment or pump tenance hole cove | tank below the ope ers? Yes No Cover Damage | rating depth or | |
| 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure Tank Septic/Holding Tank #1 Septic/Holding Tank #2 | ptic, holding, pretrally unsound main | eatment or pump tenance hole cover Leaking In Yes No Yes No | tank below the opers? Yes No Cover Damage Yes No Yes No | rating depth or | |
| 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structure Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank | ptic, holding, pretrally unsound mains Leaking Out Yes No Yes No Yes No Yes No Great Reading Out Yes No Holding, pretrally unsound mains Leaking Out Yes No Holding, pretrally unsound mains Yes No Holding, pretral | eatment or pump tenance hole cover Leaking In Yes No Yes No Yes No Yes No tank ga | tank below the operers? Yes No Cover Damage Yes No Yes No Yes No Yes No Pump Tank ty concerns, or other | gal er concerns. | |

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673