DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 4 27 2020 Reason	on for Maintenance	ompliance	* 075Wh18783
Property Address: 20080 Luna	Prop	erty Owner's Name: 👠	not printed a chance
Municipality:	State Zip Coo	de <u>\$5025</u> GEO C	ode/Property I.D. #:
What was done to the system? Tank Measurements (must be completed if tanks NOT pumpe			ompleted if tanks NOT pumped)
☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurem	Liquid Level of Ta		·
1. Access used to remove septage: Main	tenance Hole	(Go to #3 below)	* Tank must be pumped if this value
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain			
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:			
I,(owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 TYes No Verificatio Method Used: Proped Tank			
Tank#2 Yes No Verificatio Method Used:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?			
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes No	Yes No	Yes TWo
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No
Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No
Pump Tank	Yes No	Yes No	☐ Yes ☐ No
6. How many gallons of septage were remo	ved?		-
Tank #1 1250 Tank #2	Pretreatment Ta	Pretreatment Tank Pump Tank 200	
7. Other information: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conc	erns, or other concerns.
8. Certification: I hereby certify as a State of I and made the observations,	Minnesota certified SSTS or directly supervised otl	Maintainer that I persona ners in the performance o	Illy conducted the work of this job.
Maintainer's Name: 0555 Maintainer's Address: 17638 Lyons 54 NE			
Maintainer's License #: 24 Maintainer's Phone #: 464-2002			
Maintainer's Signature D			127,120