DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance (Reason	on for Maintenance:	u1087 5 25	954	ু ক
Property Address: \2201 Morel	Ar BAN Prop	perty Owner's Name: R	D fierek	4
Municipality: Stallworks	State Zip Co	de GEO C	ode/Property I.D. #:	
	tenance Hole	in. Sludge (Go to #3 below)	* Tank must be pumped if to is greater than 25%.	in.
2. If maintenance hole was used, were all cove Explanation:	ers securely replaced?	Yes No please exp	lain	
3. If owner refuses to allow a Subsurface Se them complete and sign the following st		m (SSTS) to be pumped	through the maintenance hole	, have
hole. I understand that removal of solids and the solids are solids. It is the tank designed as a leaky tank? examp Tank#1 Yes No Verificatio Methods Tank#2 Yes No Verificatio Methods Is there evidence of tank leakage from a solid	de: seepage pit, cesspool, dod Used:	lrywell, leaching pit	·	dence of
damaged, cracked, or structurally unsour	nd maintenance hole co	vers?		rence or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1 Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes Wo	
Pump Tank	Yes No	Yes No	Yes No	
5. How many gallons of septage were remov		Yes No	Yes No	
Tank #1 Tank #2	Pretreatment Ta		erns, or other concerns.	
•				
B. Certification: I hereby certify as a State of A and made the observations,				
Maintainer's Name: Olson's Sewer Service,	inc. Maintaine	er's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintainer's Maintainer's Signature	ainer's Phone #: 651-46		-7-22	
- W. S.				